



CRYSTAL REPORTS EXAMPLES


SEPTEMBER 2023

LINN COVE VIADUCT – BLUE RIDGE PARKWAY | NCDOT

AASHTO Ware™
 **BRIDGE**
MANAGEMENT



New Mexico DEPARTMENT OF
TRANSPORTATION
MOBILITY FOR EVERYONE



Bridge Inspection Report

00000000000701
 Facility Carried(7): FL-5788
 Mile Post(11): 0.28 mi (0.45 km)
 Team Leader: REYNALDO SAMPAGA
 Inspection Date: 10/05/2021

IDENTIFICATION

NBI Number:	00701	County (3):	49 SANTA FE	Custodian (21):	City/Municipal Hwy
Location (9):	JCT GRANT/ROSARIO	Health Index:	97.49	Year Built (27):	1920
SHD District (2):	District 5	SR:	45.90	Year Recon (106):	
Type of Service On (42A):	1 Highway	SD/FO:	ND	Historical (37):	2 Br eligible for rehab
Feature Intersected (6):	ARROYO DE LAS MASCARAS	Latitude (16):	35.69		
Type of Service Under(42B):	5 Waterway	Longitude (17):	-105.94		
Placecode (4):	Santa Fe	Owner (22):	City/Municipal Hwy Agency		

BRIDGE NOTES

Description: 1 simple span at 54ft concrete, through arch with cast in place concrete deck, girders, stringers and concrete stub abutments. ...

DECK GEOMETRY

Deck Geometry (68):	2 Intolerable - Replace
Deck Area:	1,647.00
Deck Type (107):	1 Concrete-Cast-in-Place
Wearing Surface (108A):	0 None
Membrane (108B):	0 None
Deck Protection (108C):	None
O. to O. Width (52):	29.53
Curb / Sidewalk Width L (50A):	6.56
Curb / Sidewalk Width R (50B):	6.56
Median (33):	0 No median
Width Curb to Curb (51):	14.76

DECK CONDITION

Deck Rating (58):	6 Satisfactory
Bridge Rail (36A):	1 Meets Standards
Transition (36B):	N N/A or not required
Approach Rail (36C):	N N/A or not required
Approach Rail Ends (36D):	N N/A or not required
Approach Roadway Width (32)(w/ shoulders)	27.89

SUPERSTRUCTURE GEOMETRY

# of Main Spans (45):	1
# of Approach Spans (46):	0
Main Material (43 A):	1 Concrete
Main Design (43 B):	12 Arch-Thru
Max Span Length (48):	55.77
Structure Length (49):	55.77
NBS Length (112):	Long Enough
Skew (34):	0
Structure Flared (35):	0 No flare
Approach Alignment (72):	5 Above Tolerable

SUPERSTRUCTURE CONDITION

Superstructure Rating (59):	5 Fair
Structure Evaluation (67):	4 Minimum Tolerable
Approach Span Material (44A):	Unknown (NB)
Approach Span Design (44B):	Unknown (P)

SUBSTRUCTURE GEOMETRY

Scour Rating (113):	8 Stable Above Footing
Waterway Adequacy (71):	8 Equal Desirable
Substructure Rating (60):	6 Satisfactory
Channel Rating (61):	8 Protected


SUBSTRUCTURE CONDITION

Team Leader

Signature and Date: REYNALDO SAMPAGA
10/05/2021

Reviewed By

Signature and Date



Bridge Inspection Report


00000000000701
 Facility Called(7): FL-5788
 Mile Post(11): 0.28 mi (0.45 km)
 Team Leader: REYNALDO SAMPAGA
 Inspection Date: 10/05/2021


IDENTIFICATION


NBI Number: 00701	County (9): 49 SANTA FE	Custodian (21): City/Municipal Hwy
Location (8): JCT GRANT/ROSARIO	Health Index: 97.49	Year Built (27): 1920
SHD District (2): District 5	SR: 45.90	Year Recon (106):
Type of Service On (42A): 1 Highway	SD/FO: ND	Historical (37): 2 Br eligible for rehab
Feature Intersected (6): ARROYO DE LAS MASCARAS	Latitude (16): 35.09	
Type of Service Under(42B) 5 Waterway	Longitude (17): -105.94	
Placecode (4): Santa Fe	Owner (22): City/Municipal Hwy Agenc	

BRIDGE NOTES


Description: 1 simple span at 54ft concrete, through arch with cast in place concrete deck, girders, stringers and concrete stub abutments. ...

<p>DECK GEOMETRY</p> <p>Deck Geometry (68): 2 Intolerable - Replace</p> <p>Deck Area: 1,647.00</p> <p>Deck Type (107): 1 Concrete-Cast-in-Place</p> <p>Wearing Surface (108A): 0 None</p> <p>Membrane (108B): 0 None</p> <p>Deck Protection (108C): None</p> <p>O. to O. Width (52): 29.53</p> <p>Curb / Sidewalk Width L (50A): 6.58</p> <p>Curb / Sidewalk Width R (50B): 6.58</p> <p>Median (33): 0 No median</p> <p>Width Curb to Curb (51): 14.76</p>	<p>DECK CONDITION</p>  <p>Deck Rating (58): 6 Satisfactory</p> <p>Bridge Rail (36A): 1 Meets Standards</p> <p>Transition (36B): N N/A or not required</p> <p>Approach Rail (36C): N N/A or not required</p> <p>Approach Rail Ends (36D): N N/A or not required</p> <p>Approach Roadway Width (32)(w/ shoulders) 27.89</p>
---	---

<p>SUPERSTRUCTURE GEOMETRY</p> <p># of Main Spans (45): 1</p> <p># of Approach Spans (46): 0</p> <p>Main Material (43 A): 1 Concrete</p> <p>Main Design (43 B): 12 Arch-Thru</p> <p>Max Span Length (48): 55.77</p> <p>Structure Length (49): 55.77</p> <p>NBS Length (112): Long Enough</p> <p>Skew (34): 0</p> <p>Structure Flared (35): 0 No flare</p> <p>Approach Alignment (72): 5 Above Tolerable</p>	<p>SUPERSTRUCTURE CONDITION</p>  <p>Superstructure Rating (59): 5 Fair</p> <p>Structure Evaluation (67): 4 Minimum Tolerable</p> <p>Approach Span Material (44A): Unknown (NB)</p> <p>Approach Span Design (44B): Unknown (P)</p>
--	--

<p>SUBSTRUCTURE GEOMETRY</p> <p>Scour Rating (113): 8 Stable Above Footing</p> <p>Waterway Adequacy (71): 8 Equal Desirable</p> <p>Substructure Rating (60): 6 Satisfactory</p> <p>Channel Rating (61): 8 Protected</p>	<p>SUBSTRUCTURE CONDITION</p> 
--	--

<p>Team Leader Signature and Date: REYNALDO SAMPAGA 10/05/2021</p>	<p>Reviewed By Signature and Date</p>
--	--



Bridge Inspection Report

00000000000701
 Facility Called(7): FL-5788
 Mile Post(11): 0.28 mi (0.45 km)
 Team Leader: REYNALDO SAMPAGA
 Inspection Date: 10/05/2021

INSPECTION

Date of Inspection (90):	10/5/2021	Inspection Type	Freq (92):	Last Insp (93)	Next Insp
Frequency (91):	24	Element	24	10/5/2021	10/5/2023
Next Inspection:	10/5/2023	Fracture Critical (A)		1/1/1901	1/1/1901
Crew Hours:	3.00	Underwater (B)		1/1/1901	1/1/1901
Snooper Hours:	0.00	Special Insp (C)		1/1/1901	1/1/1901

LOAD RATING AND POSTING

Posting Status (41): P Posted for load	Opr Method (63): 1 LF Load Factor	Posting Loads Operating NM-2 Axle: NM-3A Axle: NM-5A Axle:
Posting % (70): 3 10.0-19.9%below	Opr Rating (64): HS14.8	
Design Load (31): 2 M 13.5 (H 15)	Inv Method (65): 1 LF Load Factor	
	Inv Rating (66): HS 9.9	

ROADWAY

<p>LOCATION</p> <p>Kind of Hwy (5B): 5 City Street</p> <p>Mile Post (11): 0.28 mi (0.45 km)</p> <p>Lanes On (28A): 1</p> <p>Detour Length (19): 1.24 mi (2.00 km)</p>	<p>Lanes Under (28B): 0.00</p> <p>Route Posted Speed:</p> <p>Direction of Traffic (102): 3 1-lane Br for 2-way</p>	<p>CLASSIFICATION</p> <p>Funct Class (26): 19 Urban Local</p> <p>NHS (104): 0 Not on NHS</p> <p>Defense Hwy (100): 0 Not a STRAHNET hwy</p> <p>ADT (29): 4,905 Cars/Day</p> <p>Pot Trucks (109): 3.00%</p> <p>ADT Year (30): 2021</p> <p>Future ADT (114): 6,670.00</p> <p>Year Of Future ADT (115): 2041</p>
--	---	--

CLEARANCES

Horizontal (47): 14.76	Horiz Ref (65A): N Feature not hwy or RR
Min Lat Left (56): 0.00	Underclearance (69): N Not applicable (NBI)
Min Lat Right (56B): 0.00	
Minimum Lateral Underclearance R (55): 0.00	
Minimum Lateral Underclearance L (56): 0.00	
Minimum Vertical Clearance Minus: 0	
Minimum Vertical Clearance Plus: 0	


CRITICAL FINDINGS SUMMARY

Critical Findings: None

Date Found: Inspector Name:

Notes: Date Updated:


Action Taken:



Bridge Inspection Report

000000000000701

Facility Carried(7): FL-5788
 Mile Post(11): 0.28 mi (0.45 km)
 Team Leader: REYNALDO SAMPAGA
 Inspection Date: 10/05/2021



Bridge Inspection Report

000000000000701

Facility Carried(7): FL-5788
 Mile Post(11): 0.28 mi (0.45 km)
 Team Leader: REYNALDO SAMPAGA
 Inspection Date: 10/05/2021

IDENTIFICATION


NBI Number: 00701 County (3): 49 SANTA FE Custodian (21): City/Municipal Hwy
 Location (9): JCT GRANT/ROSARIO Health Index: 97.49 Year Built (27): 1920
 SHD District (2): District 5 SR: 45.90 Year Recon (106):
 Type of Service On (42A): 1 Highway SD/FO: ND Historical (37): 2 Br eligible for rehab
 Feature Intersected (6): ARROYO DE LAS MASCARAS Latitude (16): 35.09
 Type of Service Under(42B): 5 Waterway Longitude (17): -105.94
 Placecode (4): Santa Fe Owner (22): City/Municipal Hwy Agenc

BRIDGE NOTES

Description: 1 simple span at 54ft concrete, through arch with cast in place concrete deck, girders, stringers and concrete stub abutments. ...

DECK GEOMETRY

Deck Geometry (68): 2 Intolerable - Replace
 Deck Area: 1,647.00
 Deck Type (107): 1 Concrete-Cast-in-Place
 Wearing Surface (108A): 0 None
 Membrane (108B): 0 None
 Deck Protection (108C): None
 O. to O. Width (52): 29.53
 Curb / Sidewalk Width L (50A): 6.58
 Curb / Sidewalk Width R (50B): 6.58
 Median (33): 0 No median
 Width Curb to Curb (51): 14.76




DECK CONDITION

Deck Rating (58): 6 Satisfactory
 Bridge Rail (36A): 1 Meets Standards
 Transition (36B): N N/A or not required
 Approach Rail (36C): N N/A or not required
 Approach Rail Ends (36D): N N/A or not required
 Approach Roadway Width (32)(w/ shoulders) 27.89

SUPERSTRUCTURE GEOMETRY

of Main Spans (45): 1
 # of Approach Spans (46): 0
 Main Material (43 A): 1 Concrete
 Main Design (43 B): 12 Arch-Thru
 Max Span Length (48): 55.77
 Structure Length (49): 55.77
 NBIS Length (112): Long Enough
 Skew (34): 0
 Structure Flared (35): 0 No flare
 Approach Alignment (72): 5 Above Tolerable




SUPERSTRUCTURE CONDITION

Superstructure Rating (59): 5 Fair
 Structure Evaluation (67): 4 Minimum Tolerable
 Approach Span Material (44A): Unknown (NB)
 Approach Span Design (44B): Unknown (P)

SUBSTRUCTURE GEOMETRY

Scour Rating (113): 8 Stable Above Footing
 Waterway Adequacy (71): 8 Equal Desirable
 Substructure Rating (60): 6 Satisfactory
 Channel Rating (61): 8 Protected



SUBSTRUCTURE CONDITION

Team Leader

Signature
and Date

REYNALDO SAMPAGA
10/05/2021

Reviewed By

Signature
and Date

Next Insp:

10/5/2023
1/1/1901
1/1/1901
1/1/1901

ads Operating

ATION

Urban Local
lot on NHS
lot a STRAHNET hwy
05 Cars/Day
21
70.00
2041

NMDOT MISC. DATA

Old Bridge Number: Known Utilities:
 Stay In Place Forms: No Stay In Place Form Type: 0
 Overlay Thickness: Culvert Fill Depth: 0.00

SIP Notes:

Approach Roadway Condition:

Roadway at south end has isolated longitudinal diagonal cracks up to 1/4in and minor raveling. Pavement at north end has T intersection with stop control. Pavements are in good condition. Bridge signing consists of 4 ea paddleboards and 10 ton max load posting. Traffic Safety Features: CBR and curb and gutter system.

Channel & Channel Protection:

Flat, sandy arroyo channel with moderate to steep banks, minor vegetation perpendicular to the structure. Channel is protected by vertical rock wall at North side and gabion walls at South side. No high water marks noted.

Recommendations:

Recommendations: 1. Monitor cracks at girders. 2. Repair delaminations at deck, stringers and spall at girder 1. 3. Consider sealing deck. 4. Repair scaling at CBR. 5. Post for one lane bridge.

Directions:

From JCT of Grant St and Rosario Blvd. in Santa Fe, travel north 0.1 mile on Grant St. to structure

Next Insp:

10/5/2023
1/1/1901
1/1/1901
1/1/1901

ads Operating

ATION

Urban Local
lot on NHS
lot a STRAHNET hwy
05 Cars/Day
21
70.00
2041



Bridge Inspection Report

00000000000701

Facility Carried(7): FL-5788
 Mile Post(11): 0.28 mi (0.45 km)
 Team Leader: REYNALDO SAMPAGA
 Inspection Date: 10/05/2021

00000000000701

Facility Carried(7): FL-5788
 Mile Post(11): 0.28 mi (0.45 km)
 Team Leader: REYNALDO SAMPAGA
 Inspection Date: 10/05/2021

000000000701

Facility Carried(7): FL-5788
 Mile Post(11): 0.28 mi (0.45 km)
 Team Leader: REYNALDO SAMPAGA
 Inspection Date: 10/05/2021

IDENTIFICATION			
NBI Number:	00701	County (3):	49 SANTA FE
Location (9):	JCT GRANT/ROSARIO	Health Index:	97.49
SHD District (2):	District 5	SR:	45.90
Type of Service On (42A):	1 Highway	SD/FO:	ND
Feature Intersected (6):	ARROYO DE LAS MASCARAS	Latitude (16):	35.09
Type of Service Under(42B)	5 Waterway	Longitude (17):	-105.94
Placecode (4):	Santa Fe	Owner (22):	City/Municipal Hwy Agenc
		Custodian (21):	City/Municipal Hwy
		Year Built (27):	1920
		Year Recon (106):	
		Historical (37):	2 Be eligible for NHP

BRIDGE NOTES
 Description: 1 simple span at 54ft concrete, through arch with cast in place concrete deck, girders, stringers and concrete stub abutments.

DECK GEOMETRY		DECK CONDITION	
Deck Geometry (68):	2 Intolerable - Replace	Deck Rating (58):	6 Satisfactory
Deck Area:	1,647.00	Bridge Rail (36A):	1 Meets Standards
Deck Type (107):	1 Concrete-Cast-in-Place	Transition (36B):	N N/A or not required
Wearing Surface (108A):	0 None	Approach Rail (36C):	N N/A or not required
Membrane (108B):	0 None	Approach Rail Ends (36D):	N N/A or not required
Deck Protection (108C):	None	Approach Roadway Width (32)(w/ shoulders)	27.89
O. to O. Width (52):	29.53		
Curb / Sidewalk Width L (50A):	6.56		
Curb / Sidewalk Width R (50B):	6.56		
Median (33):	0 No median		
Width Curb to Curb (51):	14.76		

SUPERSTRUCTURE GEOMETRY		SUPERSTRUCTURE CONDITION	
# of Main Spans (45):	1	Superstructure Rating (59):	5 Fair
# of Approach Spans (46):	0	Structure Evaluation (67):	4 Minimum Tolerable
Main Material (43 A):	1 Concrete	Approach Span Material (44A):	Unknown (NBI)
Main Design (43 B):	12 Arch-Thru	Approach Span Design (44B):	Unknown (P)
Max Span Length (48):	55.77		
Structure Length (49):	55.77		
NBS Length (112):	0		
Slew (54):	0 No flare		
Structure Flared (35):	0 No flare		
Approach Alignment (72):	5 Above Tolerable		

SUBSTRUCTURE GEOMETRY		SUBSTRUCTURE CONDITION	
Scour Rating (113):	8 Stable Above Footing		
Waterway Adequacy (71):	8 Equal Desirable		
Substructure Rating (60):	6 Satisfactory		
Channel Rating (61):	8 Protected		

Team Leader: REYNALDO SAMPAGA
 Signature and Date: 10/05/2021
 Reviewed By: _____
 Signature and Date: _____



Bridge Inspection Report

00000000000701

Facility Carried(7): FL-5788
 Mile Post(11): 0.28 mi (0.45 km)
 Team Leader: REYNALDO SAMPAGA
 Inspection Date: 10/05/2021

ELEMENT CONDITION SUMMARY

Element	Env	Description	Total Qty	CS 1	CS 2	CS 3	CS 4
12	1	Re Concrete Deck	1,539	0	0%	711	46%
1080		Delamination/Spall/Patched Area	25	0	0%	25	100%
1090		Exposed Rebar	8	0	0%	8	100%
1120		Efflorescence/Rust Staining	243	0	0%	243	100%
1130		Cracking (RC and Other)	927	0	0%	132	14%
1190		Abrasion/PS/CR/C	336	0	0%	336	100%
144	2	Re Conc Arch	111	111	100%	0	0%
521		Conc Prot Coating	111	111	100%	0	0%
155	2	Re Conc Floor Beam	96	48	50%	32	33%
1080		Delamination/Spall/Patched Area	48	0	0%	48	100%
215	2	Re Conc Abutment	59	35	59%	22	37%
359		Conc Effence	10	10	100%	0	0%
1080		Delamination/Spall/Patched Area	4	0	0%	4	100%
1090		Exposed Rebar	2	0	0%	2	100%
1130		Cracking (RC and Other)	8	0	0%	8	100%
321	2	Re Conc Approach Stab	408	0	0%	408	100%
1130		Cracking (RC and Other)	408	0	0%	408	100%
331	2	Re Conc Bridge Railing	161	0	0%	161	100%
1080		Delamination/Spall/Patched Area	1	0	0%	1	100%
1130		Cracking (RC and Other)	71	0	0%	71	100%
1220		Deterioration (Other)	89	0	0%	89	100%
333	2	Other Bridge Railing	108	43	40%	65	60%
1010		Cracking	60	0	0%	60	100%
7000		Damage	5	0	0%	5	100%
7370	3	Rip Rap	1,260	0	0%	1,260	100%
1220		Deterioration (Other)	1,260	0	0%	1,260	100%

ELEMENT NOTES

ELEMENT	ELEMENT NAME	QUANTITY	UNITS	QTY ST 1	QTY ST 2	QTY ST 3	QTY ST 4
12/1	Re Concrete Deck	1,539.00	sq ft	0.00	711.00	828.00	0.00

Topside of deck has extensive wide map cracking, moderate to wide diagonal, longitudinal and transverse cracks and isolated areas of delamination up to 5'x5'. Abrasion wear with exposed aggregate along wheel paths.

Note: Sidewalks have moderate size diagonal and transverse cracks and are in overall good condition.

- Note:
- 1) 4 each, 4 1/2" diameter drains along deck edges that have been clean out and operational.
 - 2) At inlet side there is a 12" utility pipe attached to decorative concrete corbels.
 - 3) There are 11 corbels along bottom of each deck edge.

ELEMENT	DEFECTS	QUANTITY	UNITS	QTY ST 1	QTY ST 2	QTY ST 3	QTY ST 4
1080/1	Delamination/Spall/Patched Ar	25.00	sq ft	0.00	0.00	25.00	0.00

Deck has isolated delamination.

ELEMENT	DEFECTS	QUANTITY	UNITS	QTY ST 1	QTY ST 2	QTY ST 3	QTY ST 4
1090/1	Exposed Rebar	8.00	sq ft	0.00	0.00	8.00	0.00

At SE corner of bottom deck, spalls with exposed rebar.





STRUCTURE INSPECTION REPORT
 MDT ID - 01001
 NBI ID - 100015000+05201
 Feature Intersected - INT MONIDA S 509
 Facility - I 15

Inspector - David Monahan
 Inspection Type - Regular NBI
 Inspection Date - 10/26/2022
 Inventory Direction - South to North



General Bridge Data	
(22) Owner	State Highway Agency
(6A) Feature Intersected	INT MONIDA S 509
(9) Location	MONIDA
(MDT058) Bridge Condition	3-Poor
(SR) Sufficiency Rating	91.00
(27) Year Built	1959
(58) Deck Rating	4 Poor
(59) Superstructure	6 Satisfactory
(60) Substructure	6 Satisfactory
(61) Channel	N N/A (NBI)
(62) Culvert	N N/A (NBI)
(MDT145) Inv Direction:	South to North

Location Data			
(MDT001) Agency Structure Name	30 Montana	(MDT031) Railroad Over/Underpass	0 - Not Applicable
(001A) FIP/State	Region 8-Denver	(MDT032) Railroad Owner	NA - Not Applicable
(061B) FHWA Region	On System	(MDT014) Interchange Indicator	1 - Interchange
(MDT027) On/Off System	Long Enough	(MDT015) Interstate Ramp Indicator	0 - Not a Ramp
(112) NBI's Bridge Length	02 - BUTTE	(MDT078) Maintenance Section	21-11 - Lima
(2) MDT Inspection District	001 - BEAVERHEAD	(MDT026) Maintenance Division	21 - BUTTE
(3) County Code	11300 - BUTTE	(MDT146) Reservation Boundary	2 - Butte
(4) Place Code	I 15	(MDT115) Administrative District	2 - Butte
(7) Facility Carried by Structure	State Highway Agency	(MDT116) Financial District	000 - NONE
(21) Maintenance Responsibility		(MDT117) Neighbor County Code	

Bridge GIS Location			
(16) Latitude (DMS)	44° 33' 33.05"	(17) Longitude (DMS)	-112° 19' 05.43"
Precise Latitude	44.559181	Precise Longitude	-112.318175

Construction Data			
(27) Year Built	1959	(MDT017) MDT Original Construction Project	I-ING 255(12)
(106) Year Reconstructed		(MDT099) MDT Rehab Proj Nbrs	I-G-15-1(44)0, M 15-1(85)0, IM 15-1(107)0
(MDT102) Year Rehabilitated	1978, 1995, 2010	(MDT018) MDT Original Construction Station	3365+00
(MDT019) MDT Original Drawing Number		(MDT106) MDT Rehab Stations	
(MDT103) MDT Rehab Drawing Nbrs	12307, 15990-15993, 20896A-C, 20897A-B, (MDT021) MDT UPN	(MDT101) MDT Rehab UPNs	NONE, I748, 6923000, 4392
(MDT097) Plans in SMS?	Y - Yes		
(MDT098) Shop Drawings in SMS?	1 - Yes-Full		

Span and Dimensional Data			
(33) Bridge Meridian	0 No median	(101) Parallel Structure Designation	Right of I/bridge
(34) Skew	0	(103) Temporary Structure Designation	Not Temporary
(35) Structure Flared	0 No flare	(38) Navigation Control	NA-no waterway
(42A) Type of Service on Bridge	1 Highway	(39) Navigation Vertical Clearance	0.0 ft
(48) Length of Maximum Span	45.0 ft	(40) Navigation Horizontal Clearance	0.0 ft
(49) Structure Length	118.0 ft	(116) Minimum Navigation Vertical Clearance	ft
(53) Min Vertical Clearance over Bridge Roadway	100.0 ft	(MDT008) Depth of Cover	0.00 in



STRUCTURE INSPECTION REPORT
 MDT ID - 01001
 NBI ID - 100015000+05201
 Feature Intersected - INT MONIDA S 509
 Facility - I 15

Inspector - David Monahan
 Inspection Type - Regular NBI
 Inspection Date - 10/26/2022
 Inventory Direction - South to North

Roadway Information (Route On Structure)

Identification	
(MDT035) Road Name	I 15
(5A) Inventory Route - Record	Route On Structure
(5B) Route Signing Prefix	1 Interstate Hwy
(5C) Designated Level of Ser	1 Mainline
(5E) Directional Suffix	1 North
(6B) Critical Facility Indicator	
(MDT087) Mile Post	522
(5D) Route Number	00015
(MDT007) Departmental Route	00015

Traffic Data			
(28A) Lanes on the Structure	2	(29) Average Daily Traffic	1,643
(28B) Lanes Under the Structure	2	(30) Year of Average Daily Traffic	2022
(MDT030) Roadway Speed	80	(109) Average Daily Truck Traffic (%)	31
(114) Future Average Daily Traffic	1,757	(115) Year of Future Avg Daily Traffic	2042

Roadway Clearances			
(10) Minimum Vertical Clearance	99.99 ft	(72) Approach Roadway Alignment	8 Equal Desirable Crit
(47) Total Horizontal Clearance	41.00 ft	(42B) Type of Service Under	1 Highway
(32) Approach Roadway Width	41.00 ft	(51) Bridge Roadway Width Curb-to-Curb	44.00 ft

Highway Networks and Service Classification			
(12) Base Highway Network	On Base Network	(20) Toll	3 On free road
(11) Accumulated Miles	0.50	(26) Functional Classification	01 Rural Interstate
(13A) LRS Number	C000015A	(102) Direction of Traffic	1 1-way traffic

Alternate Classifications			
(100) STRAHNET Highway Designation	1 On Interstate STRAHNET	(110) National Truck Network	1 Part of natl network
(104) NHS Indicator	1 On the NHS	(105) Federal Lands Highways	0 N/A (NBI)

Detour	
(19) Bypass/Detour Length	1.00 mi
(MDT009) Detour Speed	45 mi/hr

Roadway Information (One Route Under)

Identification	
(MDT035) Road Name	S VALLEY RD
(5A) Inventory Route - Record	One Route Under
(5B) Route Signing Prefix	3 State Hwy
(5C) Designated Level of Ser	1 Mainline
(5E) Directional Suffix	0 N/A (NBI)
(6B) Critical Facility Indicator	
(MDT087) Mile Post	00509
(5D) Route Number	500509
(MDT007) Departmental Route	500509

Traffic Data			
(28A) Lanes on the Structure	2	(29) Average Daily Traffic	100
(28B) Lanes Under the Structure	2	(30) Year of Average Daily Traffic	2023
(MDT030) Roadway Speed	35	(109) Average Daily Truck Traffic (%)	3
(114) Future Average Daily Traffic	100	(115) Year of Future Avg Daily Traffic	2038

Roadway Clearances			
(10) Minimum Vertical Clearance	14.00 ft	(72) Approach Roadway Alignment	8 Equal Desirable Crit
(47) Total Horizontal Clearance	40.00 ft	(42B) Type of Service Under	1 Highway
(32) Approach Roadway Width	41.00 ft	(51) Bridge Roadway Width Curb-to-Curb	44.00 ft



STRUCTURE INSPECTION REPORT
 MDT ID - 01001
 NBI ID - 100015000+05201
 Feature Intersected - INT MONIDA S 509
 Facility - 115

Inspector - David Monahan
 Inspection Type - Regular NBI
 Inspection Date - 10/26/2022
 Inventory Direction - South to North



General Bridge Data	
(22) Owner	State Highway Agency
(6A) Feature Intersected	INT MONIDA S 509
(9) Location	MONIDA
(MDT058) Bridge Condition	3-Poor
(SR) Sufficiency Rating	91.00
(Z7) Year Built	1959
(58) Deck Rating	4 Poor
(59) Superstructure	6 Satisfactory
(60) Substructure	6 Satisfactory
(61) Channel	N N/A (NBI)
(62) Culvert	N N/A (NBI)
(MDT145) Inv Direction:	South to North

Inspector - David Monahan
 Inspection Type - Regular NBI
 Inspection Date - 10/26/2022
 Inventory Direction - South to North

ator
 522
 00015
 Route 100015

(114) Future Average Daily Traffic 1,757
 (115) Year of Future Avg Daily Traffic 2042

Alignment 8 Equal Desirable Crt
 der 1 Highway
 th Curb-to-Curb 44.00 ft

ation
 3 On free road
 01 Rural Interstate
 1 1-way traffic

ork
 ways 1 Part of natl network
 0 N/A (NBI)

45 mi/hr

ator
 00509
 Route S00509

(114) Future Average Daily Traffic 100
 (115) Year of Future Avg Daily Traffic 2038

Alignment 8 Equal Desirable Crt
 der 1 Highway
 th Curb-to-Curb 44.00 ft

Location Data		
(MDT001) Agency Structure Name	(MDT031) Railroad Over/Underpass	0 - Not Applicable
(001A) FIP/State	(MDT032) Railroad Owner	NA - Not Applicable
(001B) FHWA Region	(MDT014) Interchange Indicator	1 - Interchange
(MDT027) On/Off System	(MDT015) Interstate Ramp Indicator	0 - Not a Ramp
(112) NBIS Bridge Length	(MDT078) Maintenance Section	21-11 - Lima
(2) MDT Inspection District	(MDT026) Maintenance Division	21 - BUTTE
(3) County Code	(MDT146) Reservation Boundary	
(4) Place Code	(MDT115) Administrative District	2 - Butte
(7) Facility Carried by Structure	(MDT116) Financial District	2 - Butte
(21) Maintenance Responsibility	(MDT117) Neighbor County Code	000 - NONE

Bridge GIS Location		
(16) Latitude (DMS)	44° 33' 33.00"	(17) Longitude (DMS)
Precise Latitude	44.559181	Precise Longitude
		-112° 19' 05.43"
		-112.318175

Construction Data	
(Z7) Year Built	1959
(106) Year Reconstructed	
(MDT102) Year Rehabilitated	1978, 1995, 2010, .
(MDT019) MDT Original Drawing Number	(MDT017) MDT Original Construction Project
(MDT103) MDT Rehab Drawing Nbrs	(MDT099) MDT Rehab Proj Nbrs
(MDT087) Plans in SMS?	(MDT018) MDT Original Construction Station
(MDT088) Shop Drawings in SMS?	(MDT100) MDT Rehab Stations
	(MDT021) MDT UPN
	(MDT101) MDT Rehab UPNs

Span and Dimensional Data		
(33) Bridge Meridian	0 No median	(101) Parallel Structure Designation
(34) Skew	0	(103) Temporary Structure Designation
(35) Structure Flared	0 No flare	(38) Navigation Control
(42A) Type of Service on Bridge	1 Highway	(39) Navigation Vertical Clearance
(48) Length of Maximum Span	45.0 ft	(40) Navigation Horizontal Clearance
(49) Structure Length	118.0 ft	(118) Minimum Navigation Vertical Clearance
(53) Min Vertical Clearance over Bridge Roadway	100.0 ft	(MDT008) Depth of Cover
		0.00 in



STRUCTURE INSPECTION REPORT
 MDT ID - 01001
 NBI ID - 100015000+05201
 Feature Intersected - INT MONIDA S 509
 Facility - 115

Inspector - David Monahan
 Inspection Type - Regular NBI
 Inspection Date - 10/26/2022
 Inventory Direction - South to North

Highway Networks and Service Classification			
(12) Base Highway Network	Not on Base Network	(20) Toll	3 On free road
(11) Accumulated Miles	0.00	(25) Functional Classification	07 Rural Mjr Collector
(13A) LRS Number	C086246A	(102) Direction of Traffic	2 2-way traffic

Alternate Classifications			
(100) STRAHNET Highway Designation	0 Not a STRAHNET Hwy	(110) National Truck Network	0 Not part of natl netwo
(104) NHS Indicator	0 Not on NHS	(105) Federal Lands Highways	0 N/A (NBI)

Detour	
(19) Bypass/Detour Length	0.00 mi
(MDT009) Detour Speed	35 mi/hr

Load Rating

Event Name: IN101001 Rating Date: 10/25/2019
 Load Rater: Damian Silverstrim Reviewer:
 Software Used: AASHTOWare BvR Secondary Software:

Notes: Transferred from SMS Category: Routine
 Wearing Surface or Fill Depth:

Vehicle Name	Current	Load Rating (Tons)	Method	Analysis	Limit State	Location	Notes
HL-93 Inventory	T	102.00	3 LRFR	Load & Res. Fact	Design	NA	SMS Design Transfer
HL-93 Operating	T	141.00	3 LRFR	Load & Res. Fact	Design	NA	SMS Design Transfer
Type 3 LRFR Rating	T	165.00	3 LRFR	Load & Res. Fact	Legal	NA	Transferred from SMS
Type 3S2 LRFR Rating	T	248.00	3 LRFR	Load & Res. Fact	Legal	NA	Transferred from SMS
Type 3-3 LRFR Rating	T	320.00	3 LRFR	Load & Res. Fact	Legal	NA	Transferred from SMS
SU4 LRFR Rating	T	150.00	3 LRFR	Load & Res. Fact	Legal	NA	Transferred from SMS
SU5 LRFR Rating	T	164.00	3 LRFR	Load & Res. Fact	Legal	NA	Transferred from SMS
SU6 LRFR Rating	T	166.00	3 LRFR	Load & Res. Fact	Legal	NA	Transferred from SMS
SU7 LRFR Rating	T	174.00	3 LRFR	Load & Res. Fact	Legal	NA	Transferred from SMS
EV2 LRFR Rating	T	206.00	3 LRFR	Load & Res. Fact	Legal	NA	Transferred from SMS
EV3 LRFR Rating	T	203.00	3 LRFR	Load & Res. Fact	Legal	NA	Transferred from SMS



STRUCTURE INSPECTION REPORT

MDT ID - 01001
 NBI ID - 100015000+05201
 Feature Intersected - INT MONIDA S 509
 Facility - I 15

Inspector - David Monahan
 Inspection Type - Regular NBI
 Inspection Date - 10/26/2022
 Inventory Direction - South to North

David Monahan
 Regular NBI
 10/26/2022
 South to North

David Monahan
 Regular NBI
 10/26/2022
 South to North



General Bridge Data

(22) Owner	State Highway Agency
(8A) Feature Intersected	INT MONIDA S 509
(9) Location	MONIDA
(MDT058) Bridge Condition	3-Floor
(SR) Sufficiency Rating	91.00
(27) Year Built	1959
(58) Deck Rating	4 Floor
(59) Superstructure	6 Satisfactory
(60) Substructure	6 Satisfactory
(61) Channel	N N/A (NBI)
(62) Culvert	N N/A (NBI)
(MDT145) Inv Direction:	South to North

1,757
 2042

ft

ft

ft

Notes

- SMS Design Transfer
- transferred from SMS
- transferred from SMS
- transferred from SMS
- transferred from SMS
- transferred from SMS
- transferred from SMS
- transferred from SMS

100
 2038

ft

ft

ft

Location Data		
(MDT001) Agency Structure Name		(MDT031) Railroad Over/Underpass
(001A) FIP/State	30 Montana	(MDT032) Railroad Owner
(001B) FHWA Region	Region 8-Denver	(MDT014) Interchange Indicator
(MDT027) On/Off System	On System	(MDT015) Interstate Ramp Indicator
(112) NBIS Bridge Length	Long Enough	(MDT078) Maintenance Section
(2) MDT Inspection District	02 - BUTTE	(MDT026) Maintenance Division
(3) County Code	001 - BEAVERHEAD	(MDT146) Reservation Boundary
(4) Place Code	11300 - BUTTE	(MDT115) Administrative District
(7) Facility Carried by Structure	I 15	(MDT116) Financial District
(21) Maintenance Responsibility	State Highway Agency	(MDT117) Neighbor County Code

Bridge GIS Location		
(16) Latitude (DMS)	44° 33' 33.05"	(17) Longitude (DMS)
Precise Latitude	44.559181	Precise Longitude

Construction Data			
(27) Year Built	1959	(MDT017) MDT Original Construction Project	I-ING 255(12)
(106) Year Reconstructed		(MDT099) MDT Rehab Proj Nbrs	I-G-15-1(44)0, IM 15-1(85)0, IM 15-1(107)0
(MDT102) Year Rehabilitated	1978, 1995, 2010	(MDT018) MDT Original Construction Station	3365+00
(MDT019) MDT Original Drawing Number		(MDT100) MDT Rehab Stations	
(MDT103) MDT Rehab Drawing Nbrs	12307, 15990, 15993, 20896A-C, 20897A-B, (MDT023) MDT UPN	(MDT101) MDT Rehab UPNs	NONE, 1748, 6923000, 4392
(MDT087) Plans in SMS?	Y - Yes		
(MDT098) Shop Drawings in SMS?	1 - Yes-Full		

Span and Dimensional Data			
(33) Bridge Meridian	0 No median	(101) Parallel Structure Designation	Right of I/bridge
(34) Skew	0	(103) Temporary Structure Designation	Not Temporary
(35) Structure Flared	0 No flare	(38) Navigation Control	NA-no waterway
(42A) Type of Service on Bridge	1 Highway	(39) Navigation Vertical Clearance	0.0 ft
(48) Length of Maximum Span	45.0 ft	(40) Navigation Horizontal Clearance	0.0 ft
(49) Structure Length	118.0 ft	(116) Minimum Navigation Vertical Clearance	ft
(53) Min Vertical Clearance over Bridge Roadway	100.0 ft	(MDT008) Depth of Cover	0.00 in




STRUCTURE INSPECTION REPORT

MDT ID - 01001
 NBI ID - 100015000+05201
 Feature Intersected - INT MONIDA S 509
 Facility - I 15

Inspector - David Monahan
 Inspection Type - Regular NBI
 Inspection Date - 10/26/2022
 Inventory Direction - South to North

Load Posting Information

Operational Status	Load Posting Requirements
(41) Open/Posted/Closed	A Open, no restriction
(MDT135) Posting Sign Type	(70) Legal Load Status
(MDT067) Type 3 Truck Posting	Load Posting Authorization Date
(MDT073) Truck 3S2 Posting	Required Posting Sign Type
(MDT070) Truck 3-3 Posting	Required Type 3 Truck Posting
(MDT136) Line 1 Number of Axles Posting	Required Type 3S2 Truck Posting
(MDT137) Line 1 GVW Posting	Required Type 3-3 Truck Posting
(MDT142) EV Single Axle Posting	Required Line 1 Number of Axles Posting
(MDT143) EV Tandem Axles Posting	Required Line 1 GVW Posting
(MDT144) EV Gross Weight Posting	Required EV Single Axle Posting
(MDT148) Load Posting Basis	Required EV Tandem Axles Posting
	Required EV Gross Weight Posting



Inspection Activities

Inspector	Signature			
David Monahan	<i>David Monahan</i>			
Start Date	End Date	Weather	Temperature	Comments
10/26/2022	10/26/2022	Cloudy	30	David Monahan (TL), and Katie Christy on-site.
Quality Control Reviewer				
Brandon Willis	<i>Brandon Willis</i>			



STRUCTURE INSPECTION REPORT

MDT ID - 01001
 NBI ID - 100015000+05201
 Feature Intersected - INT MONIDA S 509
 Facility - I 15

Inspector - David Monahan
 Inspection Type - Regular NBI
 Inspection Date - 10/26/2022
 Inventory Direction - South to North

David Monahan
 10/26/2022
 South to North

David Monahan
 10/26/2022
 South to North

David Monahan
 10/26/2022
 South to North



General Bridge Data

(22) Owner	State Highway Agency
(6A) Feature Intersected	INT MONIDA S 509
(9) Location	MONIDA
(MDT058) Bridge Condition	3-Poor
(SR) Sufficiency Rating	91.00
(Z7) Year Built	1959
(58) Deck Rating	4 Poor
(59) Superstructure	6 Satisfactory
(60) Substructure	6 Satisfactory
(61) Channel	N N/A (NBI)
(62) Culvert	N N/A (NBI)
(MDT145) Inv Direction:	South to North

Location Data

(MDT001) Agency Structure Name	30 Montana	(MDT031) Railroad Over/Underpass	0 - Not Applicable
(001A) FIP State	Region 8-Denver	(MDT032) Railroad Owner	NA - Not Applicable
(001B) FHWA Region	On System	(MDT014) Interchange Indicator	1 - Interchange
(MDT027) On/Off System	Long Enough	(MDT015) Interstate Ramp Indicator	0 - Not a Ramp
(112) NBIS Bridge Length	02 - BUTTE	(MDT078) Maintenance Section	21-11 - Lima
(2) MDT Inspection District	001 - BEAVERHEAD	(MDT026) Maintenance Division	21 - BUTTE
(3) County Code	11300 - BUTTE	(MDT146) Reservation Boundary	
(4) Place Code	115	(MDT115) Administrative District	2 - Butte
(7) Facility Carried by Structure	State Highway Agency	(MDT116) Financial District	2 - Butte
(Z1) Maintenance Responsibility		(MDT117) Neighbor County Code	000 - NONE

Bridge GIS Location

(16) Latitude (DMS)	44° 33' 33.05"	(17) Longitude (DMS)	-112° 19' 05.43"
Precise Latitude	44.559181	Precise Longitude	-112.318175

Construction Data

(Z7) Year Built	1959	(MDT017) MDT Original Construction Project	I-ING 255(12)
(106) Year Reconstructed		(MDT099) MDT Rehab Proj Nbrs	I-G-15-1(44)0, IM 15-1(85)0, IM 15-1(107)0
(MDT102) Year Rehabilitated	1978, 1995, 2010, .	(MDT018) MDT Original Construction Station	3365+00
(MDT019) MDT Original Drawing Number		(MDT100) MDT Rehab Stations	
(MDT103) MDT Rehab Drawing Nbrs	12307, 15900-15903, 20896A-C, 20897A-B, (MDT023) MDT UPN	(MDT101) MDT Rehab UPNs	NONE, 1748, 6923000, 4392
(MDT087) Plans in SMS?	Y - Yes		
(MDT088) Shop Drawings in SMS?	1 - Yes-Full		

Span and Dimensional Data

(33) Bridge Meridian	0 No median	(101) Parallel Structure Designation	Right of I/bridge
(34) Skew	0	(103) Temporary Structure Designation	Not Temporary
(35) Structure Flared	0 No flare	(38) Navigation Control	NA-no waterway
(42A) Type of Service on Bridge	1 Highway	(39) Navigation Vertical Clearance	0.0 ft
(48) Length of Maximum Span	45.0 ft	(40) Navigation Horizontal Clearance	0.0 ft
(49) Structure Length	118.0 ft	(116) Minimum Navigation Vertical Clearance	ft
(53) Min Vertical Clearance over Bridge Roadway	100.0 ft	(MDT008) Depth of Cover	0.00 in



STRUCTURE INSPECTION REPORT

MDT ID - 01001
 NBI ID - 100015000+05201
 Feature Intersected - INT MONIDA S 509
 Facility - I 15

Inspector - David Monahan
 Inspection Type - Regular NBI
 Inspection Date - 10/26/2022
 Inventory Direction - South to North

Element Inspection

M Main Span (0)

12 - Re Concrete Deck	Total Quantity	Condition State 1 QTY (PCT)	Condition State 2 QTY (PCT)	Condition State 3 QTY (PCT)	Condition State 4 QTY (PCT)
Inspected: Yes	5,479.00 sq.ft	2,724.00 (49.70%)	2,300.00 (42.00%)	455.00 (8.30%)	0.00 (0.00%)
Environment: Mod.					

Comments:
 CS1: The top of the deck had been re-sealed in some locations prior to the 2022 inspection. The top of the deck exhibited effectively sealed cracks in Span 1 and on the shoulders. The previously noted small areas of rust staining associated with cracking on the deck surface totaling approximately 25 square feet had been effectively sealed.

CS2:
 CS3:
 CS4:

521 - Conc Prot Coating	Total Quantity	Condition State 1 QTY (PCT)	Condition State 2 QTY (PCT)	Condition State 3 QTY (PCT)	Condition State 4 QTY (PCT)
Inspected: Yes	5,479.00 sq.ft	4,109.00 (75.00%)	0.00 (0.00%)	0.00 (0.00%)	1,370.00 (25.00%)

Comments:
 CS1:
 CS2:
 CS3:
 CS4:

3540 - Eff(Crete Protect Coat)	Total Quantity	Condition State 1 QTY (PCT)	Condition State 2 QTY (PCT)	Condition State 3 QTY (PCT)	Condition State 4 QTY (PCT)
Inspected: Yes	1,370.00 sq.ft	0.00 (0.00%)	0.00 (0.00%)	0.00 (0.00%)	1,370.00 (100.00%)

Comments:
 CS1:
 CS2:
 CS3:

CS4: The HMWM crack seal on the top of the deck had lost effectiveness in areas of most severe cracking. (1370 SF)

1080 - Delamination/Spall/Patched Area	Total Quantity	Condition State 1 QTY (PCT)	Condition State 2 QTY (PCT)	Condition State 3 QTY (PCT)	Condition State 4 QTY (PCT)
Inspected: Yes	550.00 sq.ft	0.00 (0.00%)	550.00 (100.00%)	0.00 (0.00%)	0.00 (0.00%)

Comments:
 CS1:

CS2: Hammer sounding on the top of the deck revealed delaminations throughout approximately 10% of the surface area. (550 SF)

CS2:
 CS4:

8/24/2023		EMAIL LOG DATABASE MAINTENANCE TRIGGERED EMAILS FROM DATABASE LOG WITHIN LAST 7 DAYS	Page 1 of 1
TO: kmarcoux@mt.gov;ancompton@mt.gov 8/22/2023 5:49:19PM		Bridge Inspection Completed For Bridge 04079 Bridge 04079 had a Regular NBI inspection dated 07/13/2023 that has been completed. Feature Intersected: YELLOWSTONE RIVER 030 Facility Carried: MILWAUKEE RD Scour Critical Status: 3 SC - Unstable	
TO: kmarcoux@mt.gov;ancompton@mt.gov 8/17/2023 2:14:38PM		Bridge Inspection Completed For Bridge 04516 Bridge 04516 had a Regular NBI inspection dated 08/16/2023 that has been completed. Feature Intersected: YELLOWSTONE RIVER 010 Facility Carried: N YELLOWSTONE TRL Scour Critical Status: 4 Stable, needs action	
TO: mdtridgepost@mt.gov 8/22/2023 4:38:31PM		BrM Item 41 updated for 02124 on MDT Item 41 (Structure Open, Posted or Closed to Traffic) was updated for structure 02124 by John Jackson from value (P Posted for load) to (B Posting Recommended).	
TO: msmith@mt.gov 8/24/2023 7:50:28AM		BrM MDT034 updated for 06378 MDT034 (Request Review of Load Rating) was updated for structure 06378 by Aric Jensen from value (No) to (. Comments: Wearing surface depth measured as 13.5 in. (previously listed as 10 in.), 8/8/2023 routine inspection, Ryan Sievers, Fickett Structural Solutions.	
TO: mdtridgescour@mt.gov 8/23/2023 12:16:51PM		BrM Item 113 updated for 02401 Item 113 (Scour Critical Status) was updated for structure 02401 by Tim Welter from value (5 Stable w/in footing) to (4 Stable, needs action).	
TO: kmarcoux@mt.gov;ancompton@mt.gov 8/22/2023 8:41:56AM		Bridge Inspection Completed For Bridge 04682 Bridge 04682 had a Special inspection dated 05/24/2023 that has been completed. Feature Intersected: WEST FORK POPLAR R 026 Facility Carried: N BENCH RD Scour Critical Status: 3 SC - Unstable	
TO: kmarcoux@mt.gov;ancompton@mt.gov 8/24/2023 8:47:27AM		Bridge Inspection Completed For Bridge 03719 Bridge 03719 had a Fracture Critical inspection dated 06/28/2023 that has been completed. Feature Intersected: BITTERROOT RIVER 010 Facility Carried: NORTH AVE W Scour Critical Status: 7 Countermeasures	
TO: msmith@mt.gov 8/21/2023 8:04:12AM		BrM MDT034 updated for 02443 MDT034 (Request Review of Load Rating) was updated for structure 02443 by Aric Jensen from value (No) to (. Comments: Ryan Sievers notified MDT on 8/3/23 about negative camber and need to review load rating.	
TO: msmith@mt.gov 8/21/2023 2:17:38PM		BrM MDT034 updated for 03828 MDT034 (Request Review of Load Rating) was updated for structure 03828 by Mary Smith from value (.) to (No). Comments: Wearing surface depth changed from 3 inches to 5 inches (see detailed depth of cover sheet), 8/2/2023 routine inspection, J Jackson MDT	
		8/21/2023 review - load rating update not needed, analysis already reflects 5" depth above top of corrugated plank based on 2019 measurements (confirmed in BrR). MDT008 and load rating summary sheet were outdated. Updated load rating summary sheet with comment. M Smith	

8/24/2023		EMAIL LOG DATABASE MAINTENANCE TRIGGERED EMAILS FROM DATABASE LOG WITHIN LAST 7 DAYS	Page 1 of 1
TO: kmarcoux@mt.gov;ancompton@mt.gov 8/22/2023 5:49:19PM		Bridge Inspection Completed For Bridge 04079 Bridge 04079 had a Regular NBI inspection dated 07/13/2023 that has been completed. Feature Intersected: YELLOWSTONE RIVER 030 Facility Carried: MILWAUKEE RD Scour Critical Status: 3 SC - Unstable	
TO: kmarcoux@mt.gov;ancompton@mt.gov 8/17/2023 2:14:38PM		Bridge Inspection Completed For Bridge 04516 Bridge 04516 had a Regular NBI inspection dated 08/16/2023 that has been completed. Feature Intersected: YELLOWSTONE RIVER 010 Facility Carried: N YELLOWSTONE TRL Scour Critical Status: 4 Stable, needs action	

MONTANA



Lewis And Clark County Bridge Summary for Quarter 2 2023 (April 1 - June 30)

This is a bridge inspection summary report and includes bridges that have been inspected and had quality control performed during Quarter 2 2023 (April 1 - June 30).
 Bridges included in this report are bridges that are in Lewis And Clark county and are either owned and/or maintained by the county or a city within the county.
 This is a summary report and does not include all important information related to the bridge and may also not include all bridges in Lewis And Clark County . Please go to BrM and review each bridge inspection report.

Section 1 includes bridge condition summary information and Section 2 contains open bridge work recommendations.
 For questions about bridge inspection reports or work recommendations contact your area bridge inspection manager.
 For help with access to BrM contact Leanne Moyer.

Bridge Condition Summary:

Bridges have condition components rated on a 0 to 9 scale as part of the National Bridge Inspection Program. The lowest condition rating is used to determine if a bridge is in good, fair, or poor condition. If the lowest condition rating for a bridge is a 7 or greater it is considered good, 5 or 6 is fair, and 4 or lower is poor.

	Inspection Dates	Deck Rating	Superstructure Rating	Substructure Rating	Culvert Rating
MDT ID: 04932 NBI ID: M25037000+00201 Owner: City or Municipal Highway Agency Maintenance: City or Municipal Highway Agency Posting Status: A Open, no restriction Facility: E RIGGS ST Feature: PRICKLY PEAR CREEK 083 Location: EAST HELENA-E RIGGS ST Lat/Long: (46.590358, -111.921091)	Current: 03/06/2023 <i>Previous: 03/01/2021</i>	Current: 7 Good <i>Previous: 7 Good</i>	Current: 8 Very Good <i>Previous: 8 Very Good</i>	Current: 7 Good <i>Previous: 7 Good</i>	Current: N N/A (NBI) <i>Previous: N N/A (NBI)</i>
MDT ID: 03361 NBI ID: L25049002+02001 Owner: County Highway Agency Maintenance: County Highway Agency Posting Status: A Open, no restriction Facility: VALLEY DR Feature: HELENA VALLEY CANAL 074 Location: 2M N EAST HELENA Lat/Long: (46.614231, -111.914608)	Current: 04/04/2023 <i>Previous: 12/15/2022</i>	Current: 8 Very Good <i>Previous: 8 Very Good</i>	Current: 8 Very Good <i>Previous: 8 Very Good</i>	Current: 8 Very Good <i>Previous: 8 Very Good</i>	Current: N N/A (NBI) <i>Previous: N N/A (NBI)</i>
MDT ID: 03364 NBI ID: L25100000+07001 Owner: County Highway Agency Maintenance: County Highway Agency Posting Status: A Open, no restriction Facility: LAKE HELENA DR Feature: CAUSEWAY-LAKE HELENA 072	Current: 03/06/2023 <i>Previous: 04/02/2021</i>	Current: 7 Good <i>Previous: 7 Good</i>	Current: 7 Good <i>Previous: 7 Good</i>	Current: 6 Satisfactory <i>Previous: 6 Satisfactory</i>	Current: N N/A (NBI) <i>Previous: N N/A (NBI)</i>



Request Review of Load Rating Report as of 8/24/2023

MDT ID	Request Review of Load Rating	Request Notes	Depth of Cover	Depth of Cover Notes	Inspection Date	INSPECTOR	Entered By	Rating Date	Name of Load Rater	Rating Event Date	Name of Load Rater Event
01391		change section loss or adjust Conc			04/27/2023	Drew Sielbach	endan Prendevi	09/05/2017	Devin Roberts	09/05/2017	Devin Roberts
01543		1 impacted and have had 2 stands			05/03/2023	David Crumley	Tim Welter	04/26/2019	Jason R. Krempf	04/26/2019	Jason R. Krempf
01587		nd have had 2 bars of mild steel v			05/04/2023	David Crumley	Tim Welter	10/29/2019	Damian Silverstrim	10/29/2019	Damian Silverstrim
01960		ion in the pipe walls. 6/15/2023 R			06/15/2023	Jeff Malone	Ryan Kaskie			01/01/1901	
02172		ize than reflected in 2021 rating. I			01/16/2023	Benjamin Schaefer	Benjamin Schaefer	09/22/2021	Damian Silverstrim	09/22/2021	Damian Silverstrim
02283		as corrugated decking. Measure			03/27/2023	William Lay	William Lay	03/01/2022	Jason Wolfe	03/01/2022	Jason Wolfe
02335		s replaced by corrugated steel. V			04/21/2023	William Lay	William Lay	03/04/2022	Ryan Sherman	03/04/2022	Ryan Sherman
02438	rchived brides) Yes-chan				08/11/2021	Mitchell Pratt	Mitchell Pratt	12/29/2020	Michael Metcalf	12/29/2020	Michael Metcalf
02443		3 Critical Inspection, Ryan Sievers			07/30/2023	Ryan Sievers	Aric Jensen	12/03/2020	Anderson Potter	12/03/2020	Anderson Potter
02525					08/10/2022	William Lay	William Lay			01/01/1901	
02583		1 since the previous inspection an			06/11/2023	Brandon Willis	Bri Sievenpiper	12/21/2022	Jason Zimpfer	12/21/2022	Jason Zimpfer
02674					07/11/2023	John Jackson	Ethan Smartnick	04/03/2020	Brett Canimore	04/03/2020	Brett Canimore
02686		replaced by a new timber wearing			05/01/2023	John Jackson	John Jackson	01/28/2020	Brett Canimore	01/28/2020	Brett Canimore
02744		to new timber deck and running p			11/28/2022	Gary Gotschall	Gary Gotschall	02/17/2022	Jason Zimpfer	02/17/2022	Jason Zimpfer
02965		tailed depth of cover measureme		gated plank. See detailed d	08/02/2023	John Jackson	Ethan Smartnick	09/17/2019	Brett Canimore	09/17/2019	Brett Canimore
03201		r changed from 8 in. to 9 in. base			09/13/2022	Kyle Branham	Allison Dagesse	05/04/2022	Kayla Jacobsen	05/04/2022	Kayla Jacobsen
03279	ved brides) Yes-change	cap at bent 2 is failing and needs i			09/02/2021	Darrel Reich	Darrel Reich	01/17/2022	Jason Zimpfer	01/17/2022	Jason Zimpfer
03349		hops and Measurements. It is rec			10/17/2022	Allison Dagesse	Allison Dagesse	11/09/2020	Kyle Dana	11/09/2020	Kyle Dana
03375		details. Additional girder, new de			07/11/2023	William Lay	William Lay	09/22/2021	Damian Silverstrim	09/22/2021	Damian Silverstrim
03719		beams and stringers that was not			06/28/2023	Ryan Sievers	Kirsten Maxwell	12/27/2019	Brett Canimore	12/27/2019	Brett Canimore
03749		plan deformation. Please see dete			06/13/2023	Edward Cinadr	Jacob Molnar	04/15/2020	Brett Canimore	04/15/2020	Brett Canimore
03830		level per NBI 41 notes (4/12/202			05/18/2023	John Jackson	John Jackson	07/07/2020	Brett Canimore	07/07/2020	Brett Canimore
04056	ed brides) Yes-change in				08/09/2023	Mitchell Pratt	Mitchell Pratt	01/28/2020	Brett Canimore	01/28/2020	Brett Canimore
04702		ure rating from 5 to 4 due to adva			11/01/2022	Jerem Joyce	Jim Shields	02/05/2020	Michael Philpot	02/05/2020	Michael Philpot
04713		m 2020-2022 inspections - 3 piles			11/18/2022	Christopher Bowers	Jacob Dahlgren	02/05/2020	Michael Philpot	02/05/2020	Michael Philpot
04718		ss has advanced since last inspei			04/17/2023	Andy Kubic	Allison Dagesse	12/29/2010	crh	12/29/2010	crh
05169		rating be updated to reflect the in			02/06/2023	Jarrod Plummer	Jarrod Plummer	06/30/2022	Kayla Jacobsen	06/30/2022	Kayla Jacobsen
05170		nts. MDT034 Request Review of			10/21/2022	Allison Dagesse	Allison Dagesse	06/30/2022	Kayla Jacobsen	06/30/2022	Kayla Jacobsen
05273		1 spans between the sliding plate			08/03/2023	Edward Cinadr	Zach Bunker	06/14/2021	Jason Zimpfer	06/14/2021	Jason Zimpfer
05870		ad value in BrM (3.25 in.). It is rec			08/26/2022	Michael Banasiak	Allison Dagesse	03/03/2022	Sarah Ringling	03/03/2022	Sarah Ringling
06378		/ listed as 10 in.), 8/8/2023 routine		23 routine inspection, Ryar	08/08/2023	Ryan Sievers	Kirsten Maxwell	10/22/2020	Ryan Sherman	10/22/2020	Ryan Sherman
06529		verlay pre 2022 inspection. - Over		21/2022 - see MAR report ir	04/27/2023	David Crumley	David Crumley	10/29/2019	Damian Silverstrim	10/29/2019	Damian Silverstrim
06581		ing) was changed to Yes - change			09/27/2022	Brandon Willis	Brandon Willis	12/22/2010	AKJ	12/22/2010	AKJ
06582		1 rating be updated to reflect the ir			09/27/2022	Brandon Willis	Brandon Willis	03/21/2022	Kayla Jacobsen	03/21/2022	Kayla Jacobsen
06596		ad that the load rating be updated			09/16/2022	Kyle Branham	Allison Dagesse	11/09/2020	Kayla Jacobsen	11/09/2020	Kayla Jacobsen
06721		ad the load rating be updated to re			09/14/2022	Kyle Branham	Allison Dagesse	08/09/2021	Kyle Dana	08/09/2021	Kyle Dana
06757		is changed to 6 in. based on field			10/20/2022	Allison Dagesse	Allison Dagesse	11/09/2020	Jason Wolfe	11/09/2020	Jason Wolfe

AASHTO Ware™



BRIDGE MANAGEMENT

MONTANA

Interstate bridge inspections that have been finished since 4/ 1/2023 as of 8/24/2023

Table with columns: MCH ID, NBI ID, Ref Post, Con Year, Reason Year, Const Date, Cost (Total), Len (Total), Post, Structure Length (ft), Max Span Length (ft), Main Num Span, Main Design, Main Material, Approach Num Span, Approach Design, Approach Material, Structure Type, Surface Type, Depth of Cover, Current Inspection Date, Current Deck Rating, Current Super Rating, Current Sub Rating, Current Cul Rating, Previous Inspection Date, Previous Deck Rating, Previous Super Rating, Previous Sub Rating, Previous Cul Rating.



AASHTO Ware™
 **BRIDGE**
MANAGEMENT

SCDOT®



SOUTH CAROLINA



Bridge Inspection Report

07175

Team Leader: Russell Aikens
 Inspection Date: 09/07/2023
 Inspection Type(s): Routine
 (7) Facility Carried: S-42-1061
 (8) Crossing: TRIB TO BUCK CREEK
 (16) Latitude: 35.15°
 (17) Longitude: -81.95°

IDENTIFICATION			
Asset ID:	07175	(009) Location:	5 MI. W. OF CHESNEE
(468) Structure Number:	4270109100100	(041) Traffic Status:	A Open, no restriction
(002) District:	District 3	(003) County:	(42) Spartanburg
(42A) Type of Service On:	1 Highway	(004) Placecode:	(027) Year Built: 1978
(006) Feature Intersected:	TRIB TO BUCK CREEK	(022) Owner:	State Highway Agency
(42B) Type of Service Under:	5 Waterway	(011) Mile Post:	0.465 mi (0.749 km)
		(021) Custodian:	01 SCDOT
		(106) Year Recon:	0
		(037) Historical:	5 Not eligible for NRHP

CONDITION AND APPRAISAL			
(058) Deck Structure Condition:	7 Good	(602) Bridge Railing Condition:	
(059) Superstructure Condition:	7 Good	(603) Bridge Railing Trans. Condition:	
(060) Substructure Condition:	5 Fair	(604) Bridge Bearing Condition:	
(062) Culvert Retaining Condition:	N N/A (NBI)	(605) Bridge Joint Condition:	
(600) LW Substructure Condition:		(072) Appr Roadway Align Appraisal:	8 Equal Desirable Cnt
(061) Channel Condition:	8 Protected	(071) Waterway Adequacy:	8 Equal Desirable
(601) Channel Protection Condition:		(113) Scour Condition:	U Unknown Scour

GEOMETRY			
(034) Skew:	0	(032) Approach Roadway:	28.0
(035) Structure Flared:	0 No flare	(051) Curb To Curb Width:	31.5
(049) Structure Length:	60.0	(052) Deck Width Out-To-Out:	33.1
(619) Curved Bridge:		(441) Deck Area:	
(620) Maximum Height Bridge:	0	(033) Bridge Medians:	0 No median
(621) Side Hill Bridge:		(50A) Curb Sidewalk Width/Left:	0.0
(26A) Lanes On Structure:	2	(50B) Curb Sidewalk Width/Right:	0.0
(26B) Lanes Under Structure:	0		


DECK	
Deck Material and Type	
(500) Deck Overburden Type:	
(501) Deck Overburden Depth (in):	
(107) Deck Type:	2 Concrete Precast Panel
(108A) Wearing Surface:	6 Bituminous
(108B) Membrane:	0 None
(108C) Deck Protection:	0 None



DECK CONDITION	
Roadside Hardware	
(36A) Bridge Rail:	0 Substandard
(36B) Transition:	0 Substandard
(36C) Approach Rail:	0 Substandard
(36D) Approach Rail Ends:	0 Substandard



SOUTH CAROLINA



Bridge Inspection Report
 07175

Team Leader: Russell Aikens
 Inspection Date: 09/07/2023
 Inspection Type(s): Routine

(7) Facility Carried: S-42-1091
 (8) Crossing: TRIB TO BUCK CREEK
 (16) Latitude: 35.15°
 (17) Longitude: -81.95°

IDENTIFICATION

Asset ID: 07175	(009) Location: 5 MI. W. OF CHESNEE
(468) Structure Number: 4270109100100	(041) Traffic Status: A Open, no restriction
(002) District: District 3	(003) County: (42) Spartanburg (021) Custodian: 01 SCDOT
(42A) Type of Service On: 1 Highway	(004) Placecode: (027) Year Built: 1978
(006) Feature Intersected: TRIB TO BUCK CREEK	(022) Owner: State Highway Agency (106) Year Recon: 0
(42B) Type of Service Under: 5 Waterway	(011) Mile Post: 0.465 mi (0.749 km) (037) Historical: 5 Not eligible for NRHP

CONDITION AND APPRAISAL


(058) Deck Structure Condition: 7 Good	(602) Bridge Railing Condition:
(059) Superstructure Condition: 7 Good	(603) Bridge Railing Trans. Condition:
(060) Substructure Condition: 5 Fair	(604) Bridge Bearing Condition:
(062) Culvert Retaining Condition: N N/A (NBI)	(605) Bridge Joint Condition:
(600) U/W Substructure Condition:	(072) Appr Roadway Align Appraisal: 8 Equal Desirable Cnt
(061) Channel Condition: 8 Protected	(071) Waterway Adequacy: 8 Equal Desirable
(601) Channel Protection Condition:	(113) Scour Condition: U Unknown Scour

GEOMETRY

(034) Skew: 0	(032) Approach Roadway: 28.0
(035) Structure Flared: 0 No flare	(051) Curb to Curb Width: 31.5
(049) Structure Length: 80.0	(052) Deck Width Out-To-Out: 33.1
(619) Curved Bridge:	(441) Deck Area:
(620) Maximum Height Bridge: 0	(033) Bridge Medians: 0 No median
(621) Side Hill Bridge:	(50A) Curb Sidewalk Width/Left: 0.0
(26A) Lanes On Structure: 2	(50B) Curb Sidewalk Width/Right: 0.0
(26B) Lanes Under Structure: 0	

DECK


Deck Material and Type
 (500) Deck Overburden Type:
 (501) Deck Overburden Depth (in):
 (107) Deck Type: 2 Concrete Precast Panel
 (108A) Wearing Surface: 6 Bituminous
 (108B) Membrane: 0 None
 (108C) Deck Protection: 0 None



DECK CONDITION

Roadside Hardware	
(36A) Bridge Rail:	0 Substandard
(36B) Transition:	0 Substandard
(36C) Approach Rail:	0 Substandard
(36D) Approach Rail Ends:	0 Substandard

Bridge Inspection Report
Tue 09/12/2023
Page 1 of 13



Bridge Inspection Report
 07175

Team Leader: Russell Aikens
 Inspection Date: 09/07/2023
 Inspection Type(s): Routine




(7) Facility Carried: S-42-1091
 (8) Crossing: TRIB TO BUCK CREEK
 (16) Latitude: 35.15°
 (17) Longitude: -81.95°




ELEMENT NOTES

ELEM/ENV	ELEMENT NAME	QUANTITY	UNITS	QTY ST 1	QTY ST 2	QTY ST 3	QTY ST 4
15/1	Pre Concrete Top Flange	993	ft²	993	0	0	0
PRECAST REINFORCED CONCRETE SLABS IN APPROACH SPANS AND PRESTRESSED CONCRETE CHANNEL SLABS IN MAIN SPAN WITH ASPHALT 2 OVERLAY. (NO DEFICIENCIES NOTED)							
16/1	Re Conc Top Flange	993	ft²	993	0	0	0
PRECAST REINFORCED CONCRETE SLABS IN APPROACH SPANS AND PRESTRESSED CONCRETE CHANNEL SLABS IN MAIN SPAN WITH ASPHALT 2 OVERLAY. (NO DEFICIENCIES NOTED)							
105/1	Re Cast Box Girder	210	ft	210	0	0	0
SEVEN PRECAST REINFORCED CONCRETE SLABS IN SPANS 1 AND 3. ELEVEN PRESTRESSED CONCRETE CHANNEL SLABS IN SPAN 2 (LARGE TYPE). (DEFICIENCIES) -THE RODS LOOSE IN SPAN 2.							
109/1	Pre Opn Conc Girder/Beam	330	ft	330	0	0	0
SEVEN PRECAST REINFORCED CONCRETE SLABS IN SPANS 1 AND 3. ELEVEN PRESTRESSED CONCRETE CHANNEL SLABS IN SPAN 2 (LARGE TYPE). (DEFICIENCIES) -THE RODS LOOSE IN SPAN 2.							
225/1	Steel Pile	2	each	2	0	0	0
BENTS 1, 3, AND 4 HAVE SIX TREATED TIMBER PILES. BENT 2 HAS FOUR TREATED TIMBER PILES AND TWO STEEL PILES ALL WITH CONCRETE CAPS. -PILE 4 OF BENT 3 HAS BEEN REPAIRED WITH STEEL H PILE (03-2016). (DEFICIENCIES) -PILE 1 OF BENT 2 HAS LIGHT DECAY WITH 7% SECTION LOSS							
228/1	Timber Pile	22	each	20	2	0	0
BENTS 1, 3, AND 4 HAVE SIX TREATED TIMBER PILES. BENT 2 HAS FOUR TREATED TIMBER PILES AND TWO STEEL PILES ALL WITH CONCRETE CAPS. -PILE 6 OF BENT 3 HAS BEEN REPAIRED WITH STEEL H PILE (03-2016). (DEFICIENCIES) -PILE 1 OF BENT 2 HAS LIGHT DECAY WITH 7% SECTION LOSS							
1140/1	Decay/Section Loss	1	each	0	1	0	0
Inserted by Bridge Inspection App Interface on 05/15/2022 08:49:59 AM							

Bridge Inspection Report
Tue 09/12/2023
Page 5 of 13

SOUTH CAROLINA

SCDOT		Bridge Inspection Report		07175
Team Leader: Russell Aikens		(7) Facility Carried: S-42-1091		Inspection Date: 09/07/2023
Inspection Type(s): Routine		(8) Crossing: TRIB TO BUCK CREEK		(16) Latitude: 35.15°
		(17) Longitude: -81.95°		
IDENTIFICATION				
Asset ID: 07175	(009) Location: 5 MI. W. OF CHESNEE	(041) Traffic Status: A Open, no restriction	(021) Custodian: 01 SCDOT	
(468) Structure Number: 4270109100100	(003) County: (42) Spartanburg	(004) Placecode: (027) Year Built: 1978	(106) Year Recon: 0	
(002) District: District 3	(022) Owner: State Highway Agency	(037) Historical: 5 Not eligible for NRHP		
(42A) Type of Service On: 1 Highway	(011) Mile Post: 0.465 mi (0.749 km)			
(006) Feature Intersected: TRIB TO BUCK CREEK				
(42B) Type of Service Under: 5 Waterway				
CONDITION AND APPRAISAL				
(058) Deck Structure Condition: 7 Good	(602) Bridge Railing Condition: 7 Good	(603) Bridge Railing Trans. Condition: 5 Fair	(604) Bridge Bearing Condition: N N/A (NBI)	(605) Bridge Joint Condition: 8 Equal Desirable Cnt
(059) Superstructure Condition: 7 Good	(072) Appr Roadway Align Appraisal: 8 Equal Desirable	(071) Waterway Adequacy: U Unknown Scour		
(060) Substructure Condition: 5 Fair	(113) Scour Condition: 0			
(062) Culvert Retaining Condition: N N/A (NBI)				
(060) LW Substructure Condition: 8 Protected				
(061) Channel Condition: 8 Protected				
(061) Channel Protection Condition: U Unknown Scour				
GEOMETRY				
(034) Skew: 0	(032) Approach Roadway: 28.0	(051) Curb to Curb Width: 31.5	(052) Deck Width Out-To-Out: 33.1	(441) Deck Area: 0 No median
(035) Structure Flared: 0 No flare	(051) Curb to Curb Width: 31.5	(052) Deck Width Out-To-Out: 33.1	(033) Bridge Medians: 0 No median	(050) Curb Sidewalk Width/Left: 0.0
(049) Structure Length: 60.0	(052) Deck Width Out-To-Out: 33.1	(441) Deck Area: 0	(033) Bridge Medians: 0 No median	(050) Curb Sidewalk Width/Left: 0.0
(619) Curved Bridge: 0	(441) Deck Area: 0	(033) Bridge Medians: 0 No median	(050) Curb Sidewalk Width/Left: 0.0	(50B) Curb Sidewalk Width/Right: 0.0
(620) Maximum Height Bridge: 0	(050) Curb Sidewalk Width/Left: 0.0	(50B) Curb Sidewalk Width/Right: 0.0		
(621) Side Hill Bridge: 2				
(26A) Lanes On Structure: 0				
(26B) Lanes Under Structure: 0				
DECK				
Deck Material and Type				
(500) Deck Overburden Type: 2 Concrete Precast Panel				
(501) Deck Overburden Depth (in): 8 Bituminous				
(107) Deck Type: 0 None				
(108A) Wearing Surface: 0 None				
(108B) Membrane: 0 None				
(108C) Deck Protection: 0 None				
DECK CONDITION				
Roadside Hardware				
(36A) Bridge Rail: 0 Substandard				
(36B) Transition: 0 Substandard				
(36C) Approach Rail: 0 Substandard				
(36D) Approach Rail Ends: 0 Substandard				
Report				
Team Leader: Russell Aikens		(7) Facility Carried: S-42-1091		Inspection Date: 09/07/2023
Inspection Type(s): Routine		(8) Crossing: TRIB TO BUCK CREEK		(16) Latitude: 35.15°
		(17) Longitude: -81.95°		
INSPECTION PHOTOS				
				
Photo 1: Typical Steel H-Pile		Photo 2: Erosion at southeast corner		
INSPECTION SKETCHES				
				
Sketch 1: Example sketch				

SCDOT		Bridge Inspection Report		07175
Team Leader: Russell Aikens		(7) Facility Carried: S-42-1091		Inspection Date: 09/07/2023
Inspection Type(s): Routine		(8) Crossing: TRIB TO BUCK CREEK		(16) Latitude: 35.15°
		(17) Longitude: -81.95°		
INSPECTION PHOTOS				
				
Photo 1: Typical Steel H-Pile		Photo 2: Erosion at southeast corner		
INSPECTION SKETCHES				
				
Sketch 1: Example sketch				

SOUTH CAROLINA

SCDOT Bridge Inspection Report **07175**

Team Leader: Russell Atkins (7) Facility Carried: S-42-1091
 Inspection Date: 09/07/2023 (8) Crossing: TRIB TO BUCK CREEK
 Inspection Type(s): Routine (16) Latitude: 35.15°
 (17) Longitude: -81.95°

IDENTIFICATION

Asset ID: 07175 (009) Location: 5 MI. W. OF CHESNEE
 (468) Structure Number: 4270109100100 (041) Traffic Status: A Open, no restriction
 (002) District: District 3 (003) County: (42) Spartanburg (021) Custodian: 01 SCDOT
 (42A) Type of Service On: 1 Highway (004) Placecode: (027) Year Built: 1978
 (006) Feature Intersected: TRIB TO BUCK CREEK (022) Owner: State Highway Agency (106) Year Recon: 0
 (42B) Type of Service Under: 5 Waterway (011) Mile Post: 0.465 mi (0.749 km) (037) Historical: 5 Not eligible for NRHP

CONDITION AND APPRAISAL

(058) Deck Structure Condition: 7 Good (602) Bridge Railing Condition:
 (059) Superstructure Condition: 7 Good (603) Bridge Railing Trans. Condition:
 (060) Substructure Condition: 5 Fair (604) Bridge Bearing Condition:
 (062) Culvert Retaining Condition: N N/A (NBI) (605) Bridge Joint Condition
 (600) UW Substructure Condition: (072) Appr Roadway Align Appraisal: 8 Equal Desirable Crt
 (061) Channel Condition: 8 Protected (071) Waterway Adequacy: 8 Equal Desirable
 (601) Channel Protection Condition: (113) Scour Condition: U Unknown Scour

GEOMETRY

(034) Skew: 0 (032) Approach Roadway: 28.0
 (035) Structure Flared: 0 No flare (051) Curb To Curb Width: 31.5
 (048) Structure Length: 60.0 (052) Deck Width Out-To-Out: 33.1
 (619) Curved Bridge:
 (620) Maximum Height Bridge: 0 (441) Deck Area:
 (621) Side Hill Bridge: 0 (033) Bridge Medians: 0 No median
 (28A) Lanes On Structure: 2 (50A) Curb Sidewalk Width/Left: 0.0
 (28B) Lanes Under Structure: 0 (50B) Curb Sidewalk Width/Right: 0.0

DECK

Deck Material and Type
 (500) Deck Overburden Type:
 (501) Deck Overburden Depth (in):
 (107) Deck Type: 2 Concrete Precast Panel
 (108A) Wearing Surface: 0 Bituminous
 (108B) Membrane: 0 None
 (108C) Deck Protection: 0 None

DECK CONDITION


Roadside Hardware
 (36A) Bridge Rail: 0 Substandard
 (36B) Transition: 0 Substandard
 (36C) Approach Rail: 0 Substandard
 (36D) Approach Rail Ends: 0 Substandard

Bridge Inspection Report Tue 09/12/2023 Page 1 of 13

07175

(7) Facility Carried: S-42-1091
 Crossing: TRIB TO BUCK CREEK
 (16) Latitude: 35.15°
 (17) Longitude: -81.95°

ST 3	QTY	ST 4
0		0



ST 3	QTY	ST 4
0		0

ST 3	QTY	ST 4
0		0

ST 3	QTY	ST 4
0		0

ST 3	QTY	ST 4
0		0

ST 3	QTY	ST 4
0		0

Bridge Inspection Report Tue 09/12/2023 Page 5 of 13

07175

(7) Facility Carried: S-42-1091
 Crossing: TRIB TO BUCK CREEK
 (16) Latitude: 35.15°
 (17) Longitude: -81.95°

Bridge Inspection Report Tue 09/12/2023 Page 6 of 13

SCDOT Bridge Inspection Report **07175**

Team Leader: Russell Atkins (7) Facility Carried: S-42-1091
 Inspection Date: 09/07/2023 (8) Crossing: TRIB TO BUCK CREEK
 Inspection Type(s): Routine (16) Latitude: 35.15°
 (17) Longitude: -81.95°

PROCEDURES FOR THIS INSPECTION

Done	Insp Type	Procedure Type	Procedure Name	Details
S	Routine	Routine (Typical)	Inspection: Posting Photos	Photographs of at bridge and advance (if present) posting or weight limit signs are required to be taken during all routine inspections. These requirements are applicable to the posting or weight limit signs at the bridge and in advance of the bridge which could require many signs to be photographed. These signs include R-12-6-48 and R-12-7-48 (legal loads), and R-12-9-36 (EV weight limit) at both ends of the bridge. Per BIGD 5.4.4.2 (TN03).
S	Routine	Routine (Typical)	Inspection: Pile Sketch	Pile Sketch Table required when NBI Item 60 Condition Rating = 5. Per BIGD 5.3.3.1 and 5.4.4.5.
S	Routine	Routine (Typical)	Inspection: Timber Sounding	Sound full length of exposed timber piles (including through bolts) per BIGD 5.3.3.1 and 5.3.3.2.1.
S	Routine	Routine (Typical)	Inspection: Defect Photos	Any NBE (element) with CS3 or CS4 Any deterioration causing an NBE (element) to have a CS3 or CS 4 documented with a photograph. Per BIGD 5.4.4.2.
S	Routine	Routine (Typical)	Post-Inspection: Data Verification	Verify the correct: 1) Traffic Status (NBI 041), 2) Inspection Intervals (NBI 090 to 093), 3) Bridge Condition (NBI 58, 59, 60 or 62), 4) Rating Values (NBI 064 and 066), and 5) Sign Posting Values (SBI 443 to 448 and 889).
S	Routine	Routine (Typical)	Post-Inspection: Requests	Confirm that all Inspection Requests are included as both scheduled inspections in the Schedule Table and the Requests Table when needed.

Inspector Procedure Notes

EQUIPMENT USED IN THIS INSPECTION

Name	Hours	Cost
Inspector Equipment Notes		

Bridge Inspection Report Tue 09/12/2023 Page 12 of 13

SOUTH CAROLINA

SCDOT Bridge Inspection Report **07175**

Team Leader: Russell Aikens (7) Facility Carried: S-42-1091
 Inspection Date: 09/07/2023 (8) Crossing: TRIB TO BUCK CREEK
 Inspection Type(s): Routine (16) Latitude: 35.15°
 (17) Longitude: -81.95°

IDENTIFICATION

Asset ID: 07175 (099) Location: 5 MI. W. OF CHESNEE
 (468) Structure Number: 4270106100100 (041) Traffic Status: A Open, no restriction
 (002) District: District 3 (003) County: (42) Spartanburg (021) Custodian: 01 SCDOT
 (42A) Type of Service On: 1 Highway (004) Placecode: (027) Year Built: 1978
 (006) Feature Intersected: TRIB TO BUCK CREEK (022) Owner: State Highway Agency (106) Year Recon: 0
 (42B) Type of Service Under: 5 Waterway (011) Mile Post: 0.465 mi (0.749 km) (037) Historical: 5 Not eligible for NRHP

CONDITION AND APPRAISAL

(058) Deck Structure Condition: 7 Good (602) Bridge Railing Condition:
 (059) Superstructure Condition: 7 Good (603) Bridge Railing Trans. Condition:
 (060) Substructure Condition: 5 Fair (604) Bridge Bearing Condition:
 (062) Culvert Retaining Condition: N N/A (NB) (605) Bridge Joint Condition
 (060) UW Substructure Condition: (072) Appr Roadway Align Appraisal: 8 Equal Desirable Crt
 (061) Channel Condition: 8 Protected (071) Waterway Adequacy: 8 Equal Desirable
 (601) Channel Protection Condition: (113) Scour Condition: U Unknown Scour

GEOMETRY

(034) Skew: 0 (032) Approach Roadway: 28.0
 (035) Structure Flared: 0 No Flare (051) Curb to Curb Width: 31.5
 (049) Structure Length: 60.0 (052) Deck Width Out-To-Out: 33.1
 (619) Curved Bridge:
 (620) Maximum Height Bridge: 0 (441) Deck Area:
 (621) Side Hill Bridge: 0 (033) Bridge Medians: 0 No median
 (28A) Lanes On Structure: 2 (50A) Curb Sidewalk Width/Left: 0.0
 (28B) Lanes Under Structure: 0 (50B) Curb Sidewalk Width/Right: 0.0

DECK

Deck Material and Type
 (500) Deck Overburden Type:
 (501) Deck Overburden Depth (in):
 (107) Deck Type: 2 Concrete Precast Panel
 (108A) Wearing Surface: 6 Bituminous
 (108B) Membrane: 0 None
 (108C) Deck Protection: 0 None

DECK CONDITION

Roadside Hardware
 (36A) Bridge Rail: 0 Substandard
 (36B) Transition: 0 Substandard
 (36C) Approach Rail: 0 Substandard
 (36D) Approach Rail Ends: 0 Substandard

Bridge Inspection Report Tue 09/12/2023 Page 1 of 13

07175


(7) Facility Carried: S-42-1091
 Crossing: TRIB TO BUCK CREEK
 (16) Latitude: 35.15°
 (17) Longitude: -81.95°

ST 3	QTY	ST 4
0		0

Bridge Inspection Report Tue 09/12/2023 Page 5 of 13

07175

(7) Facility Carried: S-42-1091
 Crossing: TRIB TO BUCK CREEK
 (16) Latitude: 35.15°
 (17) Longitude: -81.95°



mer

ST 3	QTY	ST 4
0		0

Bridge Inspection Report Tue 09/12/2023 Page 8 of 13

07175

(7) Facility Carried: S-42-1091
 Crossing: TRIB TO BUCK CREEK
 (16) Latitude: 35.15°
 (17) Longitude: -81.95°

advance (if present) are required to be posted in advance of the posting or in advance of the many signs to be include R-12-6-48 and R-12-9-36 (EV) be bridge. Per BIGD then NBI Item 60 SD 5.3.3.1 and timber piles BIGD 5.3.3.1 and or CS4 Any (element) to have a photograph. Per status (NBI 041), 2) to 093), 3) Bridge 52), 4) Rating Values on Posting Values requests are included in the Schedule when needed.

Bridge Inspection Report Tue 09/12/2023 Page 12 of 13

SCDOT Bridge Inspection Report **07175**

Team Leader: Russell Aikens (7) Facility Carried: S-42-1091
 Inspection Date: 09/07/2023 (8) Crossing: TRIB TO BUCK CREEK
 Inspection Type(s): Routine (16) Latitude: 35.15°
 (17) Longitude: -81.95°

INSPECTOR SIGNATURE AND QC/QA INFORMATION

INSPECTED BY: Russell Aikens
 REPORT AUTHOR: Ryan Thrush

Willie R. Giles
 Date: 9/7/2023


QC Reviewed By: QA Completed:
 QA Reviewed By: QA Completed:

REGISTERED PROFESSIONAL ENGINEER
 No. PE074722
 PENNSYLVANIA

PLACE NAME HERE

Bridge Inspection Report Tue 09/12/2023 Page 13 of 13

SOUTH CAROLINA



Critical Finding Report

Status: Addressed

Asset ID: 04148

NBI Structure No: 000000000004148

Structure Number: 2670026600100

Owner: State Highway Agency

Facility Carried: S-26-266

County: (26) Horry

District: District 5

Feature Intersected: HONEY COMB BRANCH

Critical Finding

Comment to FHWA

Comment: Bridge Closed due to washout

Status and Priority

Status: In Progress

Current Priority: Addressed

Critical Finding Data

Reporter: Elmore, Edward

Reporter Phone: 8436295152

Reporter Email: ElmoreE@scdot.org

Date of Finding: 09/07/2023

Time of Finding: 10:30:00 am

Discovered During Inspection Date: 09/07/2023 (SHMF)

Category: Other

Initial Priority: Addressed

Initial Action Taken: Close Br. w/ Insp. Trck

Bridge Owner Contact

Date/Time: 9/7/2023 11:27:00AM

Contacted Name: Harold Colman

Contacted Phone: 843-430-1738

Critical Finding Description

Bridge closed due to West roadway at transition undermining and collapsing.

Critical Finding Log (Actions Taken)

Action Date/Time	User	Action	Due Date	Comments
9/7/2023 5:50:13PM	Elmore, Edward	Saved New Critical Finding		
9/7/2023 6:05:24PM	Cox, Spencer	Completed Level 1 Review		Bridge Closed due to washout
9/7/2023 6:05:27PM	Cox, Spencer	Sent Auto-Generated Email		BRM sent auto-generated email to the following FHWA contacts: clayton.garcia@mayvue.com

Outstanding Tasks

All Critical Findings Photos

SOUTH CAROLINA



QC Most Common Flags Report

The most common items flagged during the QC review steps of inspections performed during the last quarter.

For inspections performed between 4/1/2023 and 6/30/2023.

Procedures		
Procedure Type	Procedure Name	Count

Bridge & Inspection Values		
Data Table	Field	Count

Roadway		
Data Table	Field	Count

Elements	
Element	Count

Multimedia	
Multimedia Agency Types	Count

Cross Sections
 There were 0 items flagged on cross sections.

Schedule	
Inspection Type	Count

Equipment	
Equipment Name	Count





NEBRASKA

Good Life. Great Journey.

DEPARTMENT OF TRANSPORTATION

Inspection > NDOT Load Rating

Inventory Type (065): 1 LF Load Factor

Bridge Posting (070): 0 >39.9% below

Truck	Inventory Rating		Operating Rating		Legal		Posting Value (Tons)	Member	Control Location			Limit State
	Rating Factor	Tons	Rating Factor	Tons	Rating Factor	Tons			Span	Location (ft)	Percent of Span	
HS/HL93	0.29	10					N/A	G2	1	12.40	40.00	Design Flexure - Steel
HS/HL93			0.49	17			N/A	G2	1	12.40	40.00	Design Flexure - Steel
SU4					0.51	13	-	G2	1	15.50	50.00	Design Flexure - Steel
SU5					0.47	14	-	G2	1	15.50	50.00	Design Flexure - Steel
SU6					0.43	14	-	G2	1	15.50	50.00	Design Flexure - Steel
SU7					0.41	16	-	G2	1	15.50	50.00	Design Flexure - Steel
NE Type 3					0.62	15	13	G2	1	12.40	40.00	Design Flexure - Steel
NE Type 3S2					0.61	22	22	G2	1	15.50	50.00	Design Flexure - Steel
NE Type 3-3					0.76	32	32	G2	1	12.40	40.00	Design Flexure - Steel
EV2					0.51	14	8 - Axle	G2	1	12.40	40.00	Design Flexure - Steel
EV3					0.34	14	10 - Axle	G2	1	15.50	50.00	Design Flexure - Steel
Triple-Triple			0.39	26	Fatigue Load Truck		N/A	G2	1	15.50	50.00	Design Flexure - Steel

- 11/2/2022 MOTD & BIP
- BRIDGES
- INSPECTION
- CONDITION
- BRIDGE/WATERWAY APPRAISAL
- INVENTORY
- NDOT LOAD RATING**
- INSP SCHEDULE
- WORK
- NDOT MULTIMEDIA
- NOTES SUMMARY
- CRITICAL FINDINGS
- ASSESSMENTS
- ANALYSIS
- PROJECTS
- PROGRAMS
- REPORTS

Weight Limit Posting Requirements



A rectangular sign with a white background and black text. It reads "WEIGHT LIMIT" at the top, followed by three truck icons and their corresponding limits: "13T", "22T", and "32T".

Documentation

Rating Information Provided: Plans Field Measurements
 Testing No Information Exists

BR Computations Submitted:

Analysis Engine Version: Legacy AASHTO LFR Engine Version 6.8.4.3002

Rating Program Used (381): 14 BrR

Additional Comments:
 This bridge is currently posted at 10 Tons. The revised bridge load rating is shown above, and is lower than the legal limits for Nebraska legal trucks; load posting is required.
 Recommended review posting notified to bridge owner on 12/29/20.

NE Professional Engineer Seal



A circular seal for a Professional Civil Engineer in the State of Nebraska. The outer ring contains the text "PROFESSIONAL CIVIL ENGINEER" and "STATE OF NEBRASKA". The center of the seal is blank.

NEBRASKA

Truck	Inventory Rating		Operating Rating		Legal		Posting Value (Tons)
	Rating Factor	Tons	Rating Factor	Tons	Rating Factor	Tons	
HS/HL93	0.29	10					N/A
HS/HL93							N/A
SU4					0.51	13	-
SU5					0.47	14	-
SU6					0.43	14	-
SU7					0.41	16	-
NE Type 3					0.62	15	13
NE Type 3S2					0.61	22	22
NE Type 3-3					0.76	32	32
EV2					0.51	14	8 - Axle
EV3					0.34	14	10 - Axle

Weight Limit Posting Requirements

WEIGHT LIMIT
 13T
 22T
 32T

SU4
 SU5
 SU6
 SU7
 NE Type 3
 NE Type 3S2
 NE Type 3-3

0.51 13
 0.47 14
 0.43 14
 0.41 16
 0.62 15
 0.61 22
 0.76 32
 0.51 14 8 - Axle
 0.34 14 10 - Axle

NEBRASKA

Load Rating Summary

Structure ID: C002250510 Analyst: DPage
 Location: HW 204 OF HUBBARD QC By:
 Analysis Date: Nov 10, 2023

Structure Identification

Feature Hierarchical: MINNOW CREEK County: Dakota
 Material Main Span: 3 Steel National Highway System Indicator: 0 Not on NHS
 Design for Main Span: 62 Stringer/Girder District: District 3
 Year Built: 1940 Administrative Area: 901 - Unknown
 Maintainer: County Hwy Agency Name: SERVINE
 Owner: County Hwy Agency Emergency Route: 0 Not on Emergency Rte

Description

Concrete Design: 00 Not rated

Retains and Loads

Deck (S): 5' Flat SuperStructure (S): 4 Four Substructure (S): 2 Critical Culvert (S): N/A (NBI)
 Design Load (S1): 8 Unknown Type of Overlay:
 Operating Type (S2): 1 LF Load Factor Overlay Thickness / FE Height (in):
 Inventory Type (S3): 1 LF Load Factor Bridge Posting (O70): 0 >39.9% below

Truck	Rating Factor	Tons	Rating Factor	Tons	Rating Factor	Tons	Posting Value (Tons)	Member	Span	Location (ft)	Percent of Span	Limit State
HSHL33	0.29	10					N/A	G2	1	12.40	40.00	Design Flexure - Steel
HSHL33			0.49	17			N/A	G2	1	12.40	40.00	Design Flexure - Steel
SU4			0.51	13			-	G2	1	15.50	50.00	Design Flexure - Steel
SU5			0.47	14			-	G2	1	15.50	50.00	Design Flexure - Steel
SU6			0.43	14			-	G2	1	15.50	50.00	Design Flexure - Steel
SU7			0.41	16			-	G2	1	15.50	50.00	Design Flexure - Steel
NE Type 3			0.82	18	13			G2	1	12.40	40.00	Design Flexure - Steel
NE Type 3B2			0.81	22	22			G2	1	15.50	50.00	Design Flexure - Steel
NE Type 3-3			0.76	32	32			G2	1	12.40	40.00	Design Flexure - Steel
EV2			0.51	14	N/A			G2	1	12.40	40.00	Design Flexure - Steel
EV3			0.34	14	N/A			G2	1	15.50	50.00	Design Flexure - Steel
Truck Type			0.28	26			N/A	G2	1	15.50	50.00	Design Flexure - Steel

Weight Limit Posting Requirements

Rating Information Provided: Plans Field Measurements
 Testing Other

Analysis Engine Version: Legacy AASHTO LFR Engine Version 6.6.4.3002
 Rating Program Used (R1): 14 BR

Additional Comments

This bridge is currently posted at 10 Tons. The revised bridge load rating is shown above, and is lower than the legal limits for Nebraska legal trucks - load posting is required.

Recommended review posting notified to bridge owner on 12/20/23.

Weight Limit Posting Requirements

WEIGHT LIMIT

13T

22T

32T

BR Form 685, version 1.0 [Updated 6/17/2021] Generated By: Kent Miller (A20196) Print Time: 9/10/2023 1:25:49PM



AASHTO Ware™
BRIDGE
MANAGEMENT





Idaho Transportation Department
 Bridge Inspection Report

Bridge Key:	10520	Structure Name:	09527D 0.18
(B) Features Intersected:	US 95R SBL LEWISTON IC	(9) Location:	AT LEWISTON NCL
Facility Carried/Route:	US 95 RAMP NBL	Admin Jurisdiction:	0002 District 2
Xref Structure Name:	09527D 312.14	District:	02

Elm/Env	Element Description	Total Qty	Units	State 1	State 2	State 3	State 4
16/4	Reinforced Concrete Top Flange	15846	sq.ft	15840	6	0	0
	Reinforced concrete top flange/deck had a deck crack sealer applied in 2012. New epoxy overlay. Top flange/deck surface is worn smooth in the wheel lines with large aggregates exposed. Transverse cracks in the deck at 1 foot to 3 foot spacing are present for approximately 50 feet on either side of the piers. There are a few areas of cracking with delamination towards the north end of the deck. 1-foot square area approximately 35 foot from the end of the deck, and a 5 foot square area, 5 feet long in the east wheel line near the north end of the deck. A couple small random areas of delamination. Hairline to 1/16-inch cracks and separations along a few construction joints.						
510/4	Wearing Surfaces	14706	sq.ft	14706	0	0	0
	<i>New epoxy overlay.</i>						
521/4	Concrete Protective Coating	14706	sq.ft	14706	0	0	0
	<i>New epoxy overlay.</i>						
1080/4	Delamination/Spall/Patched Area	6	sq.ft	0	6	0	0
	<i>Delaminated areas patched and covered with an epoxy overlay.</i>						
1130/4	Cracking (RC and Other)	650	sq.ft	650	0	0	0
	<i>All previously reported deck cracks have been sealed with an epoxy overlay.</i>						
105/4	Reinforced Concrete Closed Web/Box Girder	380	ft	165	200	15	0
	Reinforced concrete box girder with 5 bays inside. There are diagonal and vertical cracks with efflorescence, and several with rust stains, in the fascia sides of the girder in all spans. Diagonal are more concentrated towards abutments and piers, vertical are more concentrated towards midspan locations. Cracks are hairline to 1/32 inch wide and at random spacing. Cracks above pier 1 and pier 2 have efflorescence and light rust stains.						
1120/4	Efflorescence/Rust Staining	15	ft	0	0	15	0
	<i>There are diagonal and vertical cracks with efflorescence, and several with rust stains, in the fascia sides of the girder in all spans. Cracks above P1 and p2 have efflorescence and light rust stains.</i>						
1130/4	Cracking (RC and Other)	200	ft	0	200	0	0
	<i>There are diagonal and vertical cracks with efflorescence, and several with rust stains, in the fascia sides of the girder in all spans. Diagonal are more concentrated towards abutments and piers, vertical are more concentrated towards midspan locations. Cracks are hairline to 1/32 inch wide and at random spacing. Cracks above pier 1 and pier 2 have efflorescence and rust stains.</i>						
210/3	Reinforced Concrete Pier Wall	60	ft	48	12	0	0
	Both concrete pier walls are in good condition. Pier 1 has a small length of the footing exposed. Vertical crack 0.020-inches wide is present on the north face of pier 1 from the groundline up approximately 11-feet.						



Elim/Env	Element Description	Total Qty	Units	State 1	State 2	State 3	State 4
16/4	Reinforced Concrete Top Flange Reinforced concrete top flange/deck had a deck crack sealer applied in 2012. New epoxy overlay. Top flange/deck surface is worn smooth in the wheel lines with large aggregates exposed. Transverse cracks in the deck at 1 foot to 3 foot spacing are present for approximately 50 feet on either side of the piers. There are a few areas of cracking with delamination towards the north end of the deck. 1-foot square area approximately 35 foot from the end of the deck, and a 5 foot square area, 5 feet long in the east wheel line near the north end of the deck. A couple small random areas of delamination. Hairline to 1/16-inch cracks and separations along a few construction joints.	15846	sq.ft	15840	6	0	0
	510/4 Wearing Surfaces New epoxy overlay.	14706	sq.ft	14706	0	0	0
	521/4 Concrete Protective Coating New epoxy overlay.	14706	sq.ft	14706	0	0	0
	1080/4 Delamination/Spall/Patched Area Delaminated areas patched and covered with an epoxy overlay.	6	sq.ft	0	6	0	0
	1130/4 Cracking (RC and Other) All previously reported deck cracks have been sealed with an epoxy overlay.	650	sq.ft	650	0	0	0
105/4	Reinforced Concrete Closed Web/Box Girder Reinforced concrete box girder with 5 bays inside. There are diagonal and vertical cracks with efflorescence, and several with rust stains, in the fascia sides of the girder in all spans. Diagonal are more concentrated towards abutments and piers, vertical are more concentrated towards midspan locations. Cracks are hairline to 1/32 inch wide and at random spacing. Cracks above pier 1 and pier 2 have efflorescence and light rust stains.	380	ft	165	200	15	0
	1120/4 Efflorescence/Rust Staining There are diagonal and vertical cracks with efflorescence, and several with rust stains, in the fascia sides of the girder in all spans. Cracks above P1 and p2 have efflorescence and light rust stains.	15	ft	0	0	15	0
	1130/4 Cracking (RC and Other) There are diagonal and vertical cracks with efflorescence, and several with rust stains, in the fascia sides of the girder in all spans. Diagonal are more concentrated towards abutments and piers, vertical are more concentrated towards midspan locations. Cracks are hairline to 1/32 inch wide and at random spacing. Cracks above pier 1 and pier 2 have efflorescence and rust stains.	200	ft	0	200	0	0
210/3	Reinforced Concrete Pier Wall Both concrete pier walls are in good condition. Pier 1 has a small length of the footing exposed. Vertical crack 0.020-inches wide is present on the north face of pier 1 from the groundline up approximately 11-feet.	60	ft	48	12	0	0

LOAD RATING		CONDITION	
(31)Design Load:	5 MS 18 (HS 20)	(58)Deck:	6 Satisfactory
(64)Operating Rating:	78 tons / HS43.3	(59)Substructure:	5 Fair
(66)Inventory Rating:	57 tons / HS31.7	(60)Superstructure:	6 Satisfactory
(70)Posting:	5 Ax/Above Legal Loads	(61)Channel/Protection:	N NA (NB)
(41)Posting Status:	A Open, no restriction	(62)Culvert:	N NA (NB)
AGE AND SERVICE		APPRAISAL	
(27)Year Built:	1977	(67)Structure Condition:	5 Above Min Tolerable
(106)Year Reconstructed:		(68)Deck Geometry:	9 Above Desirable Crt
(42a)Type of Service On:	7 3d level interchg	(69)Undrdrsr/Vert and Horiz:	4 Tolerable
(42b)Type of Service Under:	1 Highway	(71)Waterway Adequacy:	N Not applicable
(28a)Lanes On: 2	(28b)Lanes Under: 3	(72)Approach Alignment:	8 Equal Desirable Crt
(29)ADT:	4300	(38)Traffic Safety Features:	
(30)Year of ADT:	2022	(a)Bridge Rail:	1 Meets Standards
(109)Truck ADT:	0%	(b)Transition:	1 Meets Standards
(19)Detour Length:	0 miles	(c)Approach Rail:	1 Meets Standards
Speed Limit:	45 MPH	(d)Approach Rail End:	1 Meets Standards
		(113)Scour Critical:	N Not Over Waterway
PROPOSED IMPROVEMENTS		NAVIGATION DATA	
(75a)Type of Work:		(38)Navigation Control:	NA-no waterway
(75b)Work Done By:		(39)Vertical Clearance:	
(76)Length of Improvement:		(40)Horizontal Clearance:	
(94)Bridge Improvement Cost:		(111)Pier Protection:	
(95)Ramp Improvement Cost:		(116)Lit Bridge Vert Ctr:	
(96)Total Project Cost:		ENVIRONMENTAL	
(97)Year of Cost Estimate:		Environmental Concerns:	No
(114)Future ADT:	6450		
(115)Year of Future ADT:	2042		
YEAR PROGRAMMED:			
INSPECTION			
(80)Inspection Date:	2/8/22	(91)Inspection Frequency:	24 months
(92)Supplemental Inspections Frequency:		(83)Date of Inspections:	
(a)Fracture Critical Detail:	NA	(a)FC Inspection Date:	
(b)Underwater Inspection:	NA	(b)UW Inspection Date:	
(c)Fatigue Detail (OS) Inspection:	NA	(c)Fatigue Detail (OS) Date:	
(d)In-Depth Inspection:	NA	(d)In-Depth Date:	
(e)Confined Space Inspection:	72 months	(e)Confined Space Date:	
Channel Cross Section Year:			
Equipment Needed:	UBIT		

Elm/Env	Element Description	Total Qty	Units	State 1	State 2	State 3	State 4
16/4	Reinforced Concrete Top Flange	15846	sq.ft	15840	6	0	0
	Reinforced concrete top flange/deck had a deck crack sealer applied in 2012. New epoxy overlay. Top flange/deck surface is worn smooth in the wheel lines with large aggregates exposed. Transverse cracks in the deck at 1 foot to 3 foot spacing are present for approximately 50 feet on either side of the piers. There are a few areas of cracking with delamination towards the north end of the deck. 1-foot square area approximately 35 foot from the end of the deck, and a 5 foot square area, 5 feet long in the east wheel line near the north end of the deck. A couple small random areas of delamination. Hairline to 1/16-inch cracks and separations along a few construction joints.						
510/4	Wearing Surfaces <i>New epoxy overlay.</i>	14706	sq.ft	14706	0	0	0
521/4	Concrete Protective Coating <i>New epoxy overlay.</i>	14706	sq.ft	14706	0	0	0
1080/4	Delamination/Spall/Patched Area <i>Delaminated areas patched and covered with an epoxy overlay.</i>	6	sq.ft	0	6	0	0
1130/4	Cracking (RC and Other) <i>All previously reported deck cracks have been sealed with an epoxy overlay.</i>	650	sq.ft	650	0	0	0
105/4	Reinforced Concrete Closed Web/Box Girder	380	ft	165	200	15	0
	Reinforced concrete box girder with 5 bays inside. There are diagonal and vertical cracks with efflorescence, and several with rust stains, in the fascia sides of the girder in all spans. Diagonal are more concentrated towards abutments and piers, vertical are more concentrated towards midspan locations. Cracks are hairline to 1/32 inch wide and at random spacing. Cracks above pier 1 and pier 2 have efflorescence and light rust stains.						
1120/4	Efflorescence/Rust Staining <i>There are diagonal and vertical cracks with efflorescence, and several with rust stains, in the fascia sides of the girder in all spans. Cracks above P1 and p2 have efflorescence and light rust stains.</i>	15	ft	0	0	15	0
1130/4	Cracking (RC and Other) <i>There are diagonal and vertical cracks with efflorescence, and several with rust stains, in the fascia sides of the girder in all spans. Diagonal are more concentrated towards abutments and piers, vertical are more concentrated towards midspan locations. Cracks are hairline to 1/32 inch wide and at random spacing. Cracks above pier 1 and pier 2 have efflorescence and rust stains.</i>	200	ft	0	200	0	0
210/3	Reinforced Concrete Pier Wall	60	ft	48	12	0	0
	Both concrete pier walls are in good condition. Pier 1 has a small length of the footing exposed. Vertical crack 0.020-inches wide is present on the north face of pier 1 from the groundline up approximately 11-feet.						

Department Inspection Report

Structure Name: 09527D 0.18
 Location: AT LEWISTON NCL
 Min Jurisdiction: 0002 District 2
 District: 02

CONDITION

Deck: 6 Satisfactory
 Superstructure: 5 Fair
 Substructure: 6 Satisfactory
 Channel/Protection: N NA (NB)
 Culvert: N NA (NB)

APPRAISAL

Structure Condition: 5 Above Min Tolerable
 Deck Geometry: 9 Above Desirable Crt
 Undercar/Vent and Horiz: 4 Tolerable
 Waterway Adequacy: N Not applicable
 Approach Alignment: 8 Equal Desirable Crt
 Traffic Safety Features:
 (a) Bridge Rail: 1 Meets Standards
 (b) Transition: 1 Meets Standards
 (c) Approach Rail: 1 Meets Standards
 (d) Approach Rail Ends: 1 Meets Standards
 (e) Scour Critical: N Not Over Waterway

NAVIGATION DATA

Navigation Control: NA-no waterway
 Vertical Clearance:
 Horizontal Clearance:
 Pier Protection:
 LUL Bridge Vert Ctr:

ENVIRONMENTAL

Environmental Concerns: No

Inspection Date: 24 months
 Date of Inspections:
 (a) FC Inspection Date:
 (b) UW Inspection Date:
 (c) Fatigue Detail (OS) Date:
 (d) In-Depth Date:
 (e) Confined Space Date:

Elm/Env	Element Description	Total Qty	Units	State 1	State 2	State 3	State 4
16/4	Reinforced Concrete Top Flange	15846	sq.ft	15840	6	0	0
	Reinforced concrete top flange/deck had a deck crack sealer applied in 2012. New epoxy overlay. Top flange/deck surface is worn smooth in the wheel lines with large aggregates exposed. Transverse cracks in the deck at 1 foot to 3 foot spacing are present for approximately 50 feet on either side of the piers. There are a few areas of cracking with delamination towards the north end of the deck. 1-foot square area approximately 35 foot from the end of the deck, and a 5 foot square area, 5 feet long in the east wheel line near the north end of the deck. A couple small random areas of delamination. Hairline to 1/16-inch cracks and separations along a few construction joints.						
510/4	Wearing Surfaces <i>New epoxy overlay.</i>	14706	sq.ft	14706	0	0	0
521/4	Concrete Protective Coating <i>New epoxy overlay.</i>	14706	sq.ft	14706	0	0	0
1080/4	Delamination/Spall/Patched Area <i>Delaminated areas patched and covered with an epoxy overlay.</i>	6	sq.ft	0	6	0	0
1130/4	Cracking (RC and Other) <i>All previously reported deck cracks have been sealed with an epoxy overlay.</i>	650	sq.ft	650	0	0	0
105/4	Reinforced Concrete Closed Web/Box Girder	380	ft	165	200	15	0
	Reinforced concrete box girder with 5 bays inside. There are diagonal and vertical cracks with efflorescence, and several with rust stains, in the fascia sides of the girder in all spans. Diagonal are more concentrated towards abutments and piers, vertical are more concentrated towards midspan locations. Cracks are hairline to 1/32 inch wide and at random spacing. Cracks above pier 1 and pier 2 have efflorescence and light rust stains.						
1120/4	Efflorescence/Rust Staining <i>There are diagonal and vertical cracks with efflorescence, and several with rust stains, in the fascia sides of the girder in all spans. Cracks above P1 and p2 have efflorescence and light rust stains.</i>	15	ft	0	0	15	0
1130/4	Cracking (RC and Other) <i>There are diagonal and vertical cracks with efflorescence, and several with rust stains, in the fascia sides of the girder in all spans. Diagonal are more concentrated towards abutments and piers, vertical are more concentrated towards midspan locations. Cracks are hairline to 1/32 inch wide and at random spacing. Cracks above pier 1 and pier 2 have efflorescence and rust stains.</i>	200	ft	0	200	0	0
210/3	Reinforced Concrete Pier Wall	60	ft	48	12	0	0
	Both concrete pier walls are in good condition. Pier 1 has a small length of the footing exposed. Vertical crack 0.020-inches wide is present on the north face of pier 1 from the groundline up approximately 11-feet.						

Department Inspection Report

Structure Name: 09527D 0.18
 Location: AT LEWISTON NCL
 Min Jurisdiction: 0002 District 2
 District: 02

WEARING SURFACE and DEAD LOAD INFORMATION

Asphalt: 0.0 inches Concrete: 0.5 inches
 Granular: 0.0 inches Timber: 0.0 inches

POSTING INFORMATION

WEIGHT

Load Analysis Date: 01/16/2018 Bridge Factor: 159.1
 Load Analysis Required: N Analysis Complete Route Color: Interstate

Load Rating Analysis	Recommended Posting (tons)	Actual Posting (tons)
H Truck		
HS Truck		
Type 3	108	Type 3
Type 3S2	127	Type 3S2
Type 3-3	127	Type 3-3
		Axle Limit

HEIGHT

Recommended	Actual


Height Posting:




ACTUAL WIDTH POSTING


Single Lane All Vehicles: N
 Single Lane Trucks/Buses: N



Under Record Information:


(5) Inventory Route:	A27000950	B21000120
(7) Facility Under Structure:	US 95 RAMP SBL	US 12 WBL
(10) Min Vert Ctr:	18.50	17.43
(47) Inv Route Total Htz Ctr:	25.20	48.00
(11) Milepoint:	312.219	003.131
(20) Toll:	3 On free road	3 On free road
(26) Functional Classification:	14 Urban Other Princ	14 Urban Other Princ
(29) ADT:	4300	7000
(30) ADT Year:	2022	2022
(109) Truck ADT:		9%
(100) Def Hwy Designation:	0 Not a STRAHNET hwy	0 Not a STRAHNET hwy
(102) Traffic Direction:	1 1-way traffic	1 1-way traffic
(104) Highway System:	1 On the NHS	1 On the NHS
(110) Design National Network:	1 Part of natl network	0 Not part of natl network

 Idaho Transportation Department Bridge Inspection Report							
Bridge Key: 10520 (B)Features Intersected: US 95R SBLLEWISTON IC Facility Carried(Route): US 95 RAMP NBL Xref Structure Name: 09527D 312.14		Structure Name: 09527D 0.18 (S)Location: AT LEWISTON NCL Admin Jurisdiction: 0002 District 2 District: 02					
Elm/Env	Element Description	Total Qty	Units	State 1	State 2	State 3	State 4
16/4	Reinforced Concrete Top Flange	15846	sq.ft	15840	6	0	0
	Reinforced concrete top flange/deck had a deck crack sealer applied in 2012. New epoxy overlay. Top flange/deck surface is worn smooth in the wheel lines with large aggregates exposed. Transverse cracks in the deck at 1 foot to 3 foot spacing are present for approximately 50 feet on either side of the piers. There are a few areas of cracking with delamination towards the north end of the deck. 1-foot square area approximately 35 feet from the end of the deck, and a 5 foot square area, 5 feet long in the east wheel line near the north end of the deck. A couple small random areas of delamination. Hairline to 1/16-inch cracks and separations along a few construction joints.						
510/4	Wearing Surfaces <i>New epoxy overlay.</i>	14706	sq.ft	14706	0	0	0
521/4	Concrete Protective Coating <i>New epoxy overlay.</i>	14706	sq.ft	14706	0	0	0
1080/4	Delamination/Spall/Patched Area <i>Delaminated areas patched and covered with an epoxy overlay.</i>	6	sq.ft	0	6	0	0
1130/4	Cracking (RC and Other) <i>All previously reported deck cracks have been sealed with an epoxy overlay.</i>	650	sq.ft	650	0	0	0
105/4	Reinforced Concrete Closed Web/Box Girder	380	ft	165	200	15	0
	Reinforced concrete box girder with 5 bays inside. There are diagonal and vertical cracks with efflorescence, and several with rust stains, in the facia sides of the girder in all spans. Diagonal are more concentrated towards abutments and piers, vertical are more concentrated towards midspan locations. Cracks are hairline to 1/32 inch wide and at random spacing. Cracks above pier 1 and pier 2 have efflorescence and light rust stains.						
1120/4	Efflorescence/Rust Staining <i>There are diagonal and vertical cracks with efflorescence, and several with rust stains, in the facia sides of the girder in all spans. Cracks above P1 and p2 have efflorescence and light rust stains.</i>	15	ft	0	0	15	0
1130/4	Cracking (RC and Other) <i>There are diagonal and vertical cracks with efflorescence, and several with rust stains, in the facia sides of the girder in all spans. Diagonal are more concentrated towards abutments and piers, vertical are more concentrated towards midspan locations. Cracks are hairline to 1/32 inch wide and at random spacing. Cracks above pier 1 and pier 2 have efflorescence and rust stains.</i>	200	ft	0	200	0	0
210/3	Reinforced Concrete Pier Wall	60	ft	48	12	0	0
	Both concrete pier walls are in good condition. Pier 1 has a small length of the footing exposed. Vertical crack 0.020-inches wide is present on the north face of pier 1 from the groundline up approximately 11-feet.						


 Idaho Transportation Department Bridge Inspection Report							
Bridge Key: 10520 (B)Features Intersected: US 95R SBLLEWISTON IC Facility Carried(Route): US 95 RAMP NBL Xref Structure Name: 09527D 312.14		Structure Name: 09527D 0.18 (S)Location: AT LEWISTON NCL Admin Jurisdiction: 0002 District 2 District: 02					
 <p>Approach plus milepost</p>							
 <p>Right side</p>							







- UPSTREAM
 wing number 13679
 1 ft TO: 38 ft
 ELEVATION SCALE 10 ft:1 in



INSPECTED BY: JLH	BRIDGE KEY: 20345
DRAWN BY: JEC	DATE: JUL 2023
CHECKED BY: JLH	SHEET NO: 01



Idaho Transportation Department
 Bridge Inspection Report

Bridge Key:	20345	Structure Name:	95705A 13.09
(6) Features Intersected:	BENEWAH CREEK	(9) Location:	2.6 N. 2.3 E. BENEWAH
Facility Carried(Route):	STC5705;BENEWAH CR	Admin Jurisdiction:	0900 Benewah County
Xref Structure Name:		District:	01



Upstream looking southwest.



Downstream looking northeast.


IDAHO TRANSPORTATION DEPARTMENT
TUNNEL INSPECTION REPORT

Tunnel Number: 00000000T0030 Tunnel Name: CM&PS Tunnel 30; Deer Creek #2


Element Number	NOTES	Total	CS1	CS2	CS3	CS4
10001 - Cast-in-Place Conc Tunnel Liner	10001 CIP Concrete Tunnel Liner ELEMENT INSPECTION PROCEDURES: Inspect the liner utilizing visual and sounding techniques. Focus on cracks, spalls, areas of delamination, and areas of leakage/escape as shown on the Tunnel Plan. Check for separation, displacement, and misalignment of liner wall as that may be signs of shifting material behind the concrete liner. Construction joints are susceptible to delamination and spalling – check these areas for loose concrete. Use caution when sounding overhead as loose concrete may fall. Sketch all liner defects on the Tunnel Plan and describe in the element section and notes of the inspection report.	12,215	0	4,180	3,315	15
7/2023 INSPECTION:	Cast in place concrete tunnel liner has efflorescence typical throughout with some rust stains. Tunnel has spalling typical in the crown at the construction joints with some exposed rebar and other random spalls. The tunnel also has several areas of greater concern; large vertical cracks and bulging of the walls. See defects below and attached drawing that marks the defect locations.					
82100 - Delamination / Spall / Patch	(CS2 / CS3): Several locations of spalls and areas of delamination throughout the tunnel walls and crown. Typical spalling/deterioration of concrete in the tunnel crown at the construction joints. See attached drawing that marks the defect locations. Largest spall is in the tunnel crown around station 0+78. Spall is up to 8" deep.	1,200	0	1,000	200	0
82101 - Exposed Rebar	(CS3): The typical spalling/deterioration of concrete in the tunnel crown at the construction joints have exposed rebar in some locations. Rebar has minor to moderate corrosion.	10	0	0	10	0
82102 - Efflorescence / Staining	(CS2 / CS3): Cracks with efflorescence and rust stains typical throughout the entire length of the tunnel in both the walls and crown. Heavy buildup and stalactites of efflorescence are typical throughout the crown of the tunnel.	6,000	0	3,000	3,000	0
82103 - Cracking (Concrete Liner)	(CS3): Station 0+70: Bulging in the north wall that is offset 5/16". (CS3): Station 0+84: Bulging in the south wall that is offset 5/16". (CS3): Station 0+89 (at construction joint): Bulging in the south wall that is offset 3/16". (CS3): Station 0+89 (at construction joint): Bulging in the north wall that is offset 5/16". (CS3): Station 0+93: Bulging in the south wall that is offset 7/16". (CS4): Station 1+00: Bulging in the south wall that is offset 1". (CS3): Station 1+37 (at construction joint): Bulging in the north wall that is offset 5/8". (CS3): Around station 2+10: Bulging in the north wall that is offset 3/8".	300	0	180	105	15
	See attached drawing that marks the defect locations.					
	Several other minor to moderate width cracks throughout the tunnel walls and crown.					
10051 - Concrete Portal	10051 Concrete Portal ELEMENT INSPECTION PROCEDURES: Inspect the concrete portals and wingwalls utilizing visual and sounding techniques. Carefully examine the slopes above the portal and wingwalls assessing stability of the rock and any hazardous debris (e.g. fallen trees). Document changes in rock fall above and at the base of portal and wings. Describe in the element section of the inspection report. Contact geotechnical engineer if significant changes have been found in slopes since the last inspection.	3,427	0	1,450	1,050	5
7/2023 INSPECTION:	Reinforced concrete portals at both ends of the tunnel. Both portals have efflorescence with some rust stains mostly in east portal. Both portals have heavy spalling with large loose aggregate exposed along the portal arch, heavier at west portal.					
82100 - Delamination / Spall / Patch	(CS2 / CS3): Both portals have heavy spalling with large loose aggregate exposed along the portal arch. Heavier deterioration at west portal. Same deterioration along tops of portal wings.	1,500	0	750	750	0
82102 - Efflorescence / Staining	(CS2 / CS3): Cracks with efflorescence and some rust stains present in both portals but mostly in east portal.	1,000	0	700	300	0

IDAHO TRANSPORTATION DEPARTMENT
TUNNEL INSPECTION REPORT

Tunnel Number: 00000000T0030 Tunnel Name: CM&PS Tunnel 30; Deer Creek #2



1. "Slow" caution sign on east approach



2. East portal



Idaho Transportation Department
 Overhead Structure Inspection Report

S4001240

Route: I 84B Location: I 84B & 21st St

Location Data

District: District 4
 County: Minidoka
 Location: I 84B & 21st St
 NBI Bridge ID (if applicable):

Route: I 84B
 Latitude: 42.5616 °N
 Longitude: 113.74628 °W
 Foreman Area: 430

Inspection Data

Inspection Date: 5/16/2023
 Insp Freq: 12
 Inspector 1: Rick Smith
 Inspector 2:
 Traffic Control: None required.

Overall Condition: 3 Serious
 Equipment Req.: Bucket Truck

Roadway Data

Route:
 Traffic Direction: NB
 # Lanes Over Traffic: 3
 ADT Total: 16500
 Truck ADT: 6%
 ADT Year: 2019

ITD Roadway Data

Route ID: 02290A/N084
 Measure: 5.705325689
 Segment Code: 002040
 Under Milepost: 260.89

Clearance

Min Vert Clr: 20.40 ft
 Min Lateral UnderClr Right: 6.0 ft
 Min Lateral UnderClr Left:

Structure Data

Ancillary Type: Traffic Signal
 Material Type: Steel
 Design Type: Single Mast Arm
 Coating: Galvanized

Span/Arm 1 Length: 50.00 ft
 Span/Arm 2 Length:
 Foundation Type: Reinforced Concrete
 No. of Spans: 1
 Year Built:

Element Condition

Steel, Single Mast Arm, Galvanized

Element/Description	Total	Quantity			
		State 1	State 2	State 3	State 4
701-Concrete Foundation	1.00 each	1.00	0.00	0.00	0.00
Reinforced concrete foundation.					
702-Steel Anchor Rods	4.00 each	4.00	0.00	0.00	0.00
Steel anchor rods.					
704-Steel Base Plate	1.00 each	1.00	0.00	0.00	0.00
Steel base plate.					
706-Steel End Support Column	38.00 ft	38.00	0.00	0.00	0.00
Steel end support column.					
716-Con for Steel End or Column	1.00 each	1.00	0.00	0.00	0.00
Steel end support column bolted joint connection.					
718-End Support-to-Chord Connection	2.00 each	1.00	0.00	0.00	1.00
Steel end support column to chord connection and steel end support column to luminaire connection.					



Idaho Transportation Department
 Overhead Structure Inspection Report

S4001240

Route: I 84B Location: I 84B & 21st St

Inspection Photos



Overhead looking north.



Base looking north.

AASHTO Ware™
 **BRIDGE**
MANAGEMENT



OKLAHOMA
Transportation

OKLAHOMA

Total SD With Square Footage
 Turnpike, R.R., Corps not included

On

ADAIR	Total Bridges	Total Bridges SQFT	SD Count	Total SD SQFT
Culvert	29	51,740.28	0	
Stringer/Girder	13	180,430.61	0	
	<u>42</u>	<u>232,170.89</u>	<u>0</u>	

ALFALFA	Total Bridges	Total Bridges SQFT	SD Count	Total SD SQFT
Culvert	34	65,679.24	0	
Slab	1	4,037.48	0	
Stringer/Girder	35	326,268.39	0	
	<u>70</u>	<u>395,985.12</u>	<u>0</u>	

ATOKA	Total Bridges	Total Bridges SQFT	SD Count	Total SD SQFT
Culvert	26	69,425.16	0	
Slab	4	10,021.78	0	
Stringer/Girder	48	455,178.34	0	
	<u>78</u>	<u>534,625.28</u>	<u>0</u>	

BEAVER	Total Bridges	Total Bridges SQFT	SD Count	Total SD SQFT
Culvert	38	88,844.76	0	
Stringer/Girder	12	235,303.03	0	
	<u>50</u>	<u>324,147.79</u>	<u>0</u>	

BECKHAM	Total Bridges	Total Bridges SQFT	SD Count	Total SD SQFT
Culvert	45	173,071.61	0	
Slab	8	36,039.63	0	
Stringer/Girder	71	781,989.09	0	
Truss-Thru	2	21,949.58	0	
	<u>126</u>	<u>1,013,049.90</u>	<u>0</u>	

TULSA

	Total Bridges	Total Bridges SQFT	SD Count	Total SD SQFT
Culvert	87	794,925.18	1	4,639.04
Frame	3	23,885.12	0	
Girder-Floorbeam	16	242,111.67	0	
Multiple Box Beam	11	207,635.54	0	
Other (NBI)	1	2,421.88	0	
Single/Spread Box	4	7,997.59	0	
Slab	21	138,995.80	0	
Stringer/Girder	355	6,021,458.57	3	50,526.71
	<u>498</u>	<u>7,439,431.33</u>	<u>4</u>	<u>55,165.75</u>

OKLAHOMA DEPT. OF TRANSPORTATION
 PLAN OF ACTION FOR SCOUR CRITICAL BRIDGES

Division :	04		County :	KINGFISHER		Bridge No.:	15410000000000	
Item # 113 :	Current Condition	Previous Condition	ADT :	52	ADT Year :	2020		
Bridge Structure #	37E060N2970009		Year Built :	1902	Bus Route :	Not Desired/Current ne.		
Bridge Location :	E0690	over :	CREEK		Location :	3.5S 11.4E OF HENNESSEY		
Bridge Desc.:	2-10ft. X 10ft. X 30ft. PCB							
Structure Notes								
Inspection Notes	6/7/2023 6/3/2021 - Good shale roadway - Low chance of overtopping - Satisfactory ditches - North apron needs protection - structure placed on 12 month frequency due to scour - FX - Needs scour fixed on north with grouted rip rap. FX - Trees need cut back and all BEMs put up.							
Foundation Type	Abutment Type and Foundation:	205a: Other 205b: Bears on Natural Found.	Type of Pier and Foundation:	209a: - 209b: -	209c: -	Foundation Soils Type:	-1	
Replacement Plans :	JP Number :	Project No.:		Let Date :		/		
	Project Type :							

Bridge Condition :	Substructure	Current Condition	Previous Condition	Comments :
	Culvert	N/A (NFI)		
	Channel	3 Excessive Damage		
	Waterway	4 Protection Undermined		
		8 Equal Desirable		

Sources of Scour
 Critical Rating : 6/7/2023 - Barrels Clear 23ft
 6/3/2021 - Barrels clear
 6/3/2013 - Barrels clear - 12ft. 6/19/2014 - Barrels clear 13ft. 6/9/2015 - Barrels clear

Scour Smart Flag : 961 Condition State (CS1/CS2/CS3) : 0.00 / 100.00 / 0.00

Scour Comments : 6/7/2023 - No repairs made yet
 6/3/2021 - Hard red shale eroding very slowly. Apron extends 10 feet out from box opening. Scour now on north side is 26in. below floor level and still 6in. of undermining. Now flow is 1 ft below floor level on south side up stream no undermining noted on south side.

Inspection and Monitoring	Inspection Date :	06/07/2023	Inspection Frequency:	24 Months
Inspector	Stephen Reese	Contact No.:	Company :	

Criteria For Bridge Closure (Circle all that apply)	Roadway Overtopped	Roadway Fill Failed	Bridge Failed	Settlement
	Approach Fill Washed Out	Other (Explain)		

Detour Route : SEE FILE

Bridge Contact Info	Bridge Owner	Name :	County Bridge Coordinator	Name :
	Maintenance Responsibility	Contact Number:	County Commissioner	Contact Number:

Countermeasures Recommended :

Date Implemented : _____

Author(s) of POA	Bridge Inspector	Signature	Date
Reviewed with Bridge Owner	Bridge Owner	Signature	Date
Reviewed with Co. Bridge Coordinator	County Bridge Coordinator	Signature	Date

Sources of Scour	6/7/2023 - Barrels Clear 23ft
Critical Rating :	6/3/2021 - Barrels clear 6/20/2013 - Barrels clear * 12ft. 6/19/2014 - Barrels clear 13ft. 6/9/2015 - Barrels clear
Scour Smart Flag :	961 Condition State (CS1/CS2/CS3) : 0.00 / 100.00 / 0.00
Scour Comments :	6/7/2023 - No repairs made yet 6/3/2021 - Hard red shale eroding very slowly. Apron extends 10 feet out from box opening. Scour now on north side is 26in. below floor level and still 6in. of undermining. Now flow is 1 ft below floor level on south side up stream no undermining noted on south side.


Inspection and Monitoring	Inspection Date :	06/07/2023	Inspection Frequency:	24 Months
Inspector	Stephen Reese	Contact No.:	Company :	


Criteria For Bridge Closure (Circle all that apply)	Roadway Overtopped	Roadway Fill Failed	Bridge Failed	Settlement
	Approach Fill Washed Out	Other (Explain)		

Detour Route : SEE FILE

AASHTO Ware™
 **BRIDGE**
MANAGEMENT

LTDOT




 Keeping Utah Moving
Bridge Inspection Report Field Review Scorecard


Structure # _____ Date of Review _____
 Reviewers: _____ & _____ Date of Inspection _____

Bridge Inspection Field Review Checklist	Score: 1-5
NBI Rating Review • NBI ratings agree with the current condition of structure	Score _____
Report Photos • All inventory photos included in report • Any CS3 and CS4 defects have corresponding photos • Typical CS2 defects on the structure have photos • Consistent photo naming • Photo quality (in-focus and correct exposure)	Score _____
Parent and Defect Notes • Parent notes follow current guidelines and format o General notes include inspection type, local contact, inspection team ect. o Roadway notes include comments about sign postings, performing cross sections ect. • Defect notes follow current guidelines and format • All parent elements are correct and remain applicable • Defect notes are complete with all appropriate information • Defects are appropriately coded and identified	Score _____
SI&A Information • SI&A items coded correctly and up to date	Score _____
Work Candidates • All work candidates has appropriate information • All appropriate work candidates included in report • Work candidate has been assigned to proper group	Score _____
Cross Section and Clearances • Cross section and/or clearance information updated or verified	Score _____

Ratings:
 5 - No Issues
 4 - Minors issues, isolated to grammar and/or formatting
 3 - Some missing or incorrect items
 2 - Most of the items are missing or incorrect
 1 - Completely missing or incorrect

Final Score _____

0F 466
Sevier River Bridge, east of Joseph
 Inspector: Teddy Moffett
 Inspection Date: May 09, 2023



 Keeping Utah Moving

Condition Overview						
Deck NBI: 6	Culvert NBI: N	BHI: 78.40	BHI Rank: 1096			
Super NBI: 7	Channel NBI: 6	PHI: 78.40	PHI Rank: 1096			
Sub NBI: 6	Scour NBI: 7	FHWA Poor: No	Year Built / Recor: 1981 /			

Bridge Issues		Yes	No
This report identifies deficiencies requiring urgent corrective action.		<input type="checkbox"/>	<input checked="" type="checkbox"/>
Details:			
This bridge is scour critical:		<input type="checkbox"/>	<input checked="" type="checkbox"/>
This bridge contains fracture critical components:		<input type="checkbox"/>	<input checked="" type="checkbox"/>
This bridge needs a new load rating:		<input type="checkbox"/>	<input checked="" type="checkbox"/>
This bridge requires special inspection:		<input type="checkbox"/>	<input checked="" type="checkbox"/>
Recommended Frequency:			

Report Contents	
<input type="checkbox"/> Desk Review Audit	<input type="checkbox"/> Critical Findings Report
<input checked="" type="checkbox"/> Condition Ratings Report	<input type="checkbox"/> Vertical Underclearance Report
<input checked="" type="checkbox"/> Element Level Inspection Report	<input checked="" type="checkbox"/> Cross Section Report
<input checked="" type="checkbox"/> Bridge Photographs	<input type="checkbox"/> Other:

Type of Inspection					
NBI	Element	Fracture Critical	Underwater	Complex	Other Special
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>

Inspectors	Name	Date	P.E. Seal and Signature
Inspector of Record	Teddy Moffett	05/09/2023	
Field Checked	Brandon Reda	05/09/2023	
Checked	Jordan Monroe	08/18/2023	
Corrected	Teddy Moffett	08/18/2023	
Verified	Jordan Monroe	08/18/2023	
Independent Field QC Review			
QA Review			

UDOT Inspection Report (v3.1) Wed 08/23/2023 15:44:42
Page 1 of 31



Bridge Inspection Report Field Review Scorecard

Structure # _____ Date of Review _____

Inspectors: _____ & _____ Date of Inspection _____

Inspection Field Review Checklist	Score: 1-5
Rating Review All ratings agree with the current condition of structure	Score _____
Photos Inventory photos included in report Typical CS3 and CS4 defects have corresponding photos Typical CS2 defects on the structure have photos Consistent photo naming Photo quality (in-focus and correct exposure)	Score _____
Notes and Defect Notes Parent notes follow current guidelines and format <ul style="list-style-type: none"> General notes include inspection type, local contact, inspection team ect. Roadway notes include comments about sign postings, performing cross sections ect. Defect notes follow current guidelines and format All parent elements are correct and remain applicable Defect notes are complete with all appropriate information Defects are appropriately coded and identified	Score _____
Formulation SI&A items coded correctly and up to date	Score _____
Work Candidates All work candidates has appropriate information All appropriate work candidates included in report Work candidate has been assigned to proper group	Score _____
Section and Clearances Cross section and/or clearance information updated or verified	Score _____

Issues:
 None
 None missing or incorrect items
 None of the items are missing or incorrect
 None completely missing or incorrect

Final Score _____

0F 466
 Sevier River Bridge, east of Joseph
 Inspector: Teddy Moffett
 Inspection Date: May 09, 2023


1096
1096
1981 /
No.
<input checked="" type="checkbox"/>
<input checked="" type="checkbox"/>
<input checked="" type="checkbox"/>
<input checked="" type="checkbox"/>
<input checked="" type="checkbox"/>

Other
 Special

Inspector Signature



0F 466
 Sevier River Bridge, east of Joseph
 Inspector: Teddy Moffett
 Inspection Date: May 09, 2023



Roadway Looking East



Elevation Looking North



0F 466
 Sevier River Bridge, east of Joseph
 Inspector: Teddy Moffett
 Inspection Date: May 09, 2023



Roadside Longitudinal Cracking 0.013 IN



Deck Underside Diagonal Cracking with Efflorescence



Roadside Abrasion in Wheel Paths



Rating 2 Spall West End



Rating 1 Delamination West End



Concrete Railing Vertical Cracking

Date of Review _____
 & _____
 Date of Inspection _____

Inspection Field Review Checklist	Score: 1-5
Agree with the current condition of structure	Score _____
photos included in report CS4 defects have corresponding photos defects on the structure have photos photo naming (in-focus and correct exposure)	Score _____
Notes Notes follow current guidelines and format General notes include inspection type, local contact, inspection team ect. roadway notes include comments about sign postings, performing cross sections ect. Notes follow current guidelines and format Elements are correct and remain applicable Notes are complete with all appropriate information are appropriately coded and identified	Score _____
is coded correctly and up to date	Score _____
andidates has appropriate information riate work candidates included in report idate has been assigned to proper group	Score _____
Clearances ion and/or clearance information updated or verified	Score _____
is, isolated to grammar and/or formatting ; or incorrect items ems are missing or incorrect issing or incorrect	Score _____

Final Score _____

OF 466 Joseph ddy Moffett ay 09, 2023	OF 466 Joseph ddy Moffett ay 09, 2023	OF 466 Joseph ddy Moffett ay 09, 2023
ed 08/23/2023 15:44:42 Page 1 of 31	ed 08/23/2023 15:44:42 Page 2 of 31	ed 08/23/2023 15:44:42 Page 4 of 31

LTDOT Keeping Utah Moving

OF 466
Sevier River Bridge, east of Joseph
 Inspector: Teddy Moffett
 Inspection Date: May 09, 2023

IDENTIFICATION	INSPECTION
Bridge Key: OF 466	(00) Date of Inspection: 5/9/2023
(0) NBI Number: OF 466	(01) Frequency: 24
Structure Name: Sevier River Bridge, east of Joseph	Next Inspection: 5/9/2025
(8) Location: 0.7 MILE EAST OF JOSEPH	Inspection Type (02) Freq (03) Last Insp Next Insp
(7) Carries: SR-119	Element 24 24 5/9/2023 5/9/2025
(42A) Service On: 1 Highway	(A) Fracture Critical 24
(6) Feature Crossed: SEVIER RIVER	(B) Underwater 60 6/26/2019 6/26/2024
(42B) Service Under: 5 Waterway	(C) Special Insp 24 N/A
(4) Placecode: County	LOAD RATING, POSTING AND SIGNS
(3) County: Sevier	(41) Posting Status: A Open, no restriction
(1) State: 49 Utah	(70) Posting %: 5 Above Legal Loads
(2) Region: Region 4	Rating Date: 5/4/2019
(16) Latitude: 38.52	(31) Design Load: 6 MS18(H20)+mod
(17) Longitude: -112.21	(63) Op Method: 6 LRFR (HL83)
(22) Owner: 01 State Highway Agency	(64) Op Rating: 1.70
(21) Custodian: 01 State Highway Agency	(65) Inv Method: 6 Load Factor (MS18)
(27) Year Built: 1981	(66) Inv Rating: 1.00
(106) Year Recon: (08) Border State: Not Applicable (P)	Sign Legibility: N/A Sign Visible: N/A
(37) Historical: (09) Responsibility:	Object Markers Req'd: N/A

Deck Overlay	Steel Coatings
(106A) Wearing Surface: 1 Monolithic Concrete	Year Applied: N/A
(106B) Membrane: 0 None	Thickness: N/A
	Steel Overcoat Year: N/A
	Paint/ Repaint Year: N/A

DECK GEOMETRY	DECK CONDITION
(68) Deck Geometry: 7 Above Min Criteria	(58) Deck Rating: 6 Satisfactory
Deck Area: 3,555.90	(36A) Bridge Rail: 1 Meets Standards
(107) Deck Type: 1 Concrete-Cast-in-Place	(38B) Transition: 1 Meets Standards
(108C) Deck Protection: 1 Epoxy Coated Reinford	(34C) Approach Rail: 1 Meets Standards
(52) O. to O. Width: 40.50	(30D) Approach Rail Ends: 1 Meets Standards
(51) Curb to Curb Width: 37.30	
(56A) Curb / Sidewalk Width L: 0.00	
(56B) Curb / Sidewalk Width R: 0.00	
(33) Median: 0 No median	

SUPERSTRUCTURE GEOMETRY	SUPERSTRUCTURE CONDITION
(45) # of Main Spans: 2	(59) Superstructure Rating: 7 Good
(46) # of Approach Spans: 0	(67) Structure Evaluation: 7 Above Min Criteria
(43 A) Main Material: 6 P/S Conc Continuous	(101) Parallel Structure: No bridge exists
(43 B) Main Design: 02 Stringer/Girder	(72) Approach Alignment: 8 Equal Desirable Crt
(48) Max Span Length: 42.50	(32) Approach Roadway Width: 37.30
(49) Structure Length: 87.50	
(112) NBIS Length: Long Enough	
(103) Temp Structure: Not Applicable (P)	
(54) Skew: 25	
(35) Structure Flared: 0 No Flare	

UDOT Inspection Report (v3.1) Wed 08/23/2023 15:44:42 Page 12 of 31

Date of Review _____
 & _____
 Date of Inspection _____

Inspection Field Review Checklist **Score: 1-5**

HW
 Agree with the current condition of structure

Score _____

photos included in report
 CS4 defects have corresponding photos
 Defects on the structure have photos
 Photo naming
 (in-focus and correct exposure)

Score _____

Field Notes

Notes follow current guidelines and format
 General notes include inspection type, local contact, inspection team ect.
 Roadway notes include comments about sign postings, performing cross sections ect.
 Notes follow current guidelines and format
 Elements are correct and remain applicable
 Notes are complete with all appropriate information
 Are appropriately coded and identified

Score _____

is coded correctly and up to date

Score _____

Candidates has appropriate information
 Appropriate work candidates included in report
 Candidate date has been assigned to proper group

Score _____

Clearances

Information and/or clearance information updated or verified

Score _____

Final Score _____

is isolated to grammar and/or formatting
 is or incorrect items
 Items are missing or incorrect
 Missing or incorrect

<p>OF 466 Joseph Taddy Moffett May 09, 2023</p>  	<p>OF 466 Joseph Taddy Moffett May 09, 2023</p>  	<p>OF 466 Joseph Taddy Moffett May 09, 2023</p>  	<p>OF 466 Joseph Taddy Moffett May 09, 2023</p>  
---	---	---	---

LTDOT **Sevier River Bridge, east of Joseph**
 Inspector: Taddy Moffett
 Inspection Date: May 09, 2023
 Environment: 3

12 Re Concrete Deck

Total	CS1	CS2	CS3	CS4
3,516 sq.ft	1,216 sq.ft (35%)	2,300 sq.ft (65%)	0 sq.ft (0%)	0 sq.ft (0%)

Timeline chart showing inspection dates from 5/15/2013 to 5/9/2023 with corresponding CS levels.

05/04/2015 Judd Jar RC bare deck and underside have no significant visible defects.

05/04/2017 DALE DEBENHAM Cast in place concrete deck has random surface map cracks spaced 1 foot and more apart. Diagonal cracks are also observed near the corners. The underside is free of spalls, delaminations, and significant cracks. 875 square feet of the deck is placed in CS2 for cracks.

05/29/2019 Randy Halbur The concrete deck element has a bare concrete topside. The concrete deck topside has diagonal cracking and wear in the wheel paths. The deck underside has reflective cracking in each girder bay. The deck overhangs are free of defects.

06/26/2019 Andrew Young The concrete deck topside has random map cracking and wear in the wheel paths. The deck underside has reflective cracking in each girder bay. The deck overhangs are free of defects.

05/19/2021 Ryan Daniels Deck NBI reduced to 6 based on the defects noted below.

05/09/2023 Taddy Moffett The top face of the reinforced concrete deck is bare. Cracking and abrasion were observed. See defect notes below for details.

1130 Cracking (RC and Other) **Element Defect** Environment: 3

Total	CS1	CS2	CS3	CS4
1,000 each	0 each (0%)	1,000 each (100%)	0 each (0%)	0 each (0%)

06/29/2019 Randy Halbur The deck topside has diagonal cracking that extends perpendicularly from the skew of the backwall joints. The moderate width cracking is approximately five to ten feet in length. The underside has reflective cracking with light efflorescence. The underside cracking varies from hairline to moderate width. The cracking above abutment 1 is free of efflorescence. 85 square feet of moderate width cracking is placed in CS2.

06/26/2019 Andrew Young The cast-in-place concrete deck has random surface map cracking spaced 1 foot or more apart. Diagonal cracks are also observed near the corners. The underside has random transverse cracking up to 0.031 inch wide. There are no changes in quantity from previous inspection [875 sq.ft in CS2 due to cracking]

06/19/2021 Ryan Daniels -Deck topside; longitudinal, transverse and map type cracking; between .008"-.03" wide, spaced 1'-3' apart (some of the noted cracking appears to be full depth, as it can be found in the deck underside as well). Light to moderate efflorescence associated with some of the cracking found toward the abutments. Year found TBD/year of last change 2021/year updated 2021; 1000 sq. ft. meets CS2 criteria.

06/09/2023 Taddy Moffett Deck Topside and Underside

1) Throughout; up to 0.02 IN Width x up to Full Width (deck) x up to Full Length (deck); Longitudinal, transverse, and diagonal cracking (efflorescence on underside in corners); Year Found 2017/Year of Last Change 2021/Year Verified 2023; 1000 SQ FT CS2

1190 Abrasion(PSC/RC) **Element Defect** Environment: 3

UDOT Inspection Report (v.3.1) Wed 06/23/2023 15:44:42
Page 14 of 31


Date of Review _____
 Date of Inspection _____

Field Review Checklist	Score: 1-5
Compare with the current condition of structure	Score _____
Photos included in report Defects have corresponding photos Defects on the structure have photos Photo naming Photo focus and correct exposure)	Score _____
Notes Notes follow current guidelines and format Field notes include inspection type, local contact, inspection team ect. Safety notes include comments about sign postings, performing cross sections ect. Notes follow current guidelines and format Comments are correct and remain applicable Notes are complete with all appropriate information Notes appropriately coded and identified	Score _____
Notes dated correctly and up to date	Score _____
Notes identifies has appropriate information Notes include work candidates included in report Notes include site has been assigned to proper group	Score _____
Clearances Clearances and/or clearance information updated or verified	Score _____

Final Score _____

Issues related to grammar and/or formatting
 Issues incorrect items
 Issues are missing or incorrect
 Issues spelling or incorrect

OF 466 Joseph y Moffett 09, 2023	OF 466 Joseph y Moffett 09, 2023	466 eph y Moffett 2023	OF 466 Joseph y Moffett 09, 2023	OF 466 Joseph y Moffett 09, 2023
Next Insp. 5/9/2025 6/26/2024		GNS 7 7 8 6 01/05/2019 5/2021 5/2023		
Criteria exists irable Crit		Criteria exists irable Crit		
8/23/2023 15:44:42 Page 1 of 31	8/23/2023 15:44:42 Page 2 of 31	8/23/2023 15:44:42 Page 4 of 31	8/23/2023 15:44:42 Page 12 of 31	8/23/2023 15:44:42 Page 14 of 31





State of Utah
 SPENCER J. COX
 Governor

DEIDRE M. HENDERSON
 Lieutenant Governor

DEPARTMENT OF TRANSPORTATION

CARLOS M. BRACERAS, P.E.
 Executive Director

TERIANNE S. NEWELL, P.E.
 Deputy Director of Planning and Investment

LISA J. WILSON, P.E.
 Deputy Director of Engineering and Operations

September 14th, 2023

City Address

RE: Bridge Inspection for Salt Lake City

Dear [redacted] City:

The Utah Department of Transportation (UDOT) inspects local government bridges every two years as part of the Bridge Inspection Program. Our bridge inspection teams typically inspect your bridges in MONTH of ODD/EVEN years. UDOT's role is to provide findings from these inspections to the bridge owner. The responsibility to address the concerns, perform the required actions and manage the findings and/or recommendations resides with the individual bridge owner. Bridges must exceed 20 feet in length to be included in the Bridge Inspection Program. Culverts and bridges less than 20 feet in length are not inspected within the Bridge Inspection Program.

Enclosed is a condition summary of the bridges within your jurisdiction. The summary contains important bridge specific recommendations to address any noted deficiencies. In addition to the bridge specific recommendations, routine maintenance is recommended on each bridge twice a year. Attached to this letter is a list of routine maintenance activities. The summary also provides an inventory list of all bridges within your jurisdiction and draws specific attention to bridges rated as follows:

Bridge Health Index (BHI): A condition based score that provides an assessment of the current asset value of the bridge compared with its asset value when it was initially constructed. Additional **Poor Condition:** This new FHWA metric replaces Structurally Deficient. The deck, superstructure or substructure is in poor condition (rated 4 or less). Bridge rehabilitation or replacement should be evaluated.

Scour Critical: Bridges with a scour critical rating of 3 or less, this indicates that the bridge is susceptible to scour and scour mitigation is recommended. Bridges rated 4 are not considered scour critical but scour mitigation is recommended due to observed scour.

Load Posted: UDOT is required to evaluate the live load carrying capacity of all bridges in the inspection system, as stipulated by the Federal Highway Administration. Included with this letter is a list of bridges that should be signed (posted) to limit the weight of vehicles that can safely traverse the structure. Please ensure that the bridges in your jurisdiction that are recommended to be posted are signed with the appropriate weight limits.

If the attached report states Update Posting, changes are required for that structure. In April 2019 the Federal Highway Administration clarified that all bridge load postings must be in place with **30 days** after the load rating determines a need for such posting. Please refer to FHWA Memo Timeframe for Installing Load Posting Signs at Bridges dated April 17, 2019 on the FHWA website for more information. Please update the signage accordingly within 30 days and email photos of the updated load posting signs to Jera Irick at jirick@utah.gov. If you have any questions or concerns about posting, please reach out to Jera.

If the report states Remove Posting, the structure is currently posted but the load rating calculations indicate load restrictions are not necessary. If the recommendation is to Remove Posting or to Update Posting to a higher posting value than existing signage, but if the owner prefers to leave the structure posted, or posted at the lower value, please inform Jera.

Local Routes on State Structures: As per Utah Admin Rule R918-6-6, your jurisdiction is responsible for routine maintenance and preventive maintenance along the top of structures that carry a local route over a state route. This includes deck overlays / seal treatments, deck pothole patching, parapet surface repair and sealing, bridge joint cleaning and sealing, drain cleaning and maintenance, keeping the deck free of debris and other items indicated on the following pages. Once this work is completed, please submit records of the work to Jera Irick at jirick@utah.gov for us to update our records. If deterioration occurring from the lack of maintenance requires rehabilitation, your representative and UDOT will meet to negotiate how the cost of the rehabilitation work to be performed will be shared.

Structures without Full Plans: Structures on this list have missing or incomplete plans in UDOT's records. Having the complete plans gives our inspectors and engineers a more complete picture of the structure and enables them to make more informed inspections and recommendations for structures that you own. Please check the structures on this list and forward any plans your organization has on file for them to Jera Irick at jirick@utah.gov.

Funding may be available to help you manage your bridge system. For structures on Federal Aid routes, please contact Eric Buell at ebuell@utah.gov. For structures off the Federal Aid routes, please contact Chris Potter at cpotter@utah.gov or go to <https://www.udot.utah.gov/od/rhc>. Please note that funds are programmed several years in advance and are awarded based on condition of the structure.

We are happy to send you the entire inspection report for any of your structures upon request. Submit the request for bridge inspection reports on the UDOT website at <https://www.udot.utah.gov/gg/bridgesplans>.

UDOT's Bridge Management Manual addresses bridge maintenance as well as many other important aspects of bridge management. Follow this link to access the Manual: www.udot.utah.gov/gg/BMM. It is vitally important to maintain accurate records of each bridge. Please review section 7.4.2 of the Manual for a list of documents to collect for all newly constructed bridges.

Please review your structure inventory to ensure that all structures listed have correct ownership. Please inform us of any structures that have not made it into your inventory listing.

If you have any related questions or concerns please feel free to contact me at mix@utah.gov or 801.633.2810.

Rebecca Mix



UTAH



State of Utah
SPENCER J. COX
Governor

DEIDRE M. HENDERSON
Lieutenant Governor

DEPARTMENT OF TRANSPORTATION

CARLOS M. BRACERAS, P.E.
Executive Director
TERIANNE S. NEWELL, PE.
Deputy Director of Planning and Investment
LISA J. WILSON, PE.
Deputy Director of Engineering and Operations

September 14th, 2023

City Address

RE: Bridge Inspection for Salt Lake City

Dear [redacted] City:

The Utah Department of Transportation (UDOT) inspects local government bridges every two years as part of the Bridge Inspection Program. Our bridge inspection teams typically inspect your bridges in MONTH of ODD/EVEN years. UDOT's role is to provide findings from these inspections to the bridge owner. The responsibility to address the concerns, perform the required actions and manage the findings and/or recommendations resides with the individual bridge owner. Bridges must exceed 20 feet in length to be included in the Bridge Inspection Program. Culverts and bridges less than 20 feet in length are not inspected within the Bridge Inspection Program.

Enclosed is a condition summary of the bridges within your jurisdiction. The summary contains important bridge specific recommendations to address any noted deficiencies. In addition to the bridge specific recommendations, routine maintenance is recommended on each bridge twice a year. Attached to this letter is a list of routine maintenance activities. The summary also provides an inventory list of all bridges within your jurisdiction and draws specific attention to bridges rated as follows:

Bridge Health Index (BHI): A condition based score that provides an assessment of the current asset value of the bridge compared with its asset value when it was initially constructed. Additional **Poor Condition:** This new FHWA metric replaces Structurally Deficient. The deck, superstructure or substructure is in poor condition (rated 4 or less). Bridge rehabilitation or replacement should be evaluated.

Scour Critical: Bridges with a scour critical rating of 3 or less, this indicates that the bridge is susceptible to scour and scour mitigation is recommended. Bridges rated 4 are not considered scour critical but scour mitigation is recommended due to observed scour.

bridges in the [redacted] with this letter is can safely traverse intended to be

re. In April 2019 in place with 30 WA Memo e FHWA website email photos of estions or

rating to Remove of the owner lera.

sdition is structures that its, deck pothole ain cleaning and lowing pages. h@utah.gov for requires of the rehabilitation

e plans in a more complete is list and forward

s on Federal Aid al Aid routes, v@utah.gov. Please on condition of the

pon request.

any other

f each bridge. newly constructed

rect ownership.

iv@utah.gov or

Structures Inspected owned by [redacted] City

Bridge ID	Year Built	Facility Carried	Feature Crossed	Location	Deck	Super	Sub	Culvert	Health Index	On/Off FA System	Maintenance and Structural Recommendations
035019C	2005	2100 SOUTH STREET	JORDAN RIVER	1300 WEST 2100 SOUTH, SLC	6	7	7	N	83.32	On FA System	Seal Relief / Backwall Joints: Seal the East relief joint. 02/17/2018 BSR: Still not complete. Condition still remains. (JWM 1/21/2020) Remove Debris from Deck / Shoulder: Sweep the deck. Generated by user "breds" on 1/17/2018 Condition still remains. (JWM 1/21/2020) Repair Erosion: Generated by user "breds" on 1/17/2018 Repair erosion under the approach slabs. Condition still remains. (JWM 1/21/2020) 02/17/2022 BSR: Still not complete Remove Debris from Bearings: Generated by user "breds" on 1/17/2018 Remove debris adjacent to bearings above pier walls. Condition still remains. (JWM 1/21/2020) Other: Generated by user "breds" on 1/17/2018 Repair sidewalk settlement in southeast corner. Condition still remains. (JWM 1/21/2020) 02/17/2022 BSR: Still not complete Update Barrier to Standard: Generated by user "breds" on 1/17/2018 Install transitions, approach rail and end treatments that meet current stan Condition still remains. (JWM 1/21/2020) 1/17/2022 BSR: Still not complete Remove Debris & Veg from Chnl: Remove the timber debris at the piers and 02/17/2018 BSR: Still not complete. Condition still remains. (JWM 1/21/2020) 1/17/2022 BSR: Still not complete Repair Underlies Spalls - Repair delamination on South face of the East app 02/17/2018 BSR: Still not complete. Condition still remains. (JWM 1/21/2020)
035091F	1976	1700 SOUTH STREET	JORDAN RIVER	1150 WEST 1700 SOUTH, SLC	6	5	5	N	40.50	On FA System	Remove Debris & Veg from Chnl: Generated by user "Nash Wilson" on 1/15/2018 Remove transient debris from around the abutments. Condition still remains. (JWM 1/21/2020) Condition Remains. (JPM 1/15/2022) Remove Debris & Veg from Chnl: Remove debris from upstream piles. Gene "Jeff Malone" on 1/22/2020 Condition remains. (JPM 1/15/2022) Repair Settlement / Ride: Repair the sidewalk settlement at the Southeast a corners. Generated by user "Jeff Malone" on 1/22/2020 Condition remains. 1/15/2022 Repair Underlies Spalls - Repair spalls and delaminations along all girders a with defects noted. Repair Beam / Pier Cap: Repair pier caps 2 and 3 along lengths at spalls and f
035082F	1976	1700 SOUTH STREET	SURPLUS CANAL	1500 WEST 1700 SOUTH, SLC	5	5	6	N	49.04	On FA System	Replace/Repair Deck Overlay: The overlay appears to have been replaced si inspection. Repair the rutting in the new overlay (STM 1/21/2020). Seal Relief / Backwall Joints: Seal backwall and deck joints (STM 1/21/2020) 1/12/2022 BSR: Still not complete Repair Beam / Girder Ends: Generated by user "Nash Wilson" on 1/22/2018 Repair tie beam spalls and girder end deterioration. Condition still remains (STM 1/21/2020) 1/12/2022 BSR: Still not complete Remove Debris from Bearings: Generated by user "Nash Wilson" on 1/22/2018 Remove debris from bearing seats at piers and abutments. Condition still remains (STM 1/21/2020). 1/12/2022 BSR: Still not complete Other: Generated by user "Nash Wilson" on 1/22/2018 Clean out graffiti and transient debris from underside of bridge. Condition still remains (STM 1/21/2020) 1/12/2022 BSR: Still not complete

Structures Inspected owned by [City]

Bridge ID	Year Built	Facility Carried	Feature Crossed	Location
03509C	2005	2100 SOUTH STREET	JORDAN RIVER	1200 WEST 2 SOUTH, SLC
035091F	1976	1700 SOUTH STREET	JORDAN RIVER	1150 WEST 1 SOUTH, SLC
035092F	1976	1700 SOUTH STREET	SURPLUS CANAL	1500 WEST 2 SOUTH, SLC

Structures with 'Poor' conditions owned by [City]

Bridge ID	Year Built	Facility Carried	Feature Crossed	Location	Deck	Super	Sub	Culvert	Health Index
035097F	1960	500 SOUTH STREET	JORDAN RIVER	1130 WEST 500 SOUTH, SLC	6	4	6	N	31.21
035107F	1965	650 NORTH STREET	JORDAN RIVER	1500 WEST 650 NORTH, SLC	5	5	4	N	26.95

Scour Critical and near critical Structures owned by [City]

Bridge ID	Year Built	Facility Carried	Feature Crossed	Location	Deck	Super	Sub	Culvert	Health Index	Scour Rating
035097F	1960	500 SOUTH STREET	JORDAN RIVER	1130 WEST 500 SOUTH, SLC	6	4	6	N	31.21	4 - Stable, Needs Action
035150D	1956	GOLF CR. ENTR. RD.	SURPLUS CANAL	ADIACENT TO SLC AIRPORT	7	7	7	N	87.23	4 - Stable, Needs Action

Posting Status for [City]

Bridge ID	Year Built	Facility Carried	Feature Crossed	Location	Deck	Super	Sub	Culvert	Health Index	Posting	Recommended Action
035095D	1948	INDIANA AVENUE	JORDAN RIVER	1050 WEST 850 SOUTH, SLC	6	6	7	N	81.31	Posted	None
035098D	1964	400 SOUTH STREET	JORDAN RIVER	1140 WEST 400 SOUTH, SLC	5	5	6	N	41.17	Posted	None
035099D	1950	300 SOUTH STREET	JORDAN RIVER	1150 WEST 300 SOUTH, SLC	6	6	7	N	77.28	Posted	None
035100F	1956	200 SOUTH STREET	JORDAN RIVER	1200 WEST 200 SOUTH, SLC	5	5	5	N	42.56	Posted	None
035107F	1965	650 NORTH STREET	JORDAN RIVER	1500 WEST 650 NORTH, SLC	5	5	4	N	26.95	Posted	None
035145F	1975	1300 SOUTH STREET	UNION PACIFIC RR	5TH TO 7TH W. ON 1300 S.	6	6	5	N	72.66	Posted	None
035150D	1956	GOLF CR. ENTR. RD.	SURPLUS CANAL	ADIACENT TO SLC AIRPORT	7	7	7	N	87.23	Posted	None
035227D	1996	Main St / S Temple	City Creek Parking	Main St. S. of S. Temple	6	6	7	N	81.62	Posting Recommended	Update Posting

Preventive maintenance for local roads over a State Highway maintained by: [City]

Bridge ID	Year Built	Facility Carried	Feature Crossed	Location	Deck	Super	Sub	Culvert	Health Index	On/Off FA System	Maintenance and Preventive Actions Needed
0F 791	2010	INTCHG. X-ROAD	I-15, (SR-15)	1000 North 900 West - SLC	6	7	7	N	82.83		
1E1322	1964	INTCHG. CONNTR. ROAD	Bishops Drainage Canal	2200 NORTH INTCHG., SLC	N	N	N	6	75.72	On FA System	

Structures Inspected

Bridge ID	Year Built
035019C	2009
035091F	1976
035092F	1975

Structures with 'Poor' conditions owned by [City]

Bridge ID	Year Built	Facility Carried	Feature Crossed	Location
035097F	1960	500 SOUTH STREET	JORDAN RIVER	1130 WEST 500 SOUTH, SLC
035107F	1965	650 NORTH STREET	JORDAN RIVER	1500 WEST 650 NORTH, SLC

Scour Critical and near critical Structures owned by [City]

Bridge ID	Year Built	Facility Carried	Feature Crossed	Location
035097F	1960	500 SOUTH STREET	JORDAN RIVER	1130 WEST 500 SOUTH, SLC
0351500	1956	GOLF CR. ENTR. RD.	SURPLUS CANAL	ADJACENT TO SLC AIRPORT

Posting Status for [City]

Bridge ID	Year Built	Facility Carried	Feature Crossed	Location
035095D	1948	INDIANA AVENUE	JORDAN RIVER	1050 WEST 850 SOUTH, SLC
035098D	1964	400 SOUTH STREET	JORDAN RIVER	1140 WEST 400 SOUTH, SLC
035099D	1950	300 SOUTH STREET	JORDAN RIVER	1150 WEST 300 SOUTH, SLC
035100F	1956	200 SOUTH STREET	JORDAN RIVER	1200 WEST 200 SOUTH, SLC
035107F	1965	650 NORTH STREET	JORDAN RIVER	1500 WEST 650 NORTH, SLC
035145F	1975	1300 SOUTH STREET	UNION PACIFIC RR	5TH TO 7TH W. ON 1300 S.
0351500	1956	GOLF CR. ENTR. RD.	SURPLUS CANAL	ADJACENT TO SLC AIRPORT
035227D	1996	Main St / S Temple	City Creek Parking	Main St. S of S. Temple

Preventive maintenance for local roads over a State Highway maintained by:

Bridge ID	Year Built	Facility Carried	Feature Crossed	Location
0F 791	2010	INTCHG. X-ROAD	I-15, (SR-15)	1000 North 900 West - SLC
1E1322	1964	INTCHG. CONNTR. ROAD	Bishops Drainage Canal	2200 NORTH INTCHG. SLC

Missing / Incomplete Plans for: [City]

Bridge ID	Year Built	Facility Carried	Feature Crossed	Location	Plans Status
035091F	1976	1700 SOUTH STREET	JORDAN RIVER	1150 WEST 1700 SOUTH, SLC	Partial Plans
035095D	1948	INDIANA AVENUE	JORDAN RIVER	1050 WEST 850 SOUTH, SLC	Partial Plans
035097F	1960	500 SOUTH STREET	JORDAN RIVER	1130 WEST 500 SOUTH, SLC	Partial Plans
035098D	1964	400 SOUTH STREET	JORDAN RIVER	1140 WEST 400 SOUTH, SLC	Partial Plans
035100F	1956	200 SOUTH STREET	JORDAN RIVER	1200 WEST 200 SOUTH, SLC	Partial Plans
035103E	1980	AIRPORT EXIT ROAD	SURPLUS CANAL	ENTRANCE TO SLINT. AIRPT.	Partial Plans
035106F	1960	1000 NORTH STREET	JORDAN RIVER	1550 WEST 1000 NORTH, SLC	Partial Plans
035108D	1983	500 NORTH STREET	JORDAN RIVER	1650 WEST 500 NORTH, SLC	Partial Plans
035145F	1975	1300 SOUTH STREET	UNION PACIFIC RR	5TH TO 7TH W. ON 1300 S.	Partial Plans
035150D	1956	GOLF CR. ENTR. RD.	SURPLUS CANAL	ADJACENT TO SLC AIRPORT	Partial Plans
035225D	2009	South Temple	City Creek Parking	South Temple	Field Measurements
035230D	1998	West Temple	Conference Center Park	LDS Conference Center	Partial Plans
035221F	1999	400 SOUTH STREET	UPRR TRACKS AND 700 W	500 TO 700 W. ON 400 S.T	Partial Plans

Rehabilitation/Replacement List (No Culverts) Utah Department of Transportation Structures Division

NHPP_BR Eligible Bridges:


Bridge ID	Structure Name	Region	Vulnerability	Criticality	PHH	Location	Feature Intersected	Year Built	AADT	Deck NBI	Super NBI	Sub NBI	Culvert NBI	LRFR LR Factor	LRFR R Factor
DC 584	300 West Bridge over I-215	2	40.24	51	20.3	6300 SOUTH 300 W. MURRAY	I-215 (SR-215) EBL & SBL	1972	1,994	4(4 yrs)	5(4 yrs)	5(4 yrs)		1.24	1.65
DC 481	SR-126 (2350 W) over I-15 in South Willard	1	40.94	68	21.2	4200 N 2350 W	I-15 (SR-15) NBL AND SBL	1968	7,045	4(0 yrs)	5(2 yrs)	5(8 yrs)		1.20	1.70
DC 191R	SR-302 Bridge over Weber River At Rockport	2	41.11	25	21.5	Entr to Rockport St. Park	WEBER RIVER	2009	335	4(1 yrs)	5(3 yrs)	5(3 yrs)		2.19	
DC 709	SR-201 Bridge at the 3200 West Interchange	2	41.72	69	22.3	3200 W. 2100 SO. SLC	WEBER RIVER	1980	87,931	4(0 yrs)	4(0 yrs)	5(0 yrs)		1.08	1.32
DC 616	Pocatello Valley Interchange Bridge	1	42.13	47	22.8	POCATELLO VALLEY INTER	I-84 (SR-84) EBL & W	1969	15	4(0 yrs)	4(0 yrs)	5(4 yrs)		1.10	1.70
4F 50	I-80 Westbound bridge over 20th East St.	2	43.62	56	24.8	2400 SO. & 2000 EAST	2000 EAST STREET	1964	90,775	4(1 yrs)	5(15 yrs)	6(22 yrs)		1.30	1.87
0F 153	Long Bridge over the Weber River	1	44.74	91	26.3	1.2 MI.EAST TAGGART INT.	WEBER RIVER	1967	10,313	6(9 yrs)	4(1 yrs)	5(1 yrs)		1.40	2.09
0E 355	Sulphur Creek Culvert in Capitol Reef Park	4	44.80	55	26.4	IN FRUITA NEAR PARK HQ'S	SULPHUR CREEK	1980	985				4(0 yrs)	1.00	
0D 764	Clear Creek Bridge on US-89	4	45.17	58	26.9	0.4 MI.SO.OF SEVIER JCT.	CLEAR CREEK	1929	1,370	5(16 yrs)	4(0 yrs)	5(0 yrs)		1.60	3.20
4D 754	I-84WB Bridge over 4400 So. in Riverdale	1	45.70	49	27.6	4400 SO. IN RIVERDALE	4400 SOUTH STREET	1967	18,512	4(2 yrs)	5(15 yrs)	6(12 yrs)		2.00	1.54
0F 472	Bothwell Interchange Bridge	1	46.05	68	28.1	AT THE BOTHWELL INTERCHG.	I-84 (SR-84)	1989	5,000	4(0 yrs)	6(4 yrs)	5(4 yrs)		1.20	2.43
0D 735	4400 South Bridge in Riverdale over I-15	1	46.47	60	28.6	4400 SO.ST.IN RIVERDALE	I-15 (SR-15) NBL and SBL	1966	8,922	4(2 yrs)	6(2 yrs)	5(10 yrs)		1.36	1.90
DC 301	Cottonwood Wash Bridge, west of Blandino	4	47.08	100	29.4	8.5 MI.SW.OF BLANDINO	COTTONWOOD WASH	1959	531	6(14 yrs)	6(2 yrs)	2(2 yrs)		1.30	1.98
DC 422	Foothill Drive Bridge over I-80	2	47.36	56	29.8	MOUTH OF FARLEYS CANYON	I-80 (SR-80) EBL AND WB	1966	13,623	4(1 yrs)	6(1 yrs)	5(3 yrs)		1.57	1.98
DC 644	Adams Ave over I-84	1	48.02	65	30.7	SOUTH WEBER INTERCHANGE	I-84 (SR-84) EBL & W	1974	3,715	4(2 yrs)	7(24 yrs)	6(2 yrs)		1.06	1.65
DC 717	SR-28 Bridge at the North Nephth Interchange	3	48.14	68	30.9	NORTH NEPHTH INTERCHANGE	I-15 (SR-15) NBL & S	1984	5,355	6(18 yrs)	6(4 yrs)	4(0 yrs)		1.00	1.40
DC 669	5600 West Interchange Bridge on I-80	2	48.21	63	31.0	5600 WEST INTERCHANGE	I-80 (SR-80) EBL & W	1980	18,661	4(0 yrs)	7(22 yrs)	6(2 yrs)		1.67	2.54
DC 574	Mt. Aire Interchange Bridge on I-80	2	49.32	53	32.4	MT. AIRE INTERCHANGE	I-80 (SR-80) EBL AND WB	1973	7,905	4(1 yrs)	7(5 yrs)	5(12 yrs)		1.31	1.65
DC 288	Weber River Bridge at upper end of Rockport Res.	2	49.91	53	33.2	5.5 MI.SE.OF WANSHIP	WEBER RIVER	1955	1,660	6(23 yrs)	5(5 yrs)	4(3 yrs)		1.10	1.70
1F 454	I-15 NB over Deer Crossing, north of Mills Jct.	3	50.35	43	33.8	4 MI.NO.MILLS JCT.INTCHG.	DEER CROSSING	1984	13,275	4(0 yrs)	7(4 yrs)	6(2 yrs)		1.40	1.87
DC 375A	Sevier River Bridge, north of Redmond	4	52.44	35	36.6	NORTH OF REDMOND	SEVIER RIVER	1934	515	5(8 yrs)	5(8 yrs)	5(8 yrs)		1.40	-1.00
DC 261	Gordon Creek Bridge, east of Mountain Green	1	54.32	47	39.1	1 MILE EAST MT.GREEN INT.	GORDON CREEK	1927	7,160	5(8 yrs)	5(8 yrs)	5(8 yrs)		1.00	1.21
DC 279	Freemont River, W. of Calneville	4	55.33	73	40.4	3.5 MI. W. of Calneville	FREMONT RIVER	1954	327	5(4 yrs)	5(14 yrs)	6(2 yrs)		1.06	-1.00
DC 740	UP&L Penstock Bridge on SR-168	1	55.61	45	40.8	0.5 MI.NO.OF HILL AFB	U.P.& L.CO. PENSTOCK	1964	1,205	5(24 yrs)	5(24 yrs)	5(4 yrs)		1.00	0.80
DC 276	Rocky Canyon Wash Bridge on SR-14	4	55.80	61	41.1	3.5 MI EAST CEDAR CITY	ROCKY CANYON WASH	1950	2,090	5(16 yrs)	5(16 yrs)	5(16 yrs)		1.00	1.10
DC 144	West Green River Railroad Underpass	4	55.92	44	41.2	2 MI.WEST OF GREEN RIVER	SR-19	1938	4,600	5(16 yrs)	5(23 yrs)	5(18 yrs)		-1.00	
DC 561	SR-35 over Duchesne River, North of Duchesne	3	56.12	59	41.5	16.2 MILES SE.OF TABIONA	DUCHESNE RIVER	1958	475	5(10 yrs)	5(10 yrs)	5(4 yrs)		1.70	2.80
0F 238	Weber River Bridge, Just W of Intec. with SR-126	1	56.21	46	41.6	1 MILE WEST OF I-15 SR126	WEBER RIVER	1970	7,420	5(6 yrs)	5(6 yrs)	5(24 yrs)		1.30	
1C 628	NB Bangerter Hwy bridge over I-80, so of Airport	2	56.51	63	42.0	AIRPORT INTERCHANGE-GLC	I-80 (SR-80) EBL & W	1986	19,143	5(8 yrs)	5(0 yrs)	5(4 yrs)		1.56	2.54
0F 84	University Avenue Viaduct on SR-189	3	56.58	66	42.1	600 SO.UNIV.AVE.IN PROVO	UPRR, UTA & 500 SO.S	1966	26,869	5(14 yrs)	5(22 yrs)	5(8 yrs)		1.37	1.54
DC 284	Smith's Crossing Bridge, NE of Henrieville	4	56.78	69	42.4	8 MILES NE OF HENRIEVILLE	HENRIEVILLE WASH	1955	770	5(2 yrs)	5(6 yrs)	6(16 yrs)		1.00	1.10
4F 86	I-80 WB bridge at Jeremy Ranch Interchange	2	56.87	56	42.5	JEREMY RANCH INTCHG.	CO.RD. INTCHG. X-ROAD	1971	55,065	5(3 yrs)	5(3 yrs)	5(1 yrs)		1.18	1.76
1C 302	1000 North Bridge in Bountiful	1	56.95	72	42.6	500 W. INTCHG. BOUNTIFUL	RAMP, I-15SB TO US-89SB	1960	120,185	5(12 yrs)	5(4 yrs)	5(4 yrs)		1.10	1.60
DC 569	Duchesne River Bridge on SR-208	3	46.54	59	42.7	9.7 MI.NORTH OF JCT.US-40	DUCHESNE RIVER	1959	355	5(2 yrs)	5(0 yrs)	5(12 yrs)		0.71	1.20
3C 330	Old Bamberger Railroad Overpass Bridge	1	57.02	44	42.7	500 W.2000 SO.-BOUNTIFUL	US-89 (SR-89)	1935	1,399	5(22 yrs)	5(22 yrs)	5(18 yrs)		1.61	-1.00
DC 368	Little Bear River Bridge, east of Wellsville	1	57.28	64	43.0	EAST OF WELLSVILLE	LITTLE BEAR RIVER	1934	3,612	5(24 yrs)	5(14 yrs)	6(6 yrs)		1.15	1.43
0F 424	East Canyon Creek Bridge, east of Porterville	1	57.41	40	43.2	2.5 MI EAST PORTERSVILLE	EAST CANYON CREEK	1930	415	5(0 yrs)	5(0 yrs)	5(6 yrs)		1.10	1.43
DC 235	Fremont River Bridge, E. of Fruita	4	57.46	62	43.3	2 MI EAST OF FRUITA	FREMONT RIVER	1960	985	5(8 yrs)	5(8 yrs)	5(22 yrs)		1.10	
2D 577	I-84EB Stoddard Farm Road Bridge	1	57.59	43	43.5	3.9 MI.PETERSON INTER.	STODDARD FARM ROAD	1964	14,997	5(2 yrs)	5(2 yrs)	5(2 yrs)		1.17	1.70
0F 131	700 West Street Bridge over I-215	2	57.63	63	43.5	6200 SO. 700 W. IN MURRAY	I-215 (SR-215) EBL & W	1969	10,236	5(0 yrs)	5(10 yrs)	5(8 yrs)		1.30	1.50
3C 625	Airport Interchange SB Bridge	2	57.66	63	43.5	AIRPORT INTERCHANGE-GLC	I-80 (SR-80) EBL & W	1986	56,887	5(0 yrs)	6(14 yrs)	5(6 yrs)		1.42	1.76
DC 868	Willow Creek Bridge on SR-191, N. of US-6	4	57.75	41	43.7	2.5 MI. N. of SR-6 JCT.	WILLOW CREEK	1962	2,884	5(14 yrs)	5(14 yrs)	5(14 yrs)		2.80	
DC 562	Mt. Dell Water Treatment Plant Access Bridge	2	57.84	60	43.8	BELLOW MT. DELL RESERVOIR	I-80 (SR-80) EB AND WB	1973	7,905	5(19 yrs)	5(3 yrs)	5(3 yrs)		1.06	
DC 779	Railroad overpass bridge on 148th South	2	57.86	41	43.8	1000 W.14500 SO., DRAPER	SR-140	1935	2,829	5(4 yrs)	5(21 yrs)	5(21 yrs)			



AD ASTRA PER ASPERA

Kansas
Department of Transportation

KANSAS



KANSAS BRIDGE INSPECTION FORM

001-0008 BIF 2023
 Page 1 of 3
 Date Printed: 8/23/2023
 Serial No: 0608

District: 4 Area: 1 Sub-Area: 3 Route: U 54 County: 001 Allen Ref. Pt: 335.66

RECORD DATA: Location Description: 0.31 MI. E. US-169 City: Rural Latitude/Longitude: 37.6221, -95.3738 [Link to Map](#)
 Feature Carried: US54 HWY Feature Crossed: ROCK CREEK Responsible: KDOT
 Orientation: ON Detour: 2.00 mi. Stream Name Sign: Yes
 Lanes Carried: 5 Trans Lanes: 0 Lanes Crossed: 0

STRUCTURAL DATA:

	H	3	HS	3S2	3-3	T130	T170	HL93
ADJ Load Rate Inv:	26	34	30	52	65	69	91	
ADJ Load Rate Opr:	43	56	65	87	109	115	152	

Posted (ton):

Bridge Length: 212.5 ft. Number of Units: 1 Bridge Roadway: 84.0 ft.
 Main Unit: 1 RCGH Wide: Spans: 1 @ 36, 3 @ 46, 1 @ 36

Date Rated: 02/05/2020
 Design Live Load Type: HS
 Design Load: 20 Ton
 Skew: N/A, Not Skewed
 Rotation: N/A, Not Rotated
 Flared: No Flare

APPRAISAL DATA:

7 Structural Evaluation Sufficiency Rating: 97.9 Structure Ht: 98.7
 9 Deck Geometry ADT: 7033 % Trucks: 8
 N Underclearances Vertical Overclearance:

	Verticals	Horizontals	Lat Left	Lat Right	Verticals Signed	Vert Clear Date

PROJECT INFORMATION:

CONSTRUCTION	1989	54-1-F-038-5(16)	Micro/File: 465 / 84
OL	2013	KA-2202-01	

	2023	2021	2019	2017	2015
Deck	7	7	8	8	8
Super	7	7	7	7	7
Sub	8	8	8	8	8
Culvert	N	N	N	N	N

BRIDGE-LEVEL NOTES:



01-0008 BIF 2023
 Page 1 of 3
 Date Printed: 8/23/2023

KANSAS BRIDGE INSPECTION FORM

District: 4 Area: 1 Sub-Area: 3 Route: U 54 County: 001 Allen Ref. Pt: 335.66 Serial No: 0008

RECORD DATA: Location Description: 0.31 MI. E. US-109 City: Rural Latitude/Longitude: 37.9221, -95.3738
 Feature Carried: US54 HWY Feature Crossed: ROCK CREEK
 Orientation: ON Responsible: KDOT
 Detour: 2.00 mi. Stream Name Sign: Yes
 Lanes Carried: 5 Trans Lanes: 0 Lanes Crossed: 0

STRUCTURAL DATA:

	H	3	HS	3S2	3-3	T130	T170	HL93
ADJ Load Rate Inv:	28	34	39	52	65	69	91	
ADJ Load Rate Opr:	43	58	65	87	100	115	152	

Posted(ton):
 Bridge Length: 212.5 ft. Number of Units: 1 Bridge Roadway: 84.0 ft.
 Main Unit: 1 RCSH Wide: Spans: 1 @ 36.3 @ 46.1 @ 36

APPRAISAL DATA: Sufficiency Rating: 07.9 Structure HI: 98.7
 7 Structural Evaluation
 0 Deck Geometry ADT: 7063 % Trucks: 8
 N Underclearances Vertical Overclearance:
 Verticals Horizontal Lat Left Lat Right Verticals Signed Vert Clear Date

PROJECT INFORMATION:

	1999	54-1-F-039-5(16)	MicroFile: 485 / 84
CONSTRUCTION			
OL	2013	KA-2202-01	

Historical Bridge Inspection Ratings

	2023	2021	2019	2017	2015
Deck	7	7	8	8	8
Super	7	7	7	7	7
Sub	8	8	8	8	8
Culvert	N	N	N	N	N

BRIDGE-LEVEL NOTES:

Page 2 of 3
 Date Printed: 8/23/2023

District: 4 Area: 1 Sub-Area: 3 Route: U 54 County: 001 Allen Ref. Pt: 335.66 Serial No: 0008

Main Unit: 1 RCSH Wide: Spans: 1 @ 36.3 @ 46.1 @ 36
DECK:
 DkRate: 7

Critical Notation: None
 Deck Material: Reinforced Concrete Deck Thickness: 15.0 in.
 Wearing Surface: Silica Fume WS Thickness: 1.0 in.
 Median: No Median Median Width: 0.0 ft.
 Railing: Conc/Curbs 2'P27" Deck Width: 86.0 ft.
 Curb/Sdwalk: Left: 0.0 Right: 0.0 Drainage Sys: Metal Slots & DI
 Exp Devices: Near: N/A Far: N/A

	Delams:	1%
TOP: Deterioration		2%
Spalls		0%
BTM: Deterioration		2%
Spalls		1%

Element Description	Qty	Qty 1	Qty 2	Qty 3	Qty 4	Pot 1	Pot 2	Pot 3	Pot 4
38 Re Concrete Slab	17900 sq.ft	17383	358	179	0	97	2	1	0
321 Re Conc Approach Slab	2185 sq.ft	2185	0	0	0	100	0	0	0
331 Re Conc Bridge Railing	425 ft	405	17	3	0	95	4	1	0
510 Wearing Surfaces	17900 sq.ft	17900	0	0	0	100	0	0	0
860 Clear Deck Panels	1 sq.ft	1	0	0	0	100	0	0	0

SUPER:
 SupRate: 7


Critical Notation: None None None None None
 Hinge Type: Not Hinged Bearing Type: N/A
 Last Painted: Type: Nothing Steel: Tons
 Paint Condition: 6 Unpainted

	State 1	State 2	State 3	State 4
Steel Protective Coating %/s	0	0	0	0

SUB:
 SubRate: 8

Critical Notation: None None
 Abutment Type Near: 12 Cap on Integral ON: Steel H-File
 Abutment Type Far: 12 Cap on Integral ON: Steel H-File
 Pier Type: Column Bent ON: Spread Footings
 Berm Protection: Earth Berms

Element Description	Qty	Qty 1	Qty 2	Qty 3	Qty 4
205 Re Conc Column	24 each	24	0	0	0
215 Re Conc Abutment	172 ft	170	2	0	0



KANSAS BRIDGE INSPECTION FORM
 Page 1 of 3
 Date Printed: 8/23/2023
 01-0008 BIF 2023

District: 4 Area: 1 Sub-Area: 3 Route: U 54 County: 001 Allen Ref. Pt: 335.66 Serial No: 0008

RECORD DATA: Location Description: 0.31 MI. E. US-109 City: Rural Latitude/Longitude: 37.9221, -95.3738 [Link to Map](#)
 Feature Carried: U554 HWY Feature Crossed: ROCK CREEK
 Orientation: ON Responsible: KDOT
 Detour: 2.00 mi. Stream Name Sign: Yes
 Lanes Carried: 5 Trans Lanes: 0 Lanes Crossed: 0

STRUCTURAL DATA:

	H	3	HS	3S2	3-3	T130	T170	HL93
ADJ Load Rate Inv:	28	34	39	52	65	69	91	
ADJ Load Rate Opr:	43	56	65	87	100	115	152	

Posted (ton):

Bridge Length: 212.5 ft. Number of Units: 1 Bridge Roadway: 84.0 ft.
 Main Unit: 1 RCSH Wide Spans: 1 @ 36, 3 @ 46, 1 @ 36

APPRAISAL DATA: Sufficiency Rating: 97.9 Structure HI: 98.7
 7 Structural Evaluation ADT: 7083 % Trucks: 8
 0 Deck Geometry Vertical Overclearance:
 N Underclearances Verticals Horizontals Lat Left Lat Right Verticals Signed Vert Clear Date

PROJECT INFORMATION:

		Historical Bridge Inspection Ratings				
		2023	2021	2019	2017	2015
CONSTRUCTION	1989 54-1-F-038-5(18) Micro/File: 485 / 84	Deck	7	7	8	8
OL	2013 KA-2202-01	Super	7	7	7	7
		Sub	8	8	8	8
		Culvert	N	N	N	N

BRIDGE-LEVEL NOTES:

County: 001 Allen Ref. Pt: 335.66 Serial No: 0008

36

Delams: 1%
 TOP: Deterioration 2%
 Spalls 0%
 BTM: Deterioration 2%
 Spalls 1%

Qty2	Qty3	Qty4	Pct1	Pct2	Pct3	Pct4
358	179	0	97	2	1	0
0	0	0	100	0	0	0
17	3	0	95	4	1	0
0	0	0	100	0	0	0
0	0	0	100	0	0	0

g Type: N/A
 ns

Steel Protective Coating %'s			
State 1	State 2	State 3	State 4
0	0	0	0

el H-Pile
 el H-Pile
 read Footings

Qty 2	Qty 3	Qty 4
0	0	0
2	0	0

Page 2 of 3
 Date Printed: 8/23/2023

Page 3 of 3
 Date Printed: 8/23/2023

County: 001 Allen Ref. Pt: 335.66 Serial No: 0008

36

Delams: 1%
 TOP: Deterioration 2%
 Spalls 0%
 BTM: Deterioration 2%
 Spalls 1%

Qty2	Qty3	Qty4	Pct1	Pct2	Pct3	Pct4
358	179	0	97	2	1	0
0	0	0	100	0	0	0
17	3	0	95	4	1	0
0	0	0	100	0	0	0
0	0	0	100	0	0	0

g Type: N/A
 ns

Steel Protective Coating %'s			
State 1	State 2	State 3	State 4
0	0	0	0

el H-Pile
 el H-Pile
 read Footings

Qty 2	Qty 3	Qty 4
0	0	0
2	0	0

Page 2 of 3
 Date Printed: 8/23/2023

Page 3 of 3
 Date Printed: 8/23/2023

District: 4 Area: 1 Sub-Area: 3 Route: U 54 County: 001 Allen Ref. Pt: 335.66 Serial No: 0008

APPROACH ROADWAY ALIGNMENT: Shld >8'-Bridg roadway = Approach rdwy
 2023 - 8 2021 - 8 2019 - 8 2017 - 8 2015 - 8
 Signing: 0 2 2 0 Has: _____ Traf Safety Feats: 0 1 1 0 Has: _____ Relief Slots _____
 Appr Rdwy Width Near: 80.0 ft. Far: 80.0 ft.
 Guardrail: Steel plate W at Ends End Treatment: Flared
 Guardrail Approach: Left: Yes Right: Yes Guardrail Exit: Left: Yes Right: Yes

CHANNEL:
 2023 - 7 2021 - 7 2019 - 7 2017 - 7 2015 - 7
 Scour Critical Rating: 3 SC - Unstable
 Channel Protection: Left: Earth Channel Right: Earth Channel

WATERWAY ADEQUACY: Drift
 2023 - 7 2021 - 7 2019 - 7 2017 - 7 2015 - 7
 Drainage: 31.0 Sq. Mi.

ATTACHMENTS:
 No Attachments
 Nothing
 Nothing
 Nothing

SPECIAL INSPECTIONS: Last Inspection Required Interval Next Inspection

OTHER SPECIAL INSPECTION
 Pin and Hanger:
 Fracture Critical:
 Routine Snooper:
 UW Inspec: 07/2001
 UW Inspec Type: Underwater Visual
 Routine Inspection: 2/15/2023 Y 2 Yr(s) 2/15/2025

RECOMMENDED MAINTENANCE: Seal EWS/approaches

A List:
 B List:
 C List:
 D List:

Inspected on Month _____ Day _____ Year _____

MAINTENANCE HISTORY:
 Maintenance Totals: \$11,616.25 Reviewed by _____ Date ____/____/____
 PROPOSED PROJECTS:


8/23/2023

BRIDGE COUNT CONDITION BY JURISDICTION

Total Count by Inspection Year - On NHS Only


	2011	2012	2013	2014	2015	2016	2017	2018	2019	2020	Last Year % of Total	Jurisdiction % of Total Bridges
State Highway System												
Total Bridges	2,235	2,567	2,581	2,585	2,582	2,591	2,600	2,603	2,612	2,626		91.91%
Good	1,907	2,148	2,152	2,136	2,105	2,105	2,096	2,107	2,100	2,110	80.4%	
Fair	313	393	407	433	465	473	491	486	498	502	19.1%	
Poor	15	26	22	16	12	13	13	10	14	14	0.5%	
City												
Total Bridges	10	1	178	15	12	12	12	9	9	8		0.28%
Good	8		118	10	9	9	9	6	6	6	75.0%	
Fair	2	1	57	5	3	3	3	3	3	2	25.0%	
Poor			3			0	0	0	0	0	0.0%	
County												
Total Bridges			28	4	4	4	4	4	4	4		0.14%
Good			10		1	1	0	0	0	0	0.0%	
Fair			16	4	3	3	4	4	4	4	100.0%	
Poor			2			0	0	0	0	0	0.0%	
Turnpike												
Total Bridges	212	218	218	219	218	218	215	215	219	219		7.67%
Good	137	142	154	151	148	150	151	153	159	163	74.4%	
Fair	75	76	64	67	69	67	64	62	60	56	25.6%	
Poor				1	1	1	0	0	0	0	0.0%	
Totals												
Total Bridges	2,457	2,786	3,005	2,823	2,816	2,825	2,831	2,831	2,844	2,857		
Good	2,052	2,290	2,434	2,297	2,263	2,265	2,256	2,266	2,265	2,279	79.8%	
Fair	390	470	544	509	540	546	562	555	565	564	19.7%	
Poor	15	26	27	17	13	14	13	10	14	14	0.5%	

% in GOOD Condition (NBI Ratings > 6)



* Note: Data for 2013 and beyond differs from other years, in that the NHS was expanded.

% of Deck Area in POOR Condition (NBI Ratings < 5)



BRIDGE PERFORMANCE MEASURES REPORT

8/23/2023


NOTE: The "% of Bridges in Good Condition" value is based on the FHWA deck area (sq. ft.) of the bridges on the State system at the time this report is run.

This data is from the FHWA NBI Submittal Year 2023. Data does not include Border Bridges. FHWA deck area may not match BrM deck area.

Performance Measures:

CONDITION	NBI Value	Deck Area	% Of Total	Number of Bridges by Age	
POOR	<= 4	1250976.02	2.54	Year Range	Totals
FAIR	5-6	13019353.21	26.48	1900 - 1910	3
GOOD	>= 7	34896935.23	70.98	1910 - 1935	420
				1935 - 1960	1042
TOTAL		49167264.46	100	1960 - 1985	1740
				1985 - 2010	1542
				2010 - Present	406

Number of Bridges by Age



Budget Preparation - Program 71110:

OUTCOME MEASURES	T-WORKS Actual 2023
Percent of Bridges on the State Highway System that are classified to be in "Good" condition	71

Comprehensive Annual Financial Report (CAFR):

Fiscal Year	Minimum Acceptable Condition Level	Actual Condition Level
2023	70	71

AASHTO Ware™
 **BRIDGE**
MANAGEMENT



Caltrans®

CALIFORNIA

Department of Transportation - Division of Maintenance Structure Maintenance & Investigations

BRIDGE PRE-INSPECTION REPORT

BRIDGE NO.: 01 0020

STRUCTURE NAME: SMITH RIVER (DR. ERNEST M FINE MEMORIAL BRIDGE)

INSPECTION DATE: August 25, 2021

PREVIOUS INSPECTION INFORMATION

(90) ROUTINE INSPECTION	08/25/2021 (P1) FREQ	24 MO	RESP	SEND TO FHWA	Yes
(93A) NSTM INSPECTION	06/20/2023 (62A) REQ - FREQ Y-YES	24 MO	FC Team	NBI BRIDGE RECORDS	Yes
(93B) UNDERWATER INSPECTION	05/25/2021 (92B) REQ - FREQ Y-YES	60 MO		NBI UNDER RECORDS	No
(93C) OTHER SPECIAL INSPECTION	N/A (92C) REQ - FREQ N-NO	MO		NBI UNDER RECORDS	No

PHOTOS - ROWY 2021
 ELEV 2021
 UNDER 2021

STREAM X SECTION 2020 - Scour Critical Verify X Section
 REACTIVE AGGREGATE 1 ASR - Not Evident

BRIDGE LOCATION INFORMATION

(9) LOCATION	01-DN-101-36.06	(7) FACILITY CARRIED	U.S. HIGHWAY 101
(11) POSTMILE	36.06	(8) FEATURE INTERSECTED	SMITH RIV, SOUTH BANK RD
(16) LATITUDE	41°52'40.37"	(5) INVENTORY RTE(ON/UNDER)	ON 121001010
(17) LONGITUDE	124°08'15"	(104) ON NATIONAL HIGHWAY SYSTEM	ROUTE ON NHS

STRUCTURAL HEALTH CONDITION SUMMARY INFORMATION

(59) DECK	5 FAIR	DECK AREA (SF)	3,095
(59) SUPERSTRUCTURE	5 FAIR	SUFFICIENCY RATING	26.1
(60) SUBSTRUCTURE	7 GOOD	PAINT CONDITION	89
(82) CULVERT	N N/A (NBI)	STRUCTURALLY DEFICIENT (SD) STATUS	NOT SD
(87) STRUCTURE EVALUATION	2 INTOLERABLE - REPLACE (113) SCOUR		3 SC - UNSTABLE

PHOTOGRAPH IDENTIFICATION



Printed on: Wednesday 08/23/2023 02:36 PM Page 1 of 15

Pre-Inspection Report

Department of Transportation - Division of Maintenance Structure Maintenance & Investigations

BRIDGE INSPECTION REPORT
 Routine Inspection

BRIDGE NO.: 01 0020

STRUCTURE NAME: SMITH RIVER (DR. ERNEST M FINE MEMORIAL BRIDGE)

INSPECTION DATE: August 25, 2021


BRIDGE LOCATION INFORMATION

(9) LOCATION	01-DN-101-36.06	(7) FACILITY CARRIED	U.S. HIGHWAY 101
(11) POSTMILE	36.06	(8) FEATURE INTERSECTED	SMITH RIV, SOUTH BANK RD
(16) LATITUDE	41°52'40.37"	(5) INVENTORY RTE(ON/UNDER)	ON 121001010
(17) LONGITUDE	124°08'15"	(104) ON NATIONAL HIGHWAY SYSTEM	ROUTE ON NHS

STRUCTURAL HEALTH CONDITION SUMMARY INFORMATION

(59) DECK	5 FAIR	DECK AREA (SF)	3,095
(59) SUPERSTRUCTURE	5 FAIR	SUFFICIENCY RATING	26.1
(60) SUBSTRUCTURE	7 GOOD	PAINT CONDITION	89
(82) CULVERT	N N/A (NBI)	STRUCTURALLY DEFICIENT (SD) STATUS	NOT SD
(87) STRUCTURE EVALUATION	2 INTOLERABLE - REPLACE (113) SCOUR		3 SC - UNSTABLE

PHOTOGRAPH IDENTIFICATION



TEAM LEADER: Warren L. Peterson
 REPORT AUTHOR: Warren L. Peterson
 INSPECTED BY: WL Peterson/JM Boulant

Warren L. Peterson (Registered Civil Engineer) Date

Printed on: Wednesday 08/23/2023 02:38 PM Page 1 of 10 01 0020/AABG/71376

Digital Report Review

Department of Transportation - Division of Maintenance Structure Maintenance & Investigations

BRIDGE INSPECTION REPORT
 Routine Inspection

BRIDGE NO.: 01 0020

STRUCTURE NAME: SMITH RIVER (DR. ERNEST M FINE MEMORIAL BRIDGE)

INSPECTION DATE: August 25, 2021


BRIDGE LOCATION INFORMATION

(9) LOCATION	01-DN-101-36.06	(7) FACILITY CARRIED	U.S. HIGHWAY 101
(11) POSTMILE	36.06	(8) FEATURE INTERSECTED	SMITH RIV, SOUTH BANK RD
(16) LATITUDE	41°52'40.37"	(5) INVENTORY RTE(ON/UNDER)	ON 121001010
(17) LONGITUDE	124°08'15"	(104) ON NATIONAL HIGHWAY SYSTEM	ROUTE ON NHS

STRUCTURAL HEALTH CONDITION SUMMARY INFORMATION

(59) DECK	5 FAIR	DECK AREA (SF)	3,095
(59) SUPERSTRUCTURE	5 FAIR	SUFFICIENCY RATING	26.1
(60) SUBSTRUCTURE	7 GOOD	PAINT CONDITION SUPER	89.0 SUBSTR 89.0
(82) CULVERT	N N/A (NBI)	STRUCTURALLY DEFICIENT (SD) STATUS	NOT SD
(87) STRUCTURE EVALUATION	2 INTOLERABLE - REPLACE (113) SCOUR		3 SC - UNSTABLE


PHOTOGRAPH IDENTIFICATION



TEAM LEADER: Warren L. Peterson
 REPORT AUTHOR: Warren L. Peterson
 INSPECTED BY: WL Peterson/JM Boulant

Warren L. Peterson (Registered Civil Engineer) 9/14/2021 Date

Printed on: Tuesday 09/14/2021 10:10 AM Page 1 of 10 01 0020/AABG/71376



Digital Report Archive

Department of Transportation - Division of Maintenance Structure Maintenance & Investigations

BRIDGE PRE-INSPECTION REPORT TEAM LEADER
 REPORT AUTHOR
 INSPECTED BY
 INSPECTION DATE
 INSPECTION TYPE

Caltrans **01 0020**

BRIDGE NO: **01 0020**
 STRUCTURE NAME: **SMITH RIVER (DR. ERNEST M FINE MEMORIAL BRIDGE)**

PREVIOUS INSPECTION INFORMATION

(60) ROUTINE INSPECTION	08/25/2021 (91) FREQ	24 MO	RESP	SEND TO FHWA	Yes
(63A) NSTM INSPECTION	06/20/2023 (92A) REQ - FREQ-Y-YES	24 MO	FC Team	NBI BRIDGE RECORDS	Yes
(63B) UNDERWATER INSPECTION	05/25/2021 (92B) REQ - FREQ-Y-YES	60 MO		NBI UNDER RECORDS	No
(63C) OTHER SPECIAL INSPECTION	N/A (92C) REQ - FREQ N-NO	MO			

PHOTOS - ROWY 2021
 ELEV 2021
 UNDER 2021

STREAM X SECTION 2020 - Scour Critical Verify X Section
 REACTIVE AGGREGATE 1 ASR - Not Evident


BRIDGE LOCATION INFORMATION

(9) LOCATION	01-DN-101-36.06	(7) FACILITY CARRIED	U.S. HIGHWAY 101
(11) POSTMILE	36.06	(8) FEATURE INTERSECTED	SMITH RIV, SOUTH BANK RD
(16) LATITUDE	41°52'40.37"	(5) INVENTORY RTE(ON/UNDER)	ON 121001010
(17) LONGITUDE	124°08'15"	(104) ON NATIONAL HIGHWAY SYSTEM	ROUTE ON NHS


STRUCTURAL HEALTH CONDITION SUMMARY INFORMATION

(58) DECK	5 FAIR	DECK AREA (M ²)	3,095
(59) SUPERSTRUCTURE	5 FAIR	SUFFICIENCY RATING	26.1
(60) SUBSTRUCTURE	7 GOOD	PAINT CONDITION	89
(62) CULVERT	N N/A (NBI)	STRUCTURALLY DEFICIENT (SD) STATUS	NOT SD
(67) STRUCTURE EVALUATION	2 INTOLERABLE - REPLACE (113) SCOUR		3 SC - UNSTABLE


PHOTOGRAPH IDENTIFICATION




Routine-Roadway View (08/25/2021)



Routine-Elevation View (08/25/2021)



Routine-Underside View (08/25/2021)



Routine-Map View (09/07/2021)

Printed on: Wednesday 08/23/2023 02:36 PM Page 1 of 15

Department of Transportation - Division of Maintenance Structure Maintenance & Investigations

STRUCTURE TO DO LIST - NONE

NOTES TO ABME

Does Caltrans have As-Built Plans in BIRIS? 1939 Originals - YES, 1952 curb joint repair-YES, 1950 Meth Deck-YES (filed under 01-0032), 1996 seismic retrofit-YES

Measure and record the vertical offset of the deck at the hinge joint in the deck at Hinge 16. See if it is increasing. On 8/9/07 the vertical offset was measured and recorded as 1/4 in (6 mm).

8/31/05 by D. Stoughton (SM&I Hydraulics): ABME should take detailed cross-sections between Piers 11 and 17 during biennial inspections. Pier 13 may become seismically vulnerable once channel elevation goes below 8.5 feet. Footing at Pier 13 would be exposed at this elevation. Not currently scour critical, but potential exists; as long as mining operations continue, channel will continue to degrade and migrate toward Pier 13. Notify SM&I Hydraulics if channel degrades further.

May 2006 A. Hope - The Caltrans Environmental Program has modified NBI Item 37 - Historical Significance - for this bridge.

05/13/2014: Need to measure and record all the vertical and horizontal clearances for South Bank Road. Compare the results with the Terrametrics data, they don't agree with the values we got back in January 2000. (TRS/andovt)

9/2019 (WLP): Retake the 10 year photos, current ones are not good.

08/06/2020 (WLP): Patch deck spalls, place anodes and treat the deck with meth in construction under EA 01-0J1804. Completed on 10/20/20.

05/2021 (WLP): Structure being replaced with 01 0041 under Contract 01-436404. Temporary structure is being built and will need to be added to NBI inventory. Construction of replacement bridge expected to take at least two years.

OUTSTANDING WORK REQUESTS - NONE

NBI DATA CHECK AND ELEMENT ERRORS

NBI Bridge Errors
 01 0020 IE030_a Edit # 30=2009 - Year of ADT is older than 10 years

NBI Under Record Errors
 Element Errors

SMI POLICY CHECKS

01 0020 This bridge has one or more paint work recommendations that are now OBSOLETE (action codes 90, 91, 92, or 93). If not programmed into a project yet, please update the recommendation(s) as necessary by using action codes 94, 95, and/or 99.

STRUCTURE OVERVIEW

AGENCY INFORMATION		INSPECTION INFORMATION	
(1) STATE NAME	CALIFORNIA 069	(90) INSPECTION DATE	08/21 (91) FREQUENCY 24 MO
(2) HIGHWAY DISTRICT	01	(92) CRITICAL FEATURE INSPECTION	(93) CFI DATE
(3) COUNTY CODE	(01)DEL NORTE	A) FRACTURE CRITICAL INSP	Y-YES 24 MO A) 06/23
(4) PLACE CODE	(00000)	B) UNDERWATER INSP	Y-YES 60 MO B) 05/21
(21) MAINTAIN	01 STATE HIGHWAY AGENCY	C) OTHER SPECIAL INSP	N-NO MO C) N/A
(22) OWNER	01 STATE HIGHWAY AGENCY		
(98) BORDER BRIDGE STATE CODE	N/A % SHARE N/A		
(99) BORDER BRIDGE STRUCTURE NUMBER	N/A		

PRIMARY AGENCY CONTACT INFORMATION

Printed on: Wednesday 08/23/2023 02:36 PM Page 2 of 15

Department of Transportation - Division of Maintenance Structure Maintenance & Investigations

BRIDGE PRE-INSPECTION REPORT TEAM LEADER
 REPORT AUTHOR
 INSPECTED BY
 INSPECTION DATE
 INSPECTION TYPE

BRIDGE NO: **01 0020**

STRUCTURE NAME: **SMITH RIVER (DR. ERNEST M FINE MEMORIAL BRIDGE)**

PREVIOUS INSPECTION INFORMATION

(60) ROUTINE INSPECTION	08/25/2021 (91) FREQ	24 MO	RESP	SEND TO FHWA	Yes
(63A) NSTM INSPECTION	06/20/2023 (92A) REQ - FREQ Y-YES	24 MO	FC Team	NBI BRIDGE RECORDS	Yes
(63B) UNDERWATER INSPECTION	05/25/2021 (92B) REQ - FREQ Y-YES	60 MO		NBI UNDER RECORDS	No
(63C) OTHER SPECIAL INSPECTION	N/A	(92C) REQ - FREQ N-NO	MO		

PHOTOS - ROWY 2021
 ELEV 2021
 UNDER 2021

STREAM X SECTION 2020 - Scour Critical Verify X Section
 REACTIVE AGGREGATE 1 ASR - Not Evident

BRIDGE LOCATION INFORMATION

(9) LOCATION	01-DN-101-36.06	(7) FACILITY CARRIED	U.S. HIGHWAY 101
(11) POSTMILE	36.06	(8) FEATURE INTERSECTED	SMITH RIV, SOUTH BANK RD
(16) LATITUDE	41°52'40.37"	(5) INVENTORY RTE(ON/UNDER)	ON 121001010
(17) LONGITUDE	124°08'15"	(104) ON NATIONAL HIGHWAY SYSTEM	ROUTE ON NHS

STRUCTURAL HEALTH CONDITION SUMMARY INFORMATION

(58) DECK	5 FAIR	DECK AREA (M ²)	3,095
(59) SUPERSTRUCTURE	5 FAIR	SUFFICIENCY RATING	26.1
(60) SUBSTRUCTURE	7 GOOD	PAINT CONDITION	89
(62) CULVERT	N N/A (NBI)	STRUCTURALLY DEFICIENT (SD) STATUS	NOT SD
(67) STRUCTURE EVALUATION	2 INTOLERABLE - REPLACE (113) SCOUR		3 SC - UNSTABLE

PHOTOGRAPH IDENTIFICATION

Routine-Roadway View (08/25/2021)

Routine-Elevation View (08/25/2021)

Routine-Underside View (08/25/2021)

Routine-Map View (09/07/2021)

Printed on: Wednesday 08/23/2023 02:36 PM Page 1 of 15

Structure Maintenance & Investigations

Bridge Number of 0020

hals - YES, 1952 curb joint repair-YES, 1990 Meth Deck-YES (filed under 01-)

hinge joint in the deck at Hinge 16. See if it is increasing. On 8/9/07 the vertical

ld take detailed cross-sections between Piers 11 and 17 during biennial once channel elevation goes below 8.5 feet. Footing at Pier 13 would be potential exists, as long as mining operations continue, channel will continue to sifics if channel degrades further.

h has modified NBI Item 37 - Historical Significance - for this bridge.

nd horizontal clearances for South Bank Road. Compare the results with the rt back in January 2000. (TRS/Sandovak)

are not good.

reat the deck with meth in construction under EA 01-0J1804. Completed on

nder Contract 01-426404. Temporary structure is being built and will need to be ge expected to take at least two years.

nder than 10 years

ndications that are now OBSOLETE (action codes 90, 91, 92, or 93). If not mendation(s) as necessary by using action codes 94, 95, and/or 99.

INSPECTION INFORMATION

N/A	069	(90) INSPECTION DATE	08/21 (91) FREQUENCY	24 MO
01	(92) CRITICAL FEATURE INSPECTION	(93) CFI DATE		
NORTE	A) FRACTURE CRITICAL INSP	Y-YES	24 MO	A) 06/23
O)	B) UNDERWATER INSP	Y-YES	60 MO	B) 05/21
AGENCY	C) OTHER SPECIAL INSP	N-NO	MO	C) N/A
N/A				
N/A				

+ 2 of 15

Department of Transportation - Division of Maintenance Structure Maintenance & Investigations

Agency - District 01

CONTACT Mr. Matthew Brady BRIDGE CONTACT
 TITLE District 1, Director BR TITLE
 ADDRESS P.O. Box 3700 BR. PHONE
 Eureka, CA, 95502 BR. CELL
 PHONE (707)445-6445 BR. EMAIL
 EMAIL matthew.brady@dot.ca.gov

CONSTRUCTION INFORMATION

(27) YEAR BUILT	1940	(45) MAIN SPANS	6	(43a) STRUCTURE TYPE MAIN	4: STEEL CONT
(109) YEAR MODIFIED	N/A	(46) APPR SPANS	14	(43b) DESIGN TYPE MAIN	02: STRINGER/MULTI-BEAM
(34) SKEW	20	(48) MAX SPAN (M)	54.9	(44a) STRUCTURE TYPE APPR	2: CONCRETE CONT
(49) LENGTH (M)	320.3	(35) STR FLARE	0-N	(44b) DESIGN TYPE APPR	01: SLAB
(112) NBIS BR LENGTH	Y	JOINTS	4	NO. OF HINGES	2

STRUCTURE DESCRIPTION

This 20-span bridge consists of two structure types. The south end has continuous 10-span CIP/RC slab approach spans, with parabolic shaped soffit, on RC three-column bent-type piers (with seismic retrofit RC infill walls between the columns of Piers 6, 7, 10 and 11). Span 1 is a cantilever end span. The six main spans are continuous riveted steel plate girders (2), with CIP/RC non-composite deck, on RC 2 column piers with web walls. The bridge's north end has continuous 4-span CIP/RC slab approach spans, with parabolic shaped soffit, on RC three-column bent-type piers (with seismic retrofit RC infill walls between the columns of Pier 17). Span 20 is a cantilever end span. The piers of the south approach are founded on CIDH concrete piles. The main span piers are on driven steel H piles, and the piers supporting the north end approach spans are on RC spread footings. The bridge was seismically retrofitted in 1997 with four 6 foot diameter CIDH RC pile-shafts with CIP/RC cap buried in the approach adjacent to both ends of the bridge. The Abutment 1 pile-shafts are connected to the Pier 12 strengthened bent cap by high-strength steel tendons encased and grouted in four galvanized steel pipes that are hung below the deck of the approach spans and supported by hangers attached to the soffit.

SPAN CONFIGURATION

1 @ 5.0 ft, 1 @ 20.0 ft, 7 @ 25.0 ft, 1 @ 20.0 ft, 1 @ 50.0 ft, 1 @ 150.0 ft, 2 @ 180.0 ft, 1 @ 150.0 ft, 1 @ 50.0 ft, 1 @ 20.0 ft, 1 @ 25.0 ft, 1 @ 20.0 ft, 1 @ 5.0 ft

OPERATIONAL INFORMATION

LOAD CAPACITY

(31) DESIGN LOAD	4 M 18 (H 20)	(65) CALC METHOD	1 LF LOAD FACTOR
(66) INVENTORY RATING	RF=0.44 => 14.3 metric tons	(83) CALC METHOD	1 LF LOAD FACTOR
(64) OPERATING RATING	RF=0.74 => 24.0 metric tons	(70) BRIDGE POSTING	5 AT/ABOVE LEGAL LOADS
(41) STRUCTURE STATUS	A-OPEN, NO RESTRICTION	PERMIT RATINGS	GGGGG
OVERLAY THICKNESS	0 inches		

POSTING LOADS

	Safe Loads	Existing Ordinance/Order	Posting Signs	Additional Ordinance/Order Requirements
Type 3	Legal	N/A	N/A	NONE
Type 3S2	Legal	N/A	N/A	NONE
Type 3-3	Legal	N/A	N/A	NONE
Speed	55	N/A	N/A	MPH

Posting Date N/A
 Load Rating Summary Date 07/22/20
 Load Rating Type Calculated
 Load Rating Tool - Date BRR 6.8.4 AASHTO - 07/22/20

MINIMUM VERTICAL CLEARANCE

(53) MIN VERT CLEAR OVER BRIDGE ROWY	Unimpaired	(55) MIN LAT UNDERCLEAR RT REF	H-HIGHWAY	1.7 M
(54) MIN VERT UNDERCLEAR REF	H-HIGHWAY	4.67 M	(56) MIN LAT UNDERCLEAR LT	0.0 M

CONDITION INFORMATION

LOAD RATING NOTES FOR ABME VERIFICATION:
 Load Rating Notes for ABME verification:

Printed on: Wednesday 08/23/2023 02:36 PM Page 3 of 15

Department of Transportation - Division of Maintenance

BRIDGE PRE-INSPECTION REPORT

01 0020
 BRIDGE NO.: **01 0020**
 STRUCTURE NAME: **SMITH RIVER (DR. ERNEST M FINE MEMORIAL BRIDGE)**

PREVIOUS INSPECTION INFORMATION

(90) ROUTINE INSPECTION	08/25/2021 (91) FREQ	24 MO	RESP	SEND TO FHWA	Yes
(93A) NSTM INSPECTION	06/20/2023 (92A) REQ - FREQ-Y-YES	24 MO	FC Team	NBI BRIDGE RECORDS	Yes
(93B) UNDERWATER INSPECTION	05/25/2021 (92B) REQ - FREQ-Y-YES	60 MO		NBI UNDER RECORDS	No
(93C) OTHER SPECIAL INSPECTION	N/A	(92C) REQ - FREQ N-NO	MO		

PHOTOS - ROWY 2021
 ELEV 2021
 UNDER 2021

STREAM X SECTION 2020 - Scour Critical Verify X Section
 REACTIVE AGGREGATE 1 ASR - Not Evident

BRIDGE LOCATION INFORMATION

(9) LOCATION	01-DN-101-36.06	(7) FACILITY CARRIED	U.S. HIGHWAY 101
(11) POSTMILE	36.06	(9) FEATURE INTERSECTED	SMITH RIV. SOUTH BANK RD
(16) LATITUDE	41°52'40.37"	(5) INVENTORY RTE(O/N/UNDER)	ON 121001010
(17) LONGITUDE	124°08'15"	(104) ON NATIONAL HIGHWAY SYSTEM	ROUTE ON NHS

STRUCTURAL HEALTH CONDITION SUMMARY INFORMATION

(98) DECK	5 FAIR	DECK AREA (M ²)	3,095
(99) SUPERSTRUCTURE	5 FAIR	SUFFICIENCY RATING	26.1
(60) SUBSTRUCTURE	7 GOOD	PAINT CONDITION	89
(82) CULVERT	N N/A (NBI)	STRUCTURALLY DEFICIENT (SD) STATUS	NOT SD
(67) STRUCTURE EVALUATION	2 INTOLERABLE - REPLACE (113) SCOUR		3 SC - UNSTABLE

PHOTOGRAPH IDENTIFICATION

Routine-Roadway View (08/25/2021)

Routine-Elevation View (08/25/2021)

Routine-Underside View (08/25/2021)

Routine-Map View (09/07/2021)

Printed on: Wednesday 08/23/2023 02:36 PM Page 1 of 15

Structure Maintenance & Investigations

1990 Meth Deck-YES (filed under 01-0020)

if it is increasing. On 8/9/07 the vertical

Piers 11 and 17 during biennial feet. Footing at Pier 13 would be rations continue, channel will continue to

Significance - for this bridge.

Road. Compare the results with the

under EA 01-0J1804. Completed on

structure is being built and will need to be

action codes 90, 91, 92, or 93). If not tion codes 94, 95, and/or 99.

ATION

08/21 (91) FREQUENCY	24 MO	(93) CFI DATE	
INSPECTION Y-YES	24 MO A)	06/23	
Y-YES	60 MO B)	05/21	
N-NO	MO C)	N/A	

MAIN 4: STEEL CONT
 02: STRINGER/MULTI-BEAM
 APPR 2: CONCRETE CONT
 01: SLAB
 2

50.0 ft, 1 @ 50.0 ft, 1 @ 20.0 ft, 1 @ 25.0

1 LF LOAD FACTOR
 1 LF LOAD FACTOR
 5 ABOVE LEGAL LOADS
 GGGGG

UNDERCLEARANCE

LEAR RT REF H-HIGHWAY 1.7 M
 LEAR LT 0.0 M

Printed on: Wednesday 08/23/2023 02:36 PM Page 7 of 15

Department of Transportation - Division of Maintenance

DECK AND ROADWAY

DECK CROSS SECTION
 0.8 ft br, 2.1 ft cu, 26.0 ft, 2.1 ft cu, 0.8 ft br

DECK GEOMETRY

(49) LENGTH	320.3 M	(42a) TYPE OF SERVICE	1-HIGHWAY
(51) NET WIDTH	7.9 M	(12) BASE HIGHWAY NETWORK	1-PART OF NET
(52) TOTAL WIDTH	9.7 M	(13) LRS INVENTORY RTE & SUBRTE	00000010101
(50) CURB OR SIDEWALK	LEFT 0.6 M RIGHT 0.6 M	(104) NATIONAL HIGHWAY SYSTEM	1-ROUTE ON NHS
(32) APPROACH ROWY WIDTH	10.1 M	(26) FUNCTIONAL CLASS	02-OTHER PRM ART RURAL
(33) BRIDGE MEDIAN	0 NO MEDIAN	(100) DEFENSE HIGHWAY	1-STRAHNET

DECK ROADWAY/OPERATIONAL INFORMATION

(107) DECK STRUCTURE TYPE	1-CIP CONCRETE	(101) PARALLEL STRUCTURE	N-NONE EXISTS
(108) WEARING SURFACE / PROTECTIVE SYSTEM		(102) DIRECTION OF TRAFFIC	2-2 WAY
A) TYPE OF WEARING SURFACE	0-NONE	(10) INVENTORY ROUTE MIN VERT CLEAR	99.99 M
B) TYPE OF MEMBRANE	0-NONE	(47) INVENTORY ROUTE TOTAL HORIZ CLEAR	7.9 M
C) TYPE OF DECK PROTECTION	0-NONE	(8) DECK GEOMETRY	3 INTOLERABLE - CORRECT
OVERLAY THICKNESS (inches)	0 inches	(72) APPR ROADWAY ALIGN	8 EQUAL DESIRABLE CRIT
(29) AVERAGE DAILY TRAFFIC	6500	(105) FEDERAL LANDS HWY	0-NOT APPLICABLE
(30) YEAR OF ADT 2009	13%	(110) DESIGNATED NATIONAL NETWORK	0-NOT ON NET
(19) BYPASS, DETOUR LENGTH	10 KM	(28a) LANES	3-ON FREE ROAD
(114) FUTURE ADT	13561	(108) SPEED	55
(115) YEAR OF FUTURE ADT	2041	(103) TEMPORARY STRUCTURE	N/A
(37) HISTORICAL SIGNIFICANCE	5; NOT ELIGIBLE FOR NRP		

DECK ELEMENT INSPECTION RATINGS AND NOTES

(68) DECK RATING = 5

Element Group: 101 - Approach - Spans 1 thru 10 - Continuous CIP/RC slab

Elem No	Defect/Prot	Defect	Elem Description	Env	Total Qty	Units	Qty in each Condition State			
							CS 1	CS 2	CS 3	CS 4
38			Slab-RC	2	658	sq.m	0	658	0	0
1130			Cracking (RC and Other)	2	4		0	4	0	0
1190			Abrasion (PS Conc./RC)	2	654		0	654	0	0
521			Concrete Coat.(Meth/Sealer)	2	551	sq.m	551	0	0	0

(38-1130) Cracking (RC and Other)
 There are a few 0.03 inch wide random cracks in the soffit in Span 2.
 (38-1190) Abrasion (PS Conc./RC)
 The bridge deck is moderately abraded throughout the length of the structure.
 (38-521) Concrete Coat.(Meth/Sealer)
 The bridge deck was treated with methacrylate in 1991 under EA 01-289604.

Element Group: 102 - Main - Spans 11 thru 16 - Riveted Built Up Steel Girders (2)

Elem No	Defect/Prot	Defect	Elem Description	Env	Total Qty	Units	Qty in each Condition State			
							CS 1	CS 2	CS 3	CS 4
12			Deck-RC	2	2210	sq.m	0	2210	0	0
1190			Abrasion (PS Conc./RC)	2	2210		0	2210	0	0
521			Concrete Coat.(Meth/Sealer)	2	1856	sq.m	1856	0	0	0

(12-1190) Abrasion (PS Conc./RC)
 The bridge deck is moderately abraded throughout the length of the structure.
 (12-521) Concrete Coat.(Meth/Sealer)
 The bridge deck was treated with methacrylate in 1991 under EA 01-289604.

Element Group: 103 - Approach - Spans 17 thru 20 - Continuous CIP-RC slab

Printed on: Wednesday 08/23/2023 02:36 PM Page 7 of 15

Department of Transportation - Division of Maintenance Structure Maintenance & Investigations

BRIDGE PRE-INSPECTION REPORT TEAM LEADER
 REPORT AUTHOR
 INSPECTED BY
 INSPECTION DATE
 INSPECTION TYPE

BRIDGE NO: **01 0020**
 STRUCTURE NAME: **SMITH RIVER (DR. ERNEST M FINE MEMORIAL BRIDGE)**

PREVIOUS INSPECTION INFORMATION

(60) ROUTINE INSPECTION	08/25/2021 (61) FREQ	24 MO	RESP	SEND TO FHWA	Yes
(63A) NSTM INSPECTION	06/20/2023 (62A) REQ - FREQ-YES	24 MO	FC Team	NBI BRIDGE RECORDS	Yes
(63B) UNDERWATER INSPECTION	05/25/2021 (62B) REQ - FREQ-YES	60 MO		NBI UNDER RECORDS	No
(63C) OTHER SPECIAL INSPECTION	N/A (62C) REQ - FREQ N-NO	MO			

PHOTOS - ROWY 2021
 ELEV 2021
 UNDER 2021

STREAM X SECTION 2020 - Scour Critical Verify X Section
 REACTIVE AGGREGATE 1 ASR - Not Evident

BRIDGE LOCATION INFORMATION

(9) LOCATION	01-DN-101-36.06	(7) FACILITY CARRIED	U.S. HIGHWAY 101
(11) POSTMILE	36.06	(6) FEATURE INTERSECTED	SMITH RIV, SOUTH BANK RD
(16) LATITUDE	41°52'40.37"	(5) INVENTORY RTE(ON/UNDER)	ON 121001010
(17) LONGITUDE	124°08'15"	(104) ON NATIONAL HIGHWAY SYSTEM	ROUTE ON NHS

STRUCTURAL HEALTH CONDITION SUMMARY INFORMATION

(58) DECK	5 FAIR	DECK AREA (M ²)	3,095
(59) SUPERSTRUCTURE	5 FAIR	SUFFICIENCY RATING	26.1
(60) SUBSTRUCTURE	7 GOOD	PAINT CONDITION	89
(62) CULVERT	N/A (NBI)	STRUCTURALLY DEFICIENT (SD) STATUS	NOT SD
(67) STRUCTURE EVALUATION	2 INTOLERABLE - REPLACE (113) SCOUR		3 SC - UNSTABLE

PHOTOGRAPH IDENTIFICATION

Routine-Roadway View (08/25/2021)

Routine-Elevation View (08/25/2021)

Routine-Underside View (08/25/2021)

Routine-Map View (09/07/2021)

Printed on: Wednesday 08/23/2023 02:36 PM Page 1 of 15

Structure Maintenance & Investigations

Bridge Number: 01 0020

Deck: YES (filed under 01-01-01804. Completed on 08/9/07 the vertical

approach spans, with columns of Piers 6, 7, 10, with CIP/RCC non-RC slab approach spans, in the columns of Pier 17). The main span piers are on a bridge was seismically adjacent to both ends of the pier tendons encased and hangers attached to the

4 STEEL CONT
 STRINGER/MULTI-BEAM
 2 CONCRETE CONT
 01: SLAB
 2

50.0 ft, 1 @ 20.0 ft, 1 @ 25.0

1 LF LOAD FACTOR
 1 LF LOAD FACTOR
 ABOVE LEGAL LOADS
 GGGGG

(61) FREQUENCY 24 MO
 (63) CFI DATE
 24 MO A) 06/23
 60 MO B) 05/21
 MO C) N/A

PERFORMANCE
 H-HIGHWAY 1.7 M
 0.0 M

Bridge Number: 01 0020

Printed on: Wednesday 08/23/2023 02:36 PM Page 1 of 15

Department of Transportation - Division of Maintenance Structure Maintenance & Investigations

SUPERSTRUCTURE

SUPERSTRUCTURE ELEMENT INSPECTION RATINGS AND NOTES (59) SUPERSTRUCTURE RATING = 5
 Element Group: 102 - Main - Spans 11 thru 16 - Riveted Built Up Steel Girders (2)

Elem No.	Defect/Prot Defect	Element Description	Env	Total Qty	Units	Qty in each Condition State			
						CS 1	CS 2	CS 3	CS 4
		3450 Paint Sys Breakdown (Steel PC)		2	575	0	0	575	0
(107)		Girder/Beam/Steel							
Non-Routine Inspection Element Notes: FCMI (06/20/2023): See the report narrative for the list of members that were inspected.									
(107-1000)		Corrosion							
There is flecked rust bleeding through the paint throughout the structure (see Photo 12 from the BIR dated 08/15/2015).									
(107-515)		Steel Coating-Paint							
The bridge was last painted in October 1990.									
(107-516)		Steel Coating-Galvanized							
There were no significant defects noted.									
(107-515-3450)		Paint Sys Breakdown (Steel PC)							
The paint on the steel girders is no longer functioning as a protective coating (see Photo 12 from the BIR dated 08/15/2015).									
161		Steel Pin+Pin/Hanger or Both		2	2	each	2	0	0
(161)		Steel Pin+Pin/Hanger or Both							
Non-Routine Inspection Element Notes: FCMI (05/20/2023): See the report narrative for the list of members that were inspected.									

SUPERSTRUCTURE PHOTOGRAPHS

Photo 1
Underside view of the bridge

Photo 2
Typical pin and hanger assembly

SUPERSTRUCTURE OUTSTANDING & RECENTLY COMPLETED WORKNONE

DESCRIPTION UNDER STRUCTURE

(42b) TYPE OF SERVICE UNDER	6-HIGHWAY-WATERWAY	(38) NAVIGATION CONTROL	0: NO CONTROL
(89) UNDERCLEARANCES V - H	4 TOLERABLE	(111) PIER PROTECTION	N/A
(71) WATER ADEQUACY	9 ABOVE DESIRABLE	(39) NAVIGATION VERTICAL CLEARANCE	0.0 M
(61) CHANNEL PROTECTION	7 MINOR DAMAGE	(116) VERT-LIFT BRIDGE NAV MIN VERTICAL CLEAR	M
(113) SCOUR	3 SC - UNSTABLE	(40) NAVIGATION HORIZONTAL CLEARANCE	0.0 M

SCOUR POA DATE: 05/28/2020

CHANNEL DESCRIPTION
 Broad flood plain, gravel bottom.

ROADWAY DESCRIPTION UNDER STRUCTURE

Printed on: Wednesday 08/23/2023 02:36 PM Page 10 of 15

Department of Transportation - Division of Maintenance

BRIDGE PRE-INSPECTION REPORT

01 0020

BRIDGE NO: 01 0020
STRUCTURE NAME: SMITH RIVER (DR. ERNEST M FINE MEMORIAL BRIDGE)

PREVIOUS INSPECTION INFORMATION

(60) ROUTINE INSPECTION	08/25/2021 (81) FREQ	24 MO	RESP	SEND TO FHWA	Yes
(63A) NSTM INSPECTION	06/20/2023 (62A) REQ - FREQ-YES	24 MO	FC Team	NBI BRIDGE RECORDS	Yes
(63B) UNDERWATER INSPECTION	05/25/2021 (62B) REQ - FREQ-YES	60 MO		NBI UNDER RECORDS	No
(63C) OTHER SPECIAL INSPECTION	N/A	(62C) REQ - FREQ N-NO	MO		

PHOTOS - ROWY 2021
ELEV 2021
UNDER 2021

STREAM X SECTION 2020 - Scour Critical Verify X Section
REACTIVE AGGREGATE 1 ASR - Not Evident

BRIDGE LOCATION INFORMATION

(9) LOCATION	01-DN-101-36.06	(7) FACILITY CARRIED	U.S. HIGHWAY 101
(11) POSTMILE	36.06	(6) FEATURE INTERSECTED	SMITH RIV, SOUTH BANK RD
(16) LATITUDE	41°52'40.37"	(5) INVENTORY RTE(ON/UNDER)	ON 121001010
(17) LONGITUDE	124°08'15"	(104) ON NATIONAL HIGHWAY SYSTEM	ROUTE ON NHS

STRUCTURAL HEALTH CONDITION SUMMARY INFORMATION

(58) DECK	5 FAIR	DECK AREA (M ²)	3,095
(59) SUPERSTRUCTURE	5 FAIR	SUFFICIENCY RATING	26.1
(60) SUBSTRUCTURE	7 GOOD	PAINT CONDITION	89
(62) CULVERT	N/A (NBI)	STRUCTURALLY DEFICIENT (SD) STATUS	NOT SD
(67) STRUCTURE EVALUATION	2 INTOLERABLE - REPLACE (113) SCOUR		3 SC - UNSTABLE

PHOTOGRAPH IDENTIFICATION

Routine-Roadway View (08/25/2021)
Routine-Elevation View (08/25/2021)
Routine-Underside View (08/25/2021)
Routine-Map View (09/07/2021)

Printed on: Wednesday 08/23/2023 02:36 PM Page 1 of 15

Structure Maintenance & Investigations

Bridge Number 01 0020

ES (filed under 01-01)

On 8/9/07 the vertical alignment was regraded. The results with the regrade are as follows:

04. Completed on 8/9/07. The bridge deck will need to be replaced.

1 spans, with spans of Piers 6, 7, 10 approach spans, (sums of Pier 17). span piers are on both ends of the bridge and are attached to the bridge.

4. STEEL CONT
GERMULTI-BEAM
CONCRETE CONT
01: SLAB
2

1-HIGHWAY
1-PART OF NET
00000010101
1-ROUTE ON NHS
R PRIN ART RURAL
1-STRAHNET
N-NONE EXISTS
2-2 WAY
99.99 M
CLEAR 7.9 M
CLEAR - CORRECT
L-DESIRABLE CRIT
NOT APPLICABLE
G-NOT ON NET
3-ON FREE ROAD
2
55
N/A

K RATING = 5

Condition State
CS 3 CS 4
0 0
0 0
0 0
0 0
0 0

Bridge Number 01 0020

0: NO CONTROL
N/A
E 0.0 M
CAL CLEAR M
NCE 0.0 M

Condition State
CS 3 CS 4
0 0
0 0
0 0

NCE
IGHWAY 1.7 M
0.0 M

Printed on: Wednesday 08/23/2023 02:36 PM Page 13 of 15

Department of Transportation - Division of Maintenance

Structure Maintenance & Investigations

CHANNEL X-SECTION

Side Upstream

Measured From From Top of Deck

X-Section Date 05/28/2020

Location	Horiz(m)	Vert(m)	Comments
	168.91	16.79	
	175.40	16.70	
	178.91	16.73	
	179.09	16.25	Pier 13 - Top of File Cap
	180.92	16.82	Upstream of Pile Cap Nose
	183.36	16.85	
	186.25	16.49	
	193.48	16.49	
	197.07	16.28	
	208.32	16.49	
	218.07	16.25	
	227.89	15.79	
	235.75	15.67	Pier 14
	237.06	15.73	
	244.29	15.06	
	255.01	14.90	
	264.46	14.93	
	273.33	15.12	
	279.52	15.21	
	282.99	15.18	Pier 15
	284.94	14.51	Edge of Water
	289.24	12.04	
	292.29	11.52	
	297.87	10.42	Pier 16
	304.11	8.93	Pier 17
	309.45	5.76	
	316.67	1.49	

OTHER PHOTOGRAPHS

Photo 1 Looking up station on route 101
Photo 2 Looking east
Photo 3 Looking towards Pier 12 from Pier 11
Photo 4 Typical satellite view.

OTHER OUTSTANDING & RECENTLY COMPLETED WORK

Rec Date	04/01/2018	Work By	SHOPP	Est Cost		Dist Target	
Status	AWARDED	Action	Bridge-Replace(Bridg	Str Target	4 YEARS	EA	43640

Bridge replacement work rec made due to a decision by a Peer Review on August 2007. If

Printed on: Wednesday 08/23/2023 02:36 PM Page 13 of 15

Department of Transportation - Division of Maintenance Structure Maintenance & Investigations

BRIDGE PRE-INSPECTION REPORT TEAM LEADER
 REPORT AUTHOR
 INSPECTED BY
 INSPECTION DATE
 INSPECTION TYPE

BRIDGE NO: **01 0020**

STRUCTURE NAME: **SMITH RIVER (DR. ERNEST M FINE MEMORIAL BRIDGE)**

PREVIOUS INSPECTION INFORMATION

(60) ROUTINE INSPECTION	08/25/2021 (61) REQ	24 MO	RESP	SEND TO FHWA	Yes
(63A) NSTM INSPECTION	06/20/2023 (62A) REQ - FREQ-YES	24 MO	FC Team	NBI BRIDGE RECORDS	Yes
(63B) UNDERWATER INSPECTION	05/25/2021 (62B) REQ - FREQ-YES	60 MO		NBI UNDER RECORDS	No
(63C) OTHER SPECIAL INSPECTION	N/A (62C) REQ - FREQ N-NO	MO			

PHOTOS - ROWY 2021
 ELEV 2021
 UNDER 2021

STREAM X SECTION 2020 - Scour Critical Verify X Section
 REACTIVE AGGREGATE 1 ASR - Not Evident

BRIDGE LOCATION INFORMATION

(9) LOCATION	01-DN-101-36.06	(7) FACILITY CARRIED	U.S. HIGHWAY 101
(11) POSTMILE	36.06	(6) FEATURE INTERSECTED	SMITH RIV, SOUTH BANK RD
(16) LATITUDE	41°52'40.37"	(5) INVENTORY RTE(ON/UNDER)	ON 121001010
(17) LONGITUDE	124°08'15"	(104) ON NATIONAL HIGHWAY SYSTEM	ROUTE ON NHS

STRUCTURAL HEALTH CONDITION SUMMARY INFORMATION

(58) DECK	5 FAIR	DECK AREA (M ²)	3,095
(59) SUPERSTRUCTURE	5 FAIR	SUFFICIENCY RATING	26.1
(60) SUBSTRUCTURE	7 GOOD	PAINT CONDITION	89
(62) CULVERT	N/A (NBI)	STRUCTURALLY DEFICIENT (SD) STATUS	NOT SD
(67) STRUCTURE EVALUATION	2 INTOLERABLE - REPLACE (113) SCOUR		3 SC - UNSTABLE

PHOTOGRAPH IDENTIFICATION

Routine-Roadway View (08/25/2021)

Routine-Elevation View (08/25/2021)

Routine-Underside View (08/25/2021)

Routine-Map View (09/07/2021)

Printed on: Wednesday 08/23/2023 02:36 PM Page 1 of 15

Structure Maintenance & Investigations Bridge Number: 01 0020
 Facility Carried: U.S. HIGHWAY 101
 Location: 01-DN-101-36.06
 City:

Load Rating Summary Sheet

Bridge Name: SMITH RIVER (DR. ERNEST M FINE MEMORIAL BRIDGE)
 Structural Element: RC Slab/ Stl Plate Girders (widely spaced)
 Rated:

Rating Summary

DESIGN LOADING

Inventory	Rating Factor	Metric	Structure	Control Element	Load Action	Location
Operating	0.44	14.3	Span 18-22	Slab	Ultimate Moment	PM 0.40pt of Sp 18, S1-RC Slab
Operating	0.74	24.0	Span 18-22	Slab	Ultimate Moment	PM 0.40pt of Sp 18, S1-RC Slab

LEGAL RATING

Type	Rating	Legal	Span	Control Element	Load Action	Location
Type 3 (25T)	1.36	Legal	Span 1-11	Slab	Ultimate Moment	PM 0.50pt of Sp 5, S1-RC Slab
Type 3S2 (36T)	1.37	Legal	Span 1-11	Slab	Ultimate Moment	NM 0.54pt of Sp 8, S1-RC Slab
Type 3-3 (40T)	1.70	Legal	Span 1-11	Slab	Ultimate Moment	PM 0.50pt of Sp 6, S1-RC Slab

PERMIT RATING

Truck Type	Rating	Permit	Span	Control Element	Load Action	Location
5 Axle Truck	0.89	G	Span 1-11	Slab	Ultimate Moment	NM 0.54pt of Sp 8, S1-RC Slab
7 Axle Truck	0.89	G	Span 1-11	Slab	Ultimate Moment	NM 0.54pt of Sp 8, S1-RC Slab
9 Axle Truck	0.89	G	Span 1-11	Slab	Ultimate Moment	NM 0.54pt of Sp 8, S1-RC Slab
11 Axle Truck	0.89	G	Span 1-11	Slab	Ultimate Moment	NM 0.54pt of Sp 8, S1-RC Slab
13 Axle Truck	0.89	G	Span 1-11	Slab	Ultimate Moment	NM 0.54pt of Sp 8, S1-RC Slab

NOTES:

Permit RFs based on Pos. Moment are 1.01, 1.01, 1.01, 1.00, 0.93 and based on Neg. Moment are 0.89, 0.89, 0.90, 0.90, 0.90 and based on Shear are 3.78, 2.98, 2.57, 2.31, 2.11 for P5-P13 Split respectively.
 This load rating is based on the existing bridge geometry and roadway configuration. Modification to the structure (such as bridge rail modification or widening) may require a new load rating.

Overlay Used in Rating: 1.5 inch AC overlay

Rating Method: 1 LF Load Factor
 Inventory (65) Operating (65)

Analysis Tool Used: BrR 6.8.4 AASHTO

Rating/File Location: BrR Database

Control Rating By: David Simmons Rating Date: 07/22/2020

Rating Checked By: Raha Hezar Rating Date: 7/22/2020

Rating Type: Calculated

Summary Prepared By: David Simmons Summary Date: 07/22/2020

David Simmons - Registered P.E. 7/22/2020 Date

REGISTERED PROFESSIONAL ENGINEER
 David Simmons
 No. 70703
 Exp. 06/30/2021
 CIVIL
 STATE OF CALIFORNIA

Str_rating_sum.ref Page 1 of 2



FINAL QUESTIONS

