

Dashboards

Jacob Armour, P.E.

Bridge Management Systems Engineer
Michigan Department of Transportation



AASHTO Ware™

BRIDGE

MANAGEMENT

Ancillary Asset List

USER, PONTIS

BrM ASHTO Wire Bridge Management AASHTO

- BRIDGES
- REPORTS
- TUNNELS
- ADMIN
- INSPECTION
- GATEWAY
- ANALYSIS
- PROJECTS
- PROGRAMS
- INSPECTION MANAGEMENT
- ANCILLARIES
 - SIGNS LIST
 - SIGN INVENTORY
 - SIGN INSPECTION
 - SIGN WORK CANDIDATES
 - ANCILLARY ASSET LIST**

Ancillaries > Ancillary Asset List

Ancillary Asset List

Filter: Test Export KML Export Add New

USER, PONTIS

Bridges > Manage Filters > Edit SQL

BrM ASHTO Wire Bridge Management AASHTO

BRIDGES

- VIEW LIST
- MANAGE LAYOUTS
- MANAGE FILTERS
 - EDIT FILTER
 - EDIT SQL
 - NEW INSPECTION
 - SUFF RATE
 - VALIDATE
 - CREATE STRUCT
 - COPY STRUCT
 - REMOVE STRUCT

Edit SQL

Select Context: Ancillary Asset List Select Filter: Test MDOT - Default New

SQL info

Description: test

Shared Active Access Filter Shared with Group

SQL Statement

SQL Statement Requirements

"The current context requires a selection statement that contains the following column:
(asset_gd) as "key_"

```
select (asset_gd) as "key_",  
pon_tunnel.tunnel_num,  
pon_tunnel.name as name,  
pon_tunnel.latitude as latitude,  
!|pon_tunnel.longitude as longitude  
from pon_tunnel
```

Structure Condition Dashboard

Bridges > Structure Condition

Bridge Filter

Structure Inventory Summary

Total Structures	13454
Highway (NBI) Structures Greater Than 20'	11275
Highway Structures Less Than 20'	2172
Rail Road Structure (X)	378
Pedestrian Structures (P)	231
Other Non-Highway Structures (V, Plaza)	21

Additional Bridge Inventory Information

Posted Structures	1126
Closed Structures	103
Fracture Critical Structures	148
Scour Critical Structures	1605
Scheduled/Under Construction (S,G)	123

Structure Condition Summary

Good/Fair (5 or Greater)	11820
Highway included in NBI	9990
Non NBI Structures (<20, RR, Ped, ect.)	1823
Poor (4)	1089
Highway included in NBI	868
Non NBI Structures (<20, RR, Ped, ect.)	221
Serious/Critical (3 or Less)	545
Highway included in NBI	417
Non NBI Structures (<20, RR, Ped, ect.)	128
Unrated Structures	23
Highway included in NBI	0
Non NBI Structures (<20, RR, Ped, ect.)	16

NBI Condition Goals

	Pct.
Good/Fair (5 or Greater)	88.60%
Freeway	93.57%
Non-Freeway	51.16%
Poor/Serious/Critical (4 or less)	11.40%
Freeway	06.43%
Non-Freeway	12.37%
Good NHS Deck Area	23.77%
Fair NHS Deck Area	68.82%
Poor NHS Deck Area	07.42%

TPM

	Current	2 Year Target	4 Year Target
% Good by Deck Area	23.77%	15.15%	12.81%
% Fair by Deck Area	68.82%	78.03%	81.42%
% Poor by Deck Area	07.42%	06.82%	05.78%



Report Assignment Dashboard

Report Assignment Dashboard

Jurisdiction ▾

NBI Filter ▾

NHS Filter ▾

Report Type	Total	Past Due	Assigned	Not Assigned	Due Next 3 Months
Routine	0	0	0	0	0
Fracture Critical	0	0	0	0	0
Fatigue Sensitive	0	0	0	0	0
Underwater	0	0	0	0	0
Other Special	0	0	0	0	0
Scour Actions	0		0	0	

Load Rating Dashboard

Load Rating Dashboard

Jurisdiction ----- Default ----- Display

<u>Structure Inventory Summary</u>	Count	<u>Compliance Summary</u>	Count	<u>Other Data Coding Issues</u>	Count
Total No. of Structures	0	Posting / Closing Issues	0	Item 64F or Item 66 = 0 with No Temp Condition	0
Highway (NBI) Structures greater than 20'	0	Posting Recommended	0	Load Rating Methods Inconsistent	0
		Structure Should be Posted	0	Load Rating Method No Longer Accepted	0
		Structure Should be Closed	0	Null Rating Value	0
		Load Rating Issues	0		
		Assigned Rating Not Applicable	0	<input type="radio"/> Non-NBI Only	
		Built/Rebuilt > 2010 & NOT LRFR	0	<input checked="" type="radio"/> NBI Only	
		Built/Rebuilt/Overlay > 1993 & ASR	0		
		Item 64F < 22T	0		
		Item 64F < or = Item 66	0		
		Judgment Rating Not Applicable	0		
		NHS & ASR	0		
		No Rating Performed	0		
		Poor Condition & Rating Does Not Represent Current Condition	0		
Structure Status/Condition Summary	Count				
Posted Structures	0				
Closed Structures	0				
Fracture Critical Structures	0				
Structures with Temporary Supports	0				
Structures in Poor Condition	0				
Structural Evaluation < 4	0				

Request For Action Dashboard

Request For Action Dashboard

Jurisdiction

NBI Filter

NHS Filter

Request For Action (RFA) Summary

	Count
Total No. of Incomplete RFAs	0
Total No. of Complete RFAs	0
RFAs Submitted by Me	0
Incomplete RFAs Assigned to Me	0
Complete RFAs Assigned to Me	0
Critical Findings	0

Priority Level	In Progress	Complete	Reviewed by Committee	Not Reviewed by Committee
Level 1	0	0	0	0
Level 2	0	0	0	0
Level 3	0	0	0	0
Level 4	0	0	0	0

Intermediate Action Type

	Complete	In Progress	Reviewed	Not Reviewed
Detailed Inspection	0	0	0	0
Damage Inspection	0	0	0	0
Scour Evaluation	0	0	0	0
Schedule Special Inspection	0	0	0	0
False Decking R&R	0	0	0	0
Load Rating	0	0	0	0
Load Reduction < 20%	0	0	0	0
Temporary Supports	0	0	0	0
PRJ Installation	0	0	0	0
Steel Repairs	0	0	0	0
Concrete Repairs	0	0	0	0
Beam End Repairs	0	0	0	0
Scour Repairs	0	0	0	0
Scale Concrete	0	0	0	0
Other Actions	0	0	0	0
Program Project	0	0	0	0
Joint Repair	0	0	0	0
Railing Repair	0	0	0	0
Sign Repair	0	0	0	0

Critical Finding Type

	Complete	Incomplete
Close Bridge	0	0
Close Lane	0	0
Close Shoulder	0	0
Load Reduction ≥ 20%	0	0

My Assignment Dashboard

My Assignments Dashboard

Inspection Type	Total
All Inspections	0
Routine	0
Fracture Critical	0
Fatigue Sensitive	0
Underwater	0
Other Special	0

Scour Actions	Total
Scour Action Plans	0

Load Ratings	Total
Load Ratings	0

Requests for Action	Total
Requests for Action	0

A blue-tinted photograph of a large bridge over a river. The bridge has multiple concrete piers and a metal truss structure. In the foreground, there are two large, smooth rocks on a sandy bank. The word "Questions?" is overlaid in white text in the center of the image.

Questions?

A blue-tinted photograph of a large bridge over a river. In the foreground, there is a sandy beach with two large rocks. The bridge has multiple concrete pillars supporting it. In the background, another bridge is visible across the river. The sky is overcast.

Thank you!